



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SCP9099L
Date of Accident : 01 February 2019

Miss Teo Yen Fen

Date : 18 February 2019

Estimate To Repair SJX1714Y - Ford MUSTANG CONVERTIBLE 2.3 GTDIA
Chassis No : 1FATP8UH4G5334963

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear fender RH <i>3.050</i>	\$ 1,600.00
02	1 pc	rear fender outer moulding <i>11</i>	\$ 320.00
03	1 pc	rear fender inner cowling RH <i>11</i>	\$ 215.00
04	1 pc	front door RH <i>2</i>	\$ 1,850.00
05	1 pc	rear wheel rim <i>cut</i>	\$ 1,300.00
		Less 10 %	\$ 5,285.00
			\$ 528.50
			\$ 4,756.50
<u>SPECIAL NETT ITEMS</u>			
06	1 pc	rear tyre <i>su</i>	\$ 600.00
07	1 pc	body sticker <i>ner</i>	\$ 1,200.00
			\$ 1,800.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of door fittings and perform water seepage test.	\$ 11 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
03		To rust-proofing of the affected areas.	\$ 100.00
04		To transfer of tyre, rim and on wheel balancing.	\$ 80.00
05		To check steering geometry and computer wheel alignment.	\$ 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
07		Putty and spray painting of the front door, rear fender and rear bumper.	\$ 1,200.00
			\$ 2,680.00
			\$ 9,236.50

LKK Auto Consultancy
Total
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

NOT Allowed
h/s
18/2/19
Teo Yen Fen
Sdy.