

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0195/2019/GW
Date : 14-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SCU 6655 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ooi May Ling Angeline
Address : 27 Springleaf Garden
Singapore 788187
Telephone : HP +65 97872341
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SDY 3636 S**
Model Code : A8 DL 3.0 TFSI QU
Model / Year : Apr-14
Engine No : CRE 003908
Chassis No : WAUZZZ4H5EN015134
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 09-Feb-19
Place of Accident : Springleaf Garden

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDY 3636 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. S/N	\$480.00 ✓	
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 ⁷ 1000.	
3	To respray front bumper, rhs front fender and bonnet.	\$ 3,000.00 1100.	
4	To carry out diagnostic check. S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$6,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 3636 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 3,051.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 446.00	ne ✓
3	FRONT BUMPER GRILLE	\$ 643.00	?
4	FRONT BUMPER CLOSING ELEMENT	\$ 238.00	?
5	FRONT BUMPER SPOILER	\$ 271.00	?
6	FRONT WHEEL SPOILER-RH OUTER	\$ 40.00	?
7	FRONT WHEEL SPOILER-RH INNER	\$ 32.00	?
8	RADIATOR GRILLE	\$ 3,236.00	X
9	INSCRIPTION ' QUATTRO '	\$ 87.00	X
10	RADIATOR COVER	\$ 56.00	X
11	RADIATOR COVER CAP	\$ 105.00	X
12	RADIATOR BRACKET	\$ 25.00	X
13	RADIATOR REINFORCEMENT-RH	\$ 44.00	X
13	RADIATOR SECURING PLATE	\$ 75.00	X
14	FRONT SUPPORT SENSOR	\$ 44.00	?
15	LICENCE PLATE HOLDER	\$ 418.00	X
16	FRONT GRILLE-RH	\$ 472.00	?
17	FRONT END CAP-RH	\$ 62.00	mis ✓
18	FRONT BUMPER CARRIER	\$ 987.00	?
19	FRONT BUMPER BRACKET TRIM-RH	\$ 22.00	?
20	FOAM FILLER PIECE	\$ 116.00	?
SUB-TOTAL SPARE PARTS CHARGES		\$ 10,470.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 3636 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT BUMPER COVER	\$ 89.00	X
22	FROTN BUMPER GUIDE PIECE-RH	\$ 48.00	?
23	FRONT BUMPER UPPER COVER	\$ 220.00	X
24	FRONT BUMPER RETAINING BRACKET-RH	\$ 22.00	?
25	SIGN " CAUTION "	\$ 13.00	X
26	AIR CONDITIONER STICKER	\$ 18.00	X
27	BONNET	\$ 6,055.00	RX
28	BONNET ATTACHMENT PARTS	\$ 240.00	X
29	BONNET CATCH HOOK	\$ 142.00	X
30	BONNET LOCK BAR	2 \$ 218.00	X
31	BONNET SEAL	\$ 53.00	X
32	BONNET BOWDEN CABLE	\$ 53.00	X
33	HEADLIGHT BRACKET-RH	\$ 42.00	?
34	BONNET LID LOCK WITH MICRO SWITCH	2 \$ 420.00	X
35	LED HEALDIGHT-RH	\$ 11,951.00	ent
36	HEALDIGHT LIFT CYLINDER	\$ 216.00	?
37	FRONT PARKING AID SENSOR	2 \$ 419.00	?
38	FRONT PARKING AID SENSOR SEAL RING	4 \$ 5.00	new
39	FRONT NO. PLATE	S/N \$ 25.00	X
40	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 31,219.00	
TOTAL LABOUR CHARGES		\$ 6,472.00	
GRAND TOTAL		\$ 37,691.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Taykū 97495749
Surveyed Date : 'WP' 14/2/19
Authorised Date :
Excess Cost :
Liability :
Remarks :
Review before print.
sur@lkauto.com
05 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant