



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SKX1165U

Date of Accident : 05 February 2019

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Guo Chongyu

Date : 12 February 2019

Estimate To Repair SJJ3800S - Mercedes Benz E250 A

Chassis No : WDD2120362A937043

S/No	Quantity	Description	Amount
<u>NETT ITEMS</u>			
01	1 pc	rear bumper <i>20/22</i>	\$ 1,520.00
02	1 pc	rear bumper chrome moulding centre <i>sun</i>	\$ 165.00
03	4 ps	rear bumper park assist sensor @ \$255.00 <i>sun</i>	\$ 1,020.00
04	2 pc	rear bumper side retainer @ \$36.00 <i>11</i>	\$ 72.00
05	2 pc	rear bumper chrome moulding side @ \$118.00 <i>NK</i>	\$ 236.00
06	1 pc	rear bumper side support LH <i>11</i>	\$ 660.00
07	1 pc	rear bumper reinforcement <i>11</i>	\$ 725.00
Less 10 %			\$ 4,398.00
			\$ 439.80
			\$ 3,958.20
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
03		Putty and spray painting of the affected portion.	\$ 300.00
			\$ 820.00
Total			\$ 4,778.20

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not added
dbr
1/5 \$1550
2019*

*18/2/19
Wheeler Attorney*

*P-1685
103
1516.50*

*—
—
X
X
X
X
X
50
200
200*