



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002711/R1pa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:RICHARD ANG

Date : 07-08-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJT 3940T	<b>Veh. Inspected</b>	SLT 9648A
<b>Policy No.</b>	CN015546	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01DOG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	21/02/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL 1.5X CVT	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	RU11227849	<b>Colour</b>	WHITE
<b>Odometer</b>	23615	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	DUNLOP	5 mm
<b>L/H Front Tyre</b>	215/60 R16	DUNLOP	5 mm
<b>R/H Rear Tyre</b>	215/60 R16	DUNLOP	5 mm
<b>L/H Rear Tyre</b>	215/60 R16	DUNLOP	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	07/02/2019	<b>Inspection Date</b>	21/02/2019
<b>Survey held at</b>	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**