

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

4K ~
13/2/19

VEHICLE ESTIMATE

AXA

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 07/02/2019@0395HRS
VRN : SLT9648A
MODEL : Honda Vezel
TP VRN : SJT3940T

Qty S\$ Unit S\$ Amt S\$ Labor

PARTS REPLACEMENT

1. Body Repair

1 Rear Bumper <i>DE</i>	1	\$	508.00	\$	508.00
2 Rear Bumper Clips <i>W</i>	10	\$	5.50	\$	55.00
3 Rear Bumper Reflector LH/RH <i>X</i>	2	\$	151.00	\$	302.00
4 End Panel <i>?</i>	1	\$	416.00	\$	416.00
5 End Panel Upper Garnish <i>?</i>	1	\$	95.00	\$	95.00
6 Tailgate <i>TH</i>	1	\$	953.00	\$	953.00
7 Tailgate Lock <i>X</i>	1	\$	107.00	\$	107.00
8 Vezel Logo <i>W</i>	1	\$	45.00	\$	45.00
9 "H" Logo <i>W</i>	1	\$	28.00	\$	28.00
10 Rear Windscreen Moulding <i>W</i>	4	\$	15.00	\$	60.00
11 Rear Reverse Sensor <i>?</i>	s/nett 1	\$	200.00	\$	200.00
12 Sealant <i>WCC</i>	s/nett 1	\$	45.00	\$	45.00

Discount 20% \$ (513.80)

TOTAL \$ 2,300.20

2. Labor Charges

1 Panel beat, cut, weld, re-align and replace damaged parts of rear portion		\$	1,000.00
2 Spray painting on rear portion of affected area	250	\$	1,000.00
3 Conduct water seepage test	30	\$	120.00
4 Remove & reinstall 2 pieces bumper sensors	60	\$	120.00
5 Cavity treatment on new parts	40	\$	80.00
6 Remove & reinstall tailgate windscreen glass	120	\$	180.00
7 Transfer tailgate lock & mechanism to new tailgate	80	\$	150.00

500

Panel Sub Total : \$ 2,650.00

Grand Total : \$ 4,950.20
Add 7% GST : \$ 346.51
Nett Total : \$ 5,296.71

*Hp 90010068
4 days
P/P
21/02/19 @ 1155
Reay by paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

No. of repair days 7