

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

4K ~
13/2/19

VEHICLE ESTIMATE

ATX
 ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 07/02/2019@0395HRS
 VRN : SLT9648A
 MODEL : Honda Vezel
 TP VRN : SJT3940T

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear Bumper <i>DE</i>	1	\$ 508.00	\$ 508.00	✓
2 Rear Bumper Clips <i>re</i>	10	\$ 5.50	\$ 55.00	✓
3 Rear Bumper Reflector LH/RH <i>X SVC</i>	2	\$ 151.00	\$ 302.00	
4 End Panel <i>?</i>	1	\$ 416.00	\$ 416.00	?
5 End Panel Upper Garnish <i>?</i>	1	\$ 95.00	\$ 95.00	?
6 Tailgate <i>TA</i>	1	\$ 953.00	\$ 953.00	✓
7 Tailgate Lock <i>X SVC</i>	1	\$ 107.00	\$ 107.00	
8 Vezel Logo <i>re</i>	1	\$ 45.00	\$ 45.00	✓
9 "H" Logo <i>re</i>	1	\$ 28.00	\$ 28.00	✓
10 Rear Windscreen Moulding <i>re</i>	4	\$ 15.00	\$ 60.00	✓
11 Rear Reverse Sensor <i>?</i>	s/nett 1	\$ 200.00	\$ 200.00	?
12 Sealant <i>rec</i>	s/nett 1	\$ 45.00	\$ 45.00	✓
Discount 20%			\$ (513.80)	
		TOTAL	\$ 2,300.20	

2. Labor Charges

1 Panel beat, cut, weld, re-align and replace damaged parts of rear portion		\$ 1,000.00
2 Spray painting on rear portion of affected area	250	\$ 1,000.00
3 Conduct water seepage test	30	\$ 120.00
4 Remove & reinstall 2 pieces bumper sensors	60	\$ 120.00
5 Cavity treatment on new parts	40	\$ 80.00
6 Remove & reinstall tailgate windscreen glass	120	\$ 180.00
7 Transfer tailgate lock & mechanism to new tailgate	80	\$ 150.00

Panel Sub Total : \$ 2,650.00

Grand Total : \$ 4,950.20
 Add 7% GST : \$ 346.51
 Nett Total : \$ 5,296.71

No. of repair days: 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Hp 90010068
4 days
P/P
21/02/19 @ 1155
Reay by paint