

Steve (LKK) w/ Arjun 22/2/19 11.45am
 P/P 7 days
 Rec baf & AF spy

✓
 in 220219

SERVICE ESTIMATE

84019 - C00001
 Mr Zhong Shijun
 150 Tanglin Road

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 12/02/2019

WIP No. : 52545

Veh.In/Out: 07/02/2019

*Tel.No. :

Reg.No. : S5356CD

Reg.date : 01/01/2015

Mileage : 0

Chassis No: 156 745154 15

Singapore 247969

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Zhong Shijun

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE, REAR SENSOR, REAR END PANEL, ETC	0	3200.00	0		3,200.00 S	2400/
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, REAR END PANEL, ETC	0	2800.00	0		2,800.00 S	2100/
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1600.00	0		1,600.00 S	1200/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	/
	BUMPER COVER REAR XC	1.0 EA	1454.80			1,454.80 S	
	BUMPER MOULDING REAR	1.0 EA	243.90			243.90 S	
	BUMPER SPOILER REAR	1.0 EA	434.30			434.30 S	
	BUMPER RAIL (BEAM) R	1.0 EA	1336.30			1,336.30 S	
	TAIL PIPE BRACKET LH	1.0 EA	44.10			44.10 S	

SERVICE ESTIMATE

84019 - C00001
Mr Zhong Shijun
150 Tanglin Road

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 12/02/2019

WIP No. : 52545

Veh.In/Out: 07/02/2019

*Tel.No. :

Reg.No. : S5356CD

Reg.date. : 01/01/2015

Mileage : 0

Chassis No: 156 745154 15

Singapore 247969

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Zhong Shijun

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAIL PIPE BRACKET RH / CUT	1.0 EA	44.10			44.10	S
	SKID PLATE RIM LH XC ✓	1.0 EA	249.30			249.30	S
	SKID PLATE RIM RH XC / CUT	1.0 EA	253.00			253.00	S
	BUMPER BRACKET REAR # ?	1.0 EA	63.00			63.00	S
	BUMPER BRACKET REAR / RH BR	1.0 EA	73.90			73.90	S
	BUMPER BRACKET LHR X X	1.0 EA	66.10			66.10	S
	BUMPER BRACKET RHR X / RH BR	1.0 EA	66.10			66.10	S
	BUMPER BRACKET REAR ?	1.0 EA	73.90			73.90	S
	INNER PANEL (SECTION ?)	1.0 EA	1104.60			1,104.60	S
	TOW COVER REAR XC60 X	1.0 EA	73.90			73.90	S
	SPOILER BRACKET REAR / NRC	1.0 EA	18.00			18.00	S
	PROTECT PLATE REAR X (S/N) / CUT	1.0 EA	1149.70			1,149.70	S
	PARK ASSIST, REAR XC S/N / BR	1.0 EA	1267.80			1,267.80	S
	PARK HOLDER KIT XC60 nec	1.0 EA	36.20			36.20	S
	SPOILER BRACKET REAR NRC /	1.0 EA	12.90			12.90	S
	SPOILER BRACKET REAR NRC /	1.0 EA	12.90			12.90	S
	REFLECTOR LAMP REAR / CUT	1.0 EA	86.60			86.60	S

SERVICE ESTIMATE

84019 - C00001
Mr Zhong Shijun
150 Tanglin Road

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date : 12/02/2019

WIP No. : 52545

Veh.In/Out: 07/02/2019

*Tel.No. :

Reg.No. : S5356CD

Reg.date : 01/01/2015

Mileage : 0

Chassis No: 156 745154 15

Singapore 247969

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Zhong Shijun

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	REFLECTOR LAMP REAR / <i>CUT</i>	1.0 EA	86.60			86.60	S
	EXTERIOR ADHESIVE GL / <i>NEC</i>	1.0 EA	142.20			142.20	S
	ADHESIV CHEMICAL / <i>NEC</i>	1.0 EA	334.20			334.20	S
	D WELDING PRIMER / <i>NEC</i>	1.0 EA	350.00			350.00	S

Gross Total. 17,128.40

Net..... 17,128.40

GST @ 7.0% 1,198.99

Total..... 18,327.40

Paid..... 0.00

Please Pay.. 18,327.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GST: S=Standard; O=Out of Scope; Z=Zero Rated