

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD /0171/2019/GW
Date : 9-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tai Hwei Yee
Address : 10G Braddell Hill
#19-27
Singapore 579726
Telephone : HP +65 81263277
Type of Claim : Own Damage Claims
Policy No. : 1800065855
Vehicle No : **SDJ 9318 A**
Model Code : Audi A3 1.0 Sportback
Model / Year : 7/6/2018
Engine No : CHZ 939680
Chassis No : WAUZZZ8V2JA112406
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Feb-19
Place of Accident : CNR Upper Serangoon & Braddell Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDJ 9318 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, lhs front fender, bonnet and headlight. Inspect front lock carrier for damage. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,700.00 1250	
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,200.00 1650	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SDJ 9318 A**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,698.00	+
2	FRONT BUMPER FIXING PARTS <i>no n</i>	\$ 170.00	+
3	RADIATOR GRILLE <i>cracked</i>	\$ 1,301.00	✓
4	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 174.00	?
5	AIR CONDITIONER STICKER <i>na</i>	\$ 7.00	✓
6	SIGN "CAUTION" <i>n</i>	\$ 13.00	✓
7	FRONT BUMPER GUIDE SECTION-LH	\$ 35.00	+
8	FRONT BUMPER GUIDE SECTION-RH	\$ 35.00	+
9	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	+
10	FRONT BUMPER CLOSING ELEMENT-RH	\$ 270.00	+
11	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 171.00	+
12	FRONT BUMPER COVER <i>cracked</i>	\$ 111.00	✓
13	FOAM FILLER PIECE ?	\$ 172.00	?
14	FRONT BUMPER SIDE REINFORCMENT ?	\$ 660.00	?
15	FRONT FENDER-LH <i>Repair</i>	\$ 778.00	+
16	FRONT FENDER UPPER BRACKET-LH	\$ 25.00	+
17	FRONT FENDER BRACKET-LH	\$ 43.00	+
18	FRONT FENDER CLOSING ELEMENT-LH	\$ 56.00	+
19	FRONT FENDER BRACE-LH	\$ 88.00	+
20	LED HEADLIGHT-LH <i>Cracked</i>	\$ 5,029.00	✓

SUB-TOTAL SPARE PARTS CHARGES : \$ 11,106.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDJ 9318 A

S/N	Parts Description		Damaged Par S/Nett
21	BONNET <i>Dented</i>		\$ 2,501.00 ✓
22	BONNET ATTACHMENT PARTS ?		\$ 149.00 ?
23	BONNET EDGE PROTECTION <i>in</i>		\$ 25.00 ✓
24	BONNET CATCH HOOK <i>new</i>		\$ 81.00 +
25	BONNET STRIKER-LH/RH <i>3 new</i>	2	\$ 200.00 +
26	BONNET CATCH HOOK		\$ 58.00 +
27	FRONT NO. PLATE <i>Best</i>	S/N	\$ 25.00 ✓
28	SUNDRIES ?		\$ 300.00 ?
TOTAL SPARE PARTS CHARGES			: \$ 14,445.00
TOTAL LABOUR CHARGES			\$ 5,452.00
GRAND TOTAL			<u>\$ 19,897.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 13/02/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant