



Mercedes-Benz

## Finalization

### ESTIMATE FOR SLE1598S

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811  
068811  
63387288

#### Vehicle & Document Information

WIP No 31720  
Reg No/Reg Date SLE1598S / 12/07/2016  
Date In/Mileage 09/04/2019/ 60128  
Chassis No WDD2120342B315148  
Engine No 27492030585610  
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"  
Colour/Trim 021 197 Obsidian Bl/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	09/05/2019/ 16:59	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : GA133020/1 // 14/03/2019 DRIVE IN/EXCESS : 14/03/209 // NIL DATE IN/DATE SURVEY: 09/04/2019 // RASUL LKK BY/AUTHORIZED ON : 09/04/2019 // RASUL LKK A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. A BPIRES RESpray BOOT LID, LEFT REAR FENDER AND REAR BUMPER A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS. A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT A BPILAB REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS AND SEATS FOR NEC. REPAIRS. X BOOT LID MERCEDES STAR X GROMMET X BOOT LID E200 MODEL PLATE X LEFT REAR LAMP COMBINATION X REAR BUMPER X NUT-AND-WASHER ASSEMBLY				
Attn: <b>Rasul</b> <b>06</b> Working Days				
				2400.00
				1800.00
			0.10	380.00
				120.00
				480.00
	1.00	48.25	00.00	48.25
	3.00	2.29	00.00	6.87
	1.00	83.60	00.00	83.60
	1.00	712.05	00.00	712.05
	1.00	1876.41	00.00	1876.41
	3.00	0.99	00.00	2.97

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 7,910.15  
7% GST on 7910.15 553.71

Authorized signatory and company stamp

Total Payable 8,463.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

SUPPLEMENTARY

## ESTIMATE FOR SLE1598S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811  
068811  
63387288

### Vehicle & Document Information

WIP No **31720**  
Reg No/Reg Date **SLE1598S / 12/07/2016**  
Date In/Mileage **09/04/2019/ 60128**  
Chassis No **WDD2120342B315148**  
Engine No **27492030585610**  
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**  
Colour/Trim **021 197 Obsidian Bl/ 042 241 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator		
CSI00001	Cash	09/05/2019/ 16:59	YK	395 / Yik Chan Hoe		
		Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X	NUT-AND-WASHER ASSEMBLY		3.00	0.99	00.00	2.97

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 2.97** **0.21**

Authorized signatory and company stamp

**Total Payable 3.18**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg