ASS, REC. BY	REF: C3 SM01900	2737/KIS d3 S=	cial Instruction:
Surveyor	Kalvin Assignmen	T (Office)	
From (Person	o: Girdh Puvi loong or	3M0	Date/Time: 14/2/1961 9-520W
Estimated Co.		sill to:	
	SITT RESIOD RESIEVA/INVINVICS		5011 2000
To Inspect Vo			FBH 370R
at Workshop	111/s Comfurt Delgo	Tel:	C>148300
of	- 51		
Policy No:	PFP00010)MMP110	Claim No: (MTD)	900847
Sum Insured:		Excess:	
Make of Veh (Client's Recor			D.O.A. 72/2 2019
	/ REP. / REV 24 HRS (W)		
Date/Pines	742 4 2 0 0 0 0 0	1.0000	11.O.D. Endorsement
Date/Time.	74/2 196 9-53em Person Contacted:	Jumen	chicle INI/OUT
Date/Time	Action/Instruction () Estimate		
	SHD 7263x-x		
	FBH 3702-X		
	,		

~	*	mi.	
×	-	ъ.	

		ASSIGNMENT	T :		
From -	Date:	Veh No:	SHP 72 63 x	Tr Regni 27 Nov	2018
Estimated Cost:			I M. Cycle / Bus / Van /	Yr Regn: NoV	210
DDITP NES ITPRES I DE	DRESTEVATINVIMV		k / Trailer or	CALL COURS WONET!	
to insped Vehicle No:		Make:		Prins 00 13	200
et Workshop m/s		Colour	Toyota 1	AIC: Ins God I std	4.5
ol		Sp.Reading	22955	T/Radio: Insped / Std	
rswed:	1	Eng/No:	12135		INTINA
Policy No.		C/No:	TTOK	(B3.F4003077	
Alams Ns.		The second	Good FA Poor Bur	The second second	74)0
Numbrished:	Excess:		norger / Jammed / Leake		
(Client's Record)			norder / Jammed / Leake		
Make of Veh;		in Thomas ex	iil / S/Rim / ST A/Rim		
		Tyre Size;		95/65 Ris	
(Policy Condition)			RE T	-, 0, 10,	
Remark: The veh had co		S O/S BS/DUN	/EXNOVATERY /FS / LIZ	ZA / MIC / OHTSH / PID / Ct	HALL.
repair at the tir	ne of inspection.	10.10	Y @ or	4	zientr
Ball or Market Value:					
IDAC Accident Room:	Consistent? : Yes or No	Front R/Sat.	2	Rear Rear	
GIA / PR Seen:	Consistent? : Yes or No	L/Bal.		R/Bal,	
Est Repairs:	days Res.: Yes or No		12/2/19		mm
Lum Sum:	% 3 Val.: Yes or No	_	1-11-	DGE / love	7
		Ourtey	2	() ()	ang)
CA / REV / REP.			Damages: Frt / Rear C	DIS N/S V/C Rooflop - 0/5	0.01
Drafé;	Person Contacted;	le: NI I OUT			
Dale / Time Actio	on / Instruction	11/8	UIC / Chassis frame / F	sody Structure affected du	e to collision.
	hand 1919 12465.	93/ 3 Pys.		Sompo	
(\$	515.62 Red -	17%)		110	
-				1	1
-	RECE	IVED:19 FE	2019	/ //	wenda
-		2	A.		7
				* V	1-1-
		+0		(4	1/2/20
	ente ix	311			20 - 11 C
Dale/Time, File Pass 10?	: Prell, Report	. Dava C	f Repair: 3	/	
19/02/19		5-4-5		Survey Fee:	2177
Date/Time, File Railum to?	: Final Report	Resurv	rey No. of Trip:	Transportation:	10 520
2)		A 2 4 F	Site Inen (\$		10
2	-	Add Fee:		4	
Report Format	4		Interview (\$	Photos	
55-200 (S. 2017)	\$ 2,465.93 P/P		Tech Inve 15) Obets	2/2
			THE THINK IN		260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

GNOH PAU LOONG

Date: 19 Feb 2019

Preliminary Advice

Insured Vehicle No : FBH370R

TP Vehicle No

: SHD7263X

Accident Date

: 12/02/2019

Make

Attn:

: Toyota Prius 5DR

Assignment Date

: 14/02/2019

Est. Duration of Repair

Date of Inspection

: 14/02/2019

:S\$

: 3 Days

Inspection At

: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive Singapore 508969

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,981.55
Revised Amount	:S\$	2,465.93
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,465.93

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

have also confirmed excess and policy coverage.
h

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified TRA	Est Submitted	Adi Assigned	Arti Rot	Adi Sub	mittad	This Auth ed	Status		
Main	13 Feb 2019		14 Feb 2019 09:52 Assign	1107110			77.8.74.0.1	10000000	ssignmen Case	it
	Main	Re	ference	Y	Claim Details	T	Documen	its] _	Show All
CLAIM S	UBFOLDER DE	TAILS				[Create	ed by insurer]	dilementary (up)		
Insured:	ISMAIL B	IN ABD HAMID,	ID: S1154345F							
Main Claimant:	COMFORT	TRANSPORTAT	ION PTE LTD,	Co. Reg. N	o.: 199303821R					
Vehicle Re No.:	sHD726	зх			Date of Loss:	oss: 12/02/2019 00:00 - :59				
Claim Typ	e: TP / CMT	TD1900847			Policy/Cover Note No.:	D18MTMC01000974 (Third Party Only)				
Vehicle Re No. (Insured):	FBH370R				Policy No. (Claimant):					
21 - 15					Excess:					
Repairer:	ComfortD	elGro Engineeri	ng Pte Ltd (Loy	ang) 59 Lo	yang Drive, 5089	69 Loyan	g - Tel: 6214 8300	3		
Handling Insurer:	Sompo In	surance Singap	ore Pte. Ltd. (H	Q) - Tel: 64	161 6555 [Han	dled by G	NOH PAU LOON	6 - 632952	17]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 25/	/02/2019]			
Adj Asg. Remarks:	-PLEASE B	E INFORMED THA	T OUR INSURED	HAS NOT R	EPORTED THE AC	CIDENT -	NO TP SAS & ESTI	MATE SUBI	MITTED	
ASSOCIA	ATED MAIL RE	CEIVED						View All	Compose	Case M
There are	no mail for this	case.					-			
ALL ASS	OCIATED TAS	KS-				View A	All Search Tasks	Create N	ew Task	Comple
Due Da	te Priority	Type Task	Group Sub	ect Har	ndler Assign	ed By	Completed Or	n Cre	ated On	Don
No results	5.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies;
- Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	13/02/2019 13:35
Date Of Accident	12/02/2019 21:40
Exact Location Of Accident	HOUGANG ST 61 SLIP RD AVE 4
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD7263X
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD

199303821R Co Reg No FLEETSAFETY@CDGTAXI.COM.SG Email Address

Mobile Phone No

OFFICE-65508768 Alternative Phone No Vehicle Particulars

TOYOTA Manufacturer **PRIUS** Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy NO for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken

TAXI Vehicle Category

Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

MCOM0015 Policy Number

Cover Note Number

Driver

AU CHEE MENG Name of Driver

S1254644J NRIC No 16/09/1957 Date Of Birth OUTDOOR Occupation 20/10/1978 Date Of Driving Pass

40 YEARS AND 3 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-98503555 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address

BLK 520 HOUGANG AVENUE 6 #02-93

Postcode

530520

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident: HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBH370R

Vehicle Make/Model/Colour

Details Of Properties

MOTORCYCLE

Vehicle Category

MOHAMMAD ALFIRDAUS BIN ISMAIL

NRIC/Passport Number

S9721393C

Contact Number

Name of Driver

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

Page 2 of 19

Sketch Plan Pg. 1

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 Interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my dalms;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed;
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CO REG NO 1872073318

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

	No. 2000
MALLE	
H) SHD	
1268x	
FBH	
DISTOR	
SCRIBE CIRCUMSTANCE	1.169 J. O. V. P. B.
	ON 12 Feb 2019 (D) DINO hm I VEH A-
	was driving along the bend straget
	Siderly vot- & from hit west A. Right
	50 C C C C C C C C C C C C C C C C C C C
	50 C C C C C C C C C C C C C C C C C C C
	Rem. at the point of accident wet
	500 Table
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
	Rem. at the point of accident wet
DECLARATION	Rem. at the point of accident wet

Policyholder's Signature Date & Time: Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

CONSTRUCTION FOR GOOD WIT

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:


COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 7263X

MAKE

: TOYOTA PRIUS MODEL



MODEL	: TOYOTA PRIUS	QTY	UNIT PRICE	AMOUNT
	PARTS DESCRIPTION	QII	UNIT PRIOL	\$ 458.60
	REAR BUMPER UNDER COVER			\$ 552.60
	REAR BUMPER SIDE RETAINER			\$ 112.70
	REAR BUMPER CLIPS			\$ 22.00
	RETAINER, REAR BUMPER, SIDE, RH			\$ 94.80
	SEAL, REAR BUMPER SIDE, RH	- 9		\$ 148.40
	(1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			\$ 557.90
	TAIL LAMP ASSY (UPPER) (RH) TAIL LAMP ASSY (LOWER) (RH)			\$ 548.40
				\$ 340.40
	Rem For the (RH) X 1902 SUB TOTAL			\$ 2,495.40
	LESS 25%			\$ 623.85
	DISCOUNTED TOTAL			\$ 1,871.55
	LABOUR CHARGE			3
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 400 600:00
	Wiring Charge			\$ 20 30.0
	Remove/Refix Reverse Sensor			\$ 30 80.0
	TOTAL LABOUR			\$ 1,110.00
	ESTIMATE TOTAL			\$ 2,981.55
	Kalin May			
	14/2/19 1110hz.	the	K Auto Consultants her Repairer of the following securely before after spray of display damages partial de	ng: painting ring resurvey
	Beton Print photo	-1	anti-moss are sitigect to con- find parties of your market or department for the properties of approventies of the same sent to approve to the same sent to	r hit Prejudice" basis Swed errecriveyed and
			know ligebliv recoren desurr	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.02.2019 Time: 17:41:50

Page: 1

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305268577 : SHD7263X : 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(G4)

DATE OF REGN DATE/TIME IN

: 27.11.2018 : 13.02.2019 10:55

ACCIDENT DATE : 12.02.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G REAR BUMPER

1 458.60 25.00 343.95

0002 04-01-0302-2287-G REAR BUMPER UNDER COVER 1 552.60 25.00 414.45

0003 04-01-0302-2267-G REAR BUMPER CLIPS 10 22.00 25.00 16.50

0004 04-01-0302-2965-G REAR BUMPER EXTENSION RH 1 148.40 25.00 111.30

0005 04-01-0302-0585-G TAILLAMP UPPER RH 1 557.90 25.00 418.42

0006 04-01-0302-0795-G TAILLAMP LOWER RH 1 548.40 25.00 411.30

SUB-TOTAL : 1,715.92

JOB NATURE

0000 PB

PANEL BEATING

300.00

0001 SP

SPRAYPAINT CHARGE

400.00

0002 17-01

WIRING CHECK

20.00

0003 L R/I REVERSE SENSOR

30.00

SUB-TOTAL: 750.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.02.2019 Time: 17:41:50

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

. . . 3"

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305268577 : SHD7263X : 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(C

DATE OF REGN : 27.11.2018 DATE/TIME IN : 13.02.2019 10:55 ACCIDENT DATE : 12.02.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,465.92

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

DATE:

MVA NAME & SIGNATURE

COMFORTDELGRO ENGINEERING

305268577 Our Job Ref No : ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date FINALIZATION FORM LKK Fax: KALVIN ANG 12-Feb-19 : SHD7263X Date of Accident : Vehicle Reg No. The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-**FBH 370R** SOMPO INS 1. The repair job shall bill to: The finalized amount shall be: 2. \$1,715.93 Spare Parts after List discount (a) \$750.00 Labour Charges (b) \$2,465.92 Total for Part-By-Part Repair Cost Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost working days. Estimated normal period for repairs: 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you 4. within 7 working days We confirm the estimates and Thank you for your assistance. 5. finalized amount Signature Signature: KALVIN : LIMTS Name Name 62148398 Date 65468156 Fax For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
Medical Fees (on beha of driver, if applicable)	alf			
6 Overrun				

Remarks:			
jan.			

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Breadell Rose Singspore 578/111

Mainins + 65 6380 6280 Facernite - 68 6280 9753

Workings

24 Sanoko Lono Singapore 718156 7 Sungei Kedut Way Singapore 72979

Date/Time: 13.02.2019 16:50

Page : 1


JOB CARD Sales Order: JC NO.: 305268577 ARC Repair TP(CLSO)1 Team: MILEAGE REGN NO.: SHD7263X COMFORT TRANSPORTATION PTE LTD FUEL MAKE: TOYOTA 7010045 OMERNO 383 SIN MING DRIVE E.....F PRIUS HYBRID(G4)13.02.2019 10:55 MODEL Singapore SINGAPORE 575717 YR OF MANU 27.11.2018 65508755 TARGET DATE (R) (P) CHASSIS CODE JTDKB3FU003077450 COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.02.2019 NATURE: 3P 12.02.19/C

S/NO

LABOR CODE



KED & F	PASSED OUT BY:			
	SERVICE ADVISOR			CUSTOMER'S SIGNATURE
ledgeme	ent Slip		Exit Pass	
Vo.:	SHD7263X	LIMTS	Vehicle No.: SHD7263X	
	• Advisor	Signature/Date	Name of Service Advisor	Date
turned t	s Service Reception upon a	sollection	To be kept by Security Guard	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D18MTMC01000974

Engine No:

Odometer:

Chassis No:

CS/SMO19002737/K1SD3N2

2ZR2B81811

22955 km

JTDKB3FU003077450

Date:

20/02/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Claimant Vehicle No:

Date of Loss:

SHD7263X

12/02/2019

Insured Vehicle No:

Policy No:

FBH370R

TP

Nature of Claim:

Claim No:

CMTD1900847

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD7263X

Make & Model: Reg. Date:

TOYOTA PRIUS, 1.8 (A) 27/11/2018 (Man. Year: 2018)

Colour:

Blue 1798 cc

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

195/65R15

Yokohama 7 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 195/65R15

Yokohama 7 mm Yokohama 7 mm

Yokohama 7 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 1,871.55 0.00	Adjuster's 1,715.92 0.00	Difference 155.63 0.00	Diff % 8.32
Labour Paintwork Labour	1,110.00 0.00	750.00 0.00	360.00 0.00	32.43
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,981.55	2,465.92	515.63	17.29
+ GST 7.00/7.00% (S\$)	208.71	172.61	36.10	17.30
Nett Amount (S\$)	3,190.26	2,638.53	551.73	17.29

INSPECTION

Date of Assignment:

14/02/2019

Date Inspected:

14/02/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,465.93

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 19 Feb 2019)

Parts:

144

TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD7263X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	Cut	552.60 FL	*552.60 FL
3	1		*REAR BUMPER SIDE RETAINER *REAR BUMPER CLIPS	Serviceable Necessary	112.70 FL 22.00 FL	*- FL *22.00 FL
5 6	1		*RETAINER,REAR BUMPER,SIDE,RH *SEAL,REAR BUMPER SIDE,RH	Serviceable Missing	94.80 FL 148.40 FL	*- FL
7 8	1		*TAIL LAMP ASSY (UPPER)(RH) *TAIL LAMP ASSY (LOWER)(RH)	Cracked Cracked	557.90 FL 548.40 FL	*557.90 FL
9 F=Fra	1 inchise	part. L=ListIte	*REAR FENDER (RH)(NPA)	Repair	0.00 FL	*- FL
				Sub Total (S\$)	2,495.40	2,287.90 571.98
			- List Item Discount on L Item	s 25.00/25.00% (S\$)	552.60 FL 112.70 FL 22.00 FL 94.80 FL 148.40 FL 557.90 FL 548.40 FL 0.00 FL	
				Total Parts (S\$)	1,871.55	1,715.92
			Report was unsubmitted durin	g this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	WIRING CHARGE	New	30.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
		Gross Labour Cost (S\$)	1,110.00	750.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >