

f poli k.s. Hk

Estimate Report

02/13/2019

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTKB/TP/1902/004
Policy No:	5096870535-01	Date of Loss:	11/02/2019
Vehicle Reg. No.:	SJZ99K	Driveable?	yes
Driver Age:	08/09/1977	Third Party Vehicle No.:	SLW107M
Any Injuries?	no	Contact No:	97707682
Insured/Claimant:	TERENCE FOO KONG ANG	Driver:	TERENCE FOO KONG ANG

Make/Model:	Honda, Civic 1.8L - JHMFD16	Vehicle Reg. Date:	19 Jan 2009
Vehicle Colour:	WHITE	Engine Number:	R18A14008475
Chassis No:	JHMFD16309S201444	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	6

Description of Accident/loss HEAD TO SIDE

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,720.85
Miscellaneous Items	40.00
Labour	280.00
Paintwork Labour	670.00
Towing	0.00

Gross Total(S\$):	4,710.85
GST 7.00%(S\$):	329.76
Nett Amount(S\$):	5,040.61

This claim is handled by: may chai

not Authorised H/S \$2200
Hk
15/2/19
When the other rep -
Hdy.

Warranty conditions apply
the Resurvey of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature: _____
Date: _____

P-1697.50
10%
1-1862.85
S.N-40.00
1chm-890.00
2792.85
202
2234

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BONNET <i>but/3uc</i>	0.00	350.00	+10.00 ✓	385.00
2	1	FRONT FENDER LH <i>but/3uc</i>	0.00	175.00	+10.00 ✓	192.50
3	1	FRONT BUMPER <i>to n</i>	0.00	200.00	+10.00 ✓	230.00 <i>235</i>
4	1	FRONT BUMPER FOG LAMP LH <i>one</i>	0.00	240.00	+10.00 ✓	264.00
5	1	FRONT BUMPER FOG LAMP GARNISH LH <i>(4)</i>	0.00	70.00	+10.00 ✓	77.00
6	1	FRONT BUMPER SIDE RETAINER LH <i>but</i>	0.00	10.50	+10.00 ✓	11.55
7	1	FRONT HEADLAMP LH <i>one</i>	0.00	280.00	+10.00 ✓	308.00
8	1	FRONT HEADLAMP HID BALLAST LH <i>11</i>	0.00	280.00	+10.00 ✓	308.00
9	1	FRONT HEADLAMP LOWER BRACKET LH <i>but</i>	0.00	18.00	+10.00 ✓	19.80
10	1	FRONT HEADLAMP HID BULB LH <i>11</i>	0.00	210.00	+10.00 ✓	231.00
11	1	FRONT FENDER INNER SHIELD LH <i>to n</i>	0.00	55.00	+10.00 ✓	60.50
12	1	FRONT BUMPER REINFORCEMENT <i>to n</i>	0.00	165.00	+10.00 ✓	181.50
13	1	FRONT DOOR LH <i>n</i>	0.00	475.00	+10.00 ✓	522.50
14	1	FRONT WINDSCREEN OUTER PILLAR LH <i>n</i>	0.00	450.00	+10.00 ✓	495.00
15	1	FRONT SUPPORT PANEL <i>n</i>	0.00	395.00	+10.00 ✓	434.50

Total Parts (\$\$) 3,720.85 *1563.50***Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	10	FRONT BUMPER CLIPS <i>all</i>	0.00	20.00	0.00 ✓	20.00
2	10	FRONT FENDER INNER SHIELD CLIPS <i>all</i>	0.00	20.00	0.00 ✓	20.00

Sub Total (\$\$) 40.00 *S.N 40*
*later 890***Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00 <i>20</i>	30.00
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	250.00	250.00	0.00 ✓	250.00

Gross Labour Cost (\$\$) 280.00**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	20.00	20.00	0.00 ✓	20.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	650.00	650.00	0.00 <i>600</i>	650.00

Gross Labour Cost (\$\$) 670.00

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BUMPER LOWER SPOILER LH	11 35.00	35.00	+10.00	38.50
2	1	HORN	17 30.00	30.00	+10.00	33.00
3	1	RESONATOR LH	CN 130.00	130.00	+10.00	143.00
Total Parts (\$\$)						214.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Sub Total (\$\$)						0.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (\$\$)						0.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (\$\$)						0.00

< END OF ESTIMATES >