

Acknowledged by Repairer
Signature: _____
Date: _____

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 / 62717433 FAX: 62745715

Pg 2

DOA: 31.1.2019

No	Description	Unit	List (\$)
	Special Nett		
1	FRONT LH FENDER SEALANT	1	\$ 160.00 X
2	REVERSE SENSOR	SET	\$ 360.00 ✓ 200
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 800.00 400
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 800.00 400
3	Check Wiring System & Light	1	\$ 100.00 30
4	Anti Rust Treatment	1	\$ 120.00 X
5	Wheel Aligment	1	\$ 100.00 X
6	To Remove / Refix Rear Reverse Sensor	1	\$ 180.00 20
7	To Remove/Refix Rear Inner Compartment & Carpet To Facilitate Repair	1	\$ 120.00 30
	Total (B) :	\$	2,740.00
	Grand Total:	\$	5,305.45