

000000

INS. CASE OWNER:

stacey | CC 4/AXAT900 2742, K9JB3

LKK

IDAC:

Surveyor:

Kenneth

DOE:

20/2/19

Date / Time:

4/2/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMC 904AG

Name of Insured:

Tom Turk Chief

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

11/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SMO1001C / 182664

Policy No.:

UPR / 1158833

Make / Model:

Renault

Place of Accident:

PIONEER RD WATH

If NO. Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SMC 904AG

SEP 11/19

SMC 1582K



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

BH

auto

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SEP 11/19

SMC 904AG

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup):

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

22-2-19 LIABILITY CLEAR SENT TO TP BY EM.

RM - PENDING FINALIZATION DV IN (File Pass Admin to close).

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

HS

SS 2850.00

(9 days)

Reduction: \$3206.10 = 54

FINAL SETTLEMENT

Date/Time:

6/1/19 / 6/1/19

Confirm with:

Yuni Chi

Email:

Call:

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No. : 28

If NO or B 28. Ass. Lia :

100%

Repair Cost: (w/ GST)

SS 2675.00

(ASA'S instruction)

Loss of Rental (LOR):

SS 1200.00

(12 days)

x \$100

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee

\$350/-

Total:

SS 3875.00

Global Sum SS:

3870.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS 3870.00

Name 1:

BH Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

ASM(AXA)

20/2/19

SFP 81314

01 15

Applicant's Name

Vehicle Type: ☒ PWS / ☐ RES / ☐ OD RES / ☐ EVA / ☐ BV / ☐ MV

Registered Vehicle No.

SFP 81314

at time of inspection

BH Auto

Color: BLK / Sin Ming Ind. Est. & C. #0111

Location

Expiry Date

Claims No.

Damage Incurred

Excess

Police Report No.

Make of Vehicle

11am 12pm

Vehicle Condition

Remarks: The veh had commenced its repair at the time of inspection.

Est. or Market Value

851K

RDAC Accident Report

Consistent? - Yes or No

GIA / PH Seen

Consistent? - Yes or No

Est. Report

09

days Rep. Yes or No

Est. Date

W 14/2/19

3 Val. Yes or No

CA / REV / REP / 24 HRS

Date

Person Contacted

Vehicle: IN / OUT

Date / Time

Action / Instruction

20/2 Est not ready

45 \$2850/-

Vehicle

Type: ☒ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

Toy Vios

CC

1997

Colour

M. Gold

AC

Insured / SIB / H / HA

Cap Branding

49137

10 Code. Insured / SIB / H / HA

Engine

CN

M14FBT91F3406033820

Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/Rim / ☐ STD / ☐ AirRim or

Tyre Size

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

9

mm

R/Bal

9

mm

L/Bal

9

mm

L/Bal

9

mm

D.O.A.

11/2/19

D.O.

20/2/19

Survey held at

Des. of Damages: ☒ Frt / ☐ Rear / ☐ Q/S / ☐ N/S / ☐ W/C / ☐ Rooftop or

& B

The W/C / Chassis frame / Body Structure affected due to collision

(Red = \$3286.10 / 54%)

* 8 repair days + 2 PRS + 1 Sunday = 12 days.

Date/Time: File Photo

☐

Preli. Report

Days Of Repair:

File

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return

Survey Fee

Transportation

2

File

Add Fee:

☐

Site Insp. (R)

1 x 100.00

☐

Interview (R)

1 Hour

☐

Team Insp. (R)

1 Hour

☐

Witness (R)

1 Hour

Report Format

Lump Sum / LBU

Total

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SFP8131Y
Assessment number: BA1058
Version: 1810
Date calculated: 16/05/2019 6:53 PM

Full Report
Registration: SFP8131Y
Printed: 16/05/2019 6:53 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Janice Koh	Currency:	SGD
Claim Reference:	SFP8131Y	Date of Incident:	11/02/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	VIOS
Sub Model:	E
Model Sheet Number:	70 AY 52
Registration:	SFP8131Y
VIN number:	
Odometer:	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:	
Date of Inspection:	19/02/19

Damage Areas

All ☐
Underbody ☐



BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SFP8131Y
 Assessment number: BA1058

Version: 1810

Date calculated: 16/05/2019 6:53 PM

Full Report
 Registration: SFP8131Y
 Printed: 16/05/2019 6:53 PM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B010)	R + R FRONT BUMPER		4.0	18.00
B020)	RENEW FRONT BUMPER (REMOVED)		7.0	31.50
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
B030	R + R RADIATOR GRILLE		2.0	9.00
B040)	R + R LEFT HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B310)	RENEW L/R SIDE PANEL (COMPOSITE WORK FOR END PANEL)		57.0	256.50
B410	R + R REAR BUMPER REINFORCEMENT		4.0	18.00
	INCLUDES: BUMPER REMOVE AND REFIT			
B290	RENEW REAR END PANEL (BUMPER REMOVED)		41.0	184.50
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT			
B420)	RENEW REAR BUMPER REINFORCEMENT		1.0	4.50
NO NUMBER	R + R BOOTLID MOULDING		2.0	9.00
NO NUMBER	R + R BOOTLID TRIM		2.0	9.00
640201)	R + R BOOTLID LOCK		3.0	13.50
G020	R + R REAR SCREEN		29.0	130.50
	INCLUDES: REAR PARCEL SHELF AND REQUIRED TRIMS REMOVE AND REFIT			
B420)	RENEW REAR BUMPER		1.0	4.50
B450	R + R REAR SEAT BACKREST		2.0	9.00
NN	sensor R&R / NEW PARTS		5.0*	22.50
1009	FRONT PANEL CPL REPAIR		15.0*	67.50
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		17.80	178.0	801.00
Total of Labour				801.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR PANEL NEW PART PAINTING		20.0	

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SFP8131Y
 Assessment number: BA1058
 Version: 1810
 Date calculated: 16/05/2019 6:53 PM

Full Report
 Registration: SFP8131Y
 Printed: 16/05/2019 6:53 PM

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	L/R SIDE PANEL NEW PART PAINTING		24.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	TOWING HOOK COVER NEW PART PAINT K1R		3.0	
	REAR BUMPER NEW PART PAINT K1R		9.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.54
3481	L/R SIDE PANEL NEW PART PAINTING	27.97
0281	FRONT BUMPER NEW PART PAINT K1R	44.67
0358	TOWING HOOK COVER NEW PART PAINT K1R	0.35
2581	REAR BUMPER NEW PART PAINT K1R	34.20
1009	FRONT PANEL CPL SURFACE PAINT	8.80

Labour Cost - Paint

	Factor	45.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			73.0	
	Preparation Main Work Metal		1.70	17.0	76.50
	Preparation Comp. Work Plastic		0.30	3.0	13.50
Total		10 WU/h	9.30	93.0	418.50

Material Cost - Paint

	Price SGD
New Part Painting	48.51
New Part Painting - Plastic K1R	79.22
Surface-/Blend Paint	8.80
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	163.63

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0253	FRONT BUMPER GRILLE	53112 0D300		90.00
0281	FRONT BUMPER	52119 0U913		170.00
0358	TOWING HOOK COVER	52721 0D080		22.00

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SFP8131Y
 Assessment number: BA1058
 Version: 1810

Date calculated: 16/05/2019 6:53 PM

Full Report
 Registration: SFP8131Y
 Printed: 16/05/2019 6:53 PM

Code	Description	Part Number	Supplier	Price SGD
0431	FRONT MANUFACT BADGE	90975 T2008		25.00
0563	LEFT HEADLAMP ASSY	81170 0D570		180.00
2581	REAR BUMPER	52159 0U903		170.00
2640	REAR BUMPER REINF	52023 0D090		100.00
2711	REAR PANEL	58307 0D210		210.00
2944	BOOT SEAL	64461 0D090		60.00
2977	BOOTLID LOCK	64610 0D080		40.00
2979	BOOT MOULDING	76801 0D912		85.00
3013	RR MANUFACTURE BADGE	75447 0D130		20.00
3160	REAR SCREEN BOND KIT PZ49I 00C1131			0.00
3161	LWR REAR SCREEN SEAL 64813 0D250			0.00
3162	UPP REAR SCREEN SEAL 64814 0D100			0.00
3163	REAR SCREEN FIX SET USE SINGLE PARTS			
3170	REAR SCREEN SUPPORTS	56116 22050		0.00
3171	REAR SCREEN SUPPORTS	56115 30100		0.00
3281	L/R LAMP ASSY	81560 0D440		110.00
3481	L/R SIDE PANEL	61602 0D240		370.00
1000	clip	Rear bumper		12.00
1001	sensor	Rear bumper		200.00
1002	clip X2pcs	Tail lamp		2.00
1005	lettering VIOS	Bootlid		20.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,886.00
u: Used parts	Addition(+15.00%)			282.90
	Total			2,168.90

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference: SFP8131Y
Assessment number: BA1058
Version: 1810
Date calculated: 16/05/2019 6:53 PM

Full Report
Registration: SFP8131Y
Printed: 16/05/2019 6:53 PM

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	1,886.00	
Total Parts	282.90	2,168.90
Labour Time Base 10 WU/h		
Total 178.0 WU X 45.00 SGD/h	801.00	
Total of Labour		801.00
Paint Work Time Base 10 WU/h		
Labour Cost 93.0 WU X 45.00 SGD/h	418.50	
Material Cost	163.63	
Total Paint Including Material		582.13
Repair Cost Excludes GST		3,552.03
GST (+7.0%)		248.64
Repair Cost Included GST		3,800.67

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:
Assessment number: BA1058
Version: 1810
Date calculated: 02/20/2019 04:27 PM

Full Report
Registration: SFP8131Y
Printed: 20/02/2019 4:29 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Janice Koh	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-11
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	VIOS
Sub Model:	E
Model Sheet Number:	70 AY 52
Registration:	SFP8131Y
VIN number:	
Odometer:	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:	
Date of Inspection:	2019-02-19

Damage Areas

All ☐
Underbody ☐



BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:
 Assessment number: BA1058
 Version: 1810
 Date calculated: 02/20/2019 04:27 PM

Full Report
 Registration: SFP8131Y
 Printed: 20/02/2019 4:29 PM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B100	R + R LEFT FRONT WING	5.0	22.50	
B100	R + R RIGHT FRONT WING	5.0	22.50	
B010)	R + R FRONT BUMPER	4.0	18.00	
B020)	RENEW FRONT BUMPER (REMOVED)	7.0	31.50	
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
B420	R + R REAR BUMPER SPOILER	1.0	4.50	
B020)	RENEW FRONT BUMPER REINFORCEMENT	2.0	9.00	
B030	R + R RADIATOR GRILLE	2.0	9.00	
B040)	R + R LEFT HEADLAMP	1.0	4.50	
B040)	R + R RIGHT HEADLAMP	1.0	4.50	
B040)	ADJUST HEADLAMPS	2.0	9.00	
B140	R + R FRONT PANEL CPL	13.0	58.50	
B310)	RENEW L/R SIDE PANEL	57.0	256.50	
	(COMPOSITE WORK FOR END PANEL)			
B310)	RENEW R/R SIDE PANEL	50.0	225.00	
	(COMPOSITE WORK FOR END PANEL)			
B410	R + R REAR BUMPER REINFORCEMENT	4.0	18.00	
	INCLUDES: BUMPER REMOVE AND REFIT			
B290	RENEW REAR END PANEL	41.0	184.50	
	(BUMPER REMOVED)			
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT			
B420)	RENEW REAR BUMPER REINFORCEMENT	1.0	4.50	
B310)	RENEW BOTH TAILAMP BRACKET	7.0	31.50	
NO NUMBER	R + R BOOTLID MOULDING	2.0	9.00	
B350	R + R BOOTLID	6.0	27.00	
B370	R + R L/BOOTLID HINGE	2.0	9.00	
B370	R + R R/BOOTLID HINGE	2.0	9.00	
NO NUMBER	R + R BOOTLID TRIM	2.0	9.00	
640201)	R + R BOOTLID LOCK	3.0	13.50	
G020	R + R REAR SCREEN	29.0	130.50	
	INCLUDES: REAR PARCEL SHELF AND REQUIRED TRIMS REMOVE AND REFIT			
B420)	RENEW REAR BUMPER	1.0	4.50	
B450	R + R REAR SEAT BACKREST	2.0	9.00	
M020	R + R RADIATOR	4.0	18.00	
	INCLUDES: BLEED COOLING SYSTEM			

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:

Assessment number: BA1058

Version: 1810

Date calculated: 02/20/2019 04:27 PM

Full Report

Registration: SFP8131Y

Printed: 20/02/2019 4:29 PM

Code	Description	WU	Price SGD
NN	sensor R&R / NEW PARTS	5.0*	22.50
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	26.10	261.0
	Total of Labour		1,174.50

Paint

Code	Description	WU	Price SGD
	Paint Work		
	SYSTEM AZT		
		Time Basis 10WU/h	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	REAR PANEL NEW PART PAINTING	20.0	
	L/R SIDE PANEL NEW PART PAINTING	24.0	
	R/R SIDE PANEL NEW PART PAINTING	24.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	
	TOWING HOOK COVER NEW PART PAINT K1R	3.0	
	REAR BUMPER NEW PART PAINT K1R	9.0	

Paint Material Per Part

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	8.80
2711	REAR PANEL NEW PART PAINTING	20.54
3481	L/R SIDE PANEL NEW PART PAINTING	27.97
3482	R/R SIDE PANEL NEW PART PAINTING	27.97
0281	FRONT BUMPER NEW PART PAINT K1R	44.67
0358	TOWING HOOK COVER NEW PART PAINT K1R	0.35
2581	REAR BUMPER NEW PART PAINT K1R	34.20

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		97.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.30	3.0	13.50
Total	10 WU/h	117.0	526.50

BH Auto Services Pte Ltd

1 Sin Ming Industrial Est Sector C

575636

Claim Reference:
Assessment number: BA1058
Version: 1810
Date calculated: 02/20/2019 04:27 PM

Full Report
Registration: SFP8131Y
Printed: 20/02/2019 4:29 PM

Material Cost - Paint	Price SGD
New Part Painting	76.48
New Part Painting - Plastic K1R	79.22
Surface-/Blend Paint	8.80
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	191.60

Spare Parts

				prices as at 2015-06-01/01	Price SGD	
Code	Description	Part Number	Supplier			
0253	FRONT BUMPER GRILLE	53112 0D300		CPL	90.00	✓
0281	FRONT BUMPER	52119 0U913		Bu	170.00	✓
0317	L/F BUMPER BRACKET	52536 0D140			30.00	7X
0318	R/F BUMPER BRACKET	52535 0D140		NW	30.00	7X
0340	FRT BUMPER REINF	52021 0D140			120.00	7X
0358	TOWING HOOK COVER	52721 0D080		MY	22.00	✓
0407	L/GRILLE TRIM	53124 0D080		NW	35.00	7X
0408	R/GRILLE TRIM	53121 0D160			35.00	7X
0431	FRONT MANUFACT	90975 T2008		MY	25.00	✓
	BADGE					
0563	LEFT HEADLAMP ASSY	81170 0D570		MY/M	180.00	✓
0564	RIGHT HEADLAMP ASSY	81130 0D570		NW	180.00	7X
0988	LOCK CARRIER STRUT	53215 0D121		R	55.00	X
1009	FRONT PANEL CPL	53210 0D928		R	200.00	X
2581	REAR BUMPER	52159 0U903		Bu	170.00	✓
2619	L/R INN BUMPER BRKT	52592 0D200			12.00	7X
2620	R/R INN BUMPER BRKT	52591 0D200		NW	12.00	7X
2621	L/R OUT BUMPER BRKT	52156 0D060			38.00	7X
2622	R/R OUT BUMPER BRKT	52155 0D070			38.00	7X
2640	REAR BUMPER REINF	52023 0D090		NW	100.00	✓
2711	REAR PANEL	58307 0D210		R	210.00	✓
2944	BOOT SEAL	64461 0D090		Gr	60.00	✓
2953	L/R HINGE	64503 0D040		R	30.00	X
2954	R/R HINGE	64503 0D040		R	30.00	X
2976	REAR LOCK STRIKER	64621 33030		R	10.00	X
2977	BOOTLID LOCK	64610 0D080		NW	40.00	✓
2979	BOOT MOULDING	76801 0D912		CPL	85.00	✓
3013	RR MANUFACTURE	75447 0D130		NW	20.00	✓
	BADGE					
3160	REAR SCREEN BOND KIT PZ49I 00C1131				0.00	
3161	LWR REAR SCREEN SEAL 64813 0D250				0.00	
3162	UPP REAR SCREEN SEAL 64814 0D100				0.00	

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:

Assessment number: BA1058

Version: 1810

Date calculated: 02/20/2019 04:27 PM

Full Report

Registration: SFP8131Y

Printed: 20/02/2019 4:29 PM

Code	Description	Part Number	Supplier	Price SGD
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3170	REAR SCREEN SUPPORTS	56116 22050		0.00
3171	REAR SCREEN SUPPORTS	56115 30100		0.00
3281	L/R LAMP ASSY	81560 0D440	my cm	110.00 ✓
3282	R/R LAMP ASSY	81550 0D430	NIV	110.00 7X
3339	L/R REFLECTOR	81590 0D110	Sm	65.00 X
3340	R/R REFLECTOR	81580 0D130	Sm	65.00 X
3481	L/R SIDE PANEL	61602 0D240	Bm	370.00 ✓
3482	R/R SIDE PANEL	61601 0D230	SL	370.00 XX
4907	BOOTLID TRIM	64719 0D061C0	Sm	150.00 XX
4986	RR LUGG COMPART TRIM	58387 0D110	NIV	95.00 7X
1000	clip	Rear bumper	Sm	12.00 ✓
1001	sensor	Rear bumper	Sm	250.00 2000
1002	clip X2pcs	Tail lamp	Sm	2.00 ✓
1003	shield LH	Rear fender	Sm	22.00 X
1004	shield RH	Rear fender	Sm	22.00 X
1005	lettering VIOS	Bootlid	Sm	20.00 ✓
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 3,690.00
u: Used parts				Addition(+15.00%) 553.50
Total				4,243.50

*Not Authorized
Resurvey B4 paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BH Auto Services Pte Ltd
1 Sin Ming Industrial Est Sector C
575636

Claim Reference:
 Assessment number: BA1058
 Version: 1810
 Date calculated: 02/20/2019 04:27 PM

Full Report
 Registration: SFP8131Y
 Printed: 20/02/2019 4:29 PM

Final Calculation

	SGD	SGD
Parts	3,690.00	
Addition(+15.00%)	553.50	
Total Parts		4,243.50
Labour Time Base 10 WU/h		
Total 261.0 WU X 45.00 SGD/h	801 1,174.50	
Total of Labour		1,174.50
Paint Work Time Base 10 WU/h		
Labour Cost 117.0 WU X 45.00 SGD/h	418.50 526.50	
Material Cost	163.63 191.60	
Total Paint Including Material		718.10
Repair Cost Excludes GST		6,136.10
GST (+7.0%)		429.53
Repair Cost Included GST		6,565.63

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

CHIJMESの日系ヘアサロン

① Shun Sakurai Hair&Beauty

X

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Cnc Removal Toyota A110 1.5A



2.38% p.a. (lowest interest rate)
Cars Financing \$1800
Downpayment Monthly From
\$568
GV Credit Pte Ltd. Marked



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

4 vehicles

Toyota Vios

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Vios		Any	Any	2014	Any	Any	Any	Available
	Toyota Vios	1.5A E	\$47,000	\$8,100 /yr	26-May-2014	1,497 cc	58,700 km	Sedan	Available
1 Owner And Agent Unit! Well Maintained And Serviced Regularly At Borneo Motors Only, Last Servicing By Borneo Motors At Jan 19 And Tyres Changed On June 18. Most Popular Mid Size Family Sedan, Car Is...									
Car Buyers Automotive Pte Ltd									
Posted: 13-Feb-2019 Tags: 2014 Toyota Vios, 2014 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A G	\$52,800	\$8,690 /yr	19-Aug-2014	1,497 cc	49,920 km	Sedan	Available
Just Arrived Only With 1 Owner, G Grade Vios, Lowest Price Tag In The Market Need No Compare With Others, Low Mileage Need To Be Fast Before It's Gone! Non Rental Unit, Accident Free, Regular Service B...									
AL Autocar Pte Ltd									
Posted: 12-Feb-2019 Tags: 2014 Toyota Vios, 2014 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A G	\$49,800	\$8,560 /yr	14-May-2014	1,497 cc	-	Sedan	Available
100% Loan Available. Viewing Till 9pm Possible. Priced To Clear. Come View This 1 Owner Black Unit, Well Maintained By Borneo Motors. Genuine Mileage. 100% Major Accident Free! Still Under Warranty By B...									
Posted: 01-Feb-2019 Tags: 2014 Toyota Vios, 2014 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A G	\$49,500	\$8,470 /yr	27-May-2014	1,497 cc	65,000 km	Sedan	Available
New Edition Of The Toyota Vios With Sporty And Sleek Design. G Grade Specs To Enhance On The Looks. 120 Points Evaluation By Our In-house Mechanic. One Of The Best FC And Low Maintenance Vehicle In Th...									
Posted: 31-Jan-2019 Tags: 2014 Toyota Vios, 2014 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

0 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Vios, Toyota Vios Singapore, used Toyota Vios Singapore, used Toyota Vios, used vehicles Singapore or even buy used Toyota Vios Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/07/2019

Survey Details:

Date of loss	11-Feb-19
Date of appointment	14-Feb-19
Date of survey	20-Feb-19
Location of survey	BH AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SFP 8131Y
Make and Model	TOYOTA VIOS
Date of registration	26/1/2015
Excess	
Market Value	\$51,000
Parf Rebate	\$46,610
Nett Loss	\$4,390

Repair details:

Initial Estimate	\$ 3,552.03
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,332.53
Check items (estimate)	\$ -
Labour	\$ 1,219.50
Total	\$ 3,552.03
Lump Sum(if applicable)	\$ 2,850.00

Number of days for repair	9
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

9 RECOMMENDED REPAIR DAYS + 3PRS + 1 SUNDAY= 13 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost (W/GST)	\$ 3,049.50	\$ -
Loss of use	\$ -	\$ -
Loss of rental (13days x \$100)	\$ 1,300.00	\$ -
Loss of income	-	\$ -
LTA search fees	\$ 2.00	\$ -
Others	-	\$ -
Proposed Total	\$ 4,351.50	\$ -



<MANDATE IA> - S9M01DECC {ACCIDENT INVOLVING SMC 9049G & SFP 8131Y ON 11/02/2019 }

Type

🔔 Question

Message

LIABILITY: 100% INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$4351.50 (CLAIMING LOR). MANDATE IA HAD BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 14 February 2019 9:30 AM
To: assignments
Cc: Admin A
Subject: FW: CHECKING LIABILITY AND PRE REPAIR INSPECTION (OUR VEHICLE SFP8131Y & YOUR VEHICLE SMC9049G)
Attachments: SKM_C224e19021315400.pdf; SFP8131Y.PDF

12.04pm @ 14/2/19
VNI
Jacelyn

****SMARTCLAIM NEW CASE****

Kindly arrange.TQ

Best Regards,

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Sent: Wednesday, 13 February 2019 4:03 PM
To: NGUETTE Kadi <kadidiatou.nguette@axa.com.sg>
Cc: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>; BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <Jacelyn.loh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>
Subject: CHECKING LIABILITY AND PRE REPAIR INSPECTION (OUR VEHICLE SFP8131Y & YOUR VEHICLE SMC9049G)

Dear Sir/Madam,

I would like to check liability and arrange surveyor of the above mentioned accident vehicle.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day.

Best Regards,

Yun Shi

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

 Re:<MANDATE IA> - S9M01DECC {ACCIDENT INVOLVING SMC 9049G & SFP 8131Y ON 11/02/2019 }

Type

 Question

Message

Hi LKK, to start negotiation from repair cost \$2500 (50% discount on parts). To settle at max \$4200 all-in.

[Reply](#)

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

Cecilia

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SMC9049G

Our Reference: SFP8131Y

Date: 18/07/2019

M/s AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY POST ONLY

Attention: Claims Department

CLAIMANT: FAIR CHEM INDUSTRIES PTE LTD

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11/02/2019 ALONG PIONEER ROAD NORTH TOWARDS KJE. INVOLVING VEHICLE NO SFP8131Y & SMC9049G

We act for **FAIR CHEM INDUSTRIES PTE LTD** who was the owner of motor vehicle no. **SFP8131Y**.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 11/02/2019 involving our client's vehicle registration number SFP8131Y and vehicle registration number SMC9049G, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 3049.50
2	Loss of Rental (\$ 100.00 x 16days)	\$ 1712.00
3	LTA Search Fee	\$ 2.00
	Total :	\$ 4763.50

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of ;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,



Yun Shi

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

24 JUNE 2019

TOH TUCK CHEE
805C KEAT HONG CLOSE
#06-78
SINGAPORE 683805

Dear Sir/ Mdm

OUR REF : CC4/ASM19002742/Kgb3
YOUR REF : SMC 9049G
ACCIDENT INVOLVING SMC 9049C/ SFP 8131Y/ OTHERS ALONG/AT PIONEER
ROAD NORTH ON 11/02/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from BH AUTO SERVICES PTE LTD acting on behalf of the owner of SFP 8131Y against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorisation letter of vehicle driving by your driver
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: ceciliachong@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION

Name of owner of m/vehicle FAIR CHEM INDUSTRIES PTE LTD

Address -

NRIC No: 198602546 C

RE: ACCIDENT ON 11/02/19 ALONG Pioneer Road North Towards KJE
INVOLVING SFP 8131Y Vs SMC 9049G

In consideration of BH AUTO SERVICES PTE LTD ("the Workshop") repairing my/our vehicle no SFP 8131Y at my/our request. I/We the abovenamed owner of motor vehicle no. SFP 8131Y hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 12 (day) of 02 (month) 19 (year)

x Signed: [Signature] Joye Lau

Owner of m/vehicle SFP 8131Y

HP 9785 1153

Witnessed:



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SMC 9049G	(Insd veh)	Model: TOYOTA VIOS
	SFP 8131Y	(TP veh)	
Date of Accident/ Time:	11/02/2019 / 17:50		

Repair Estimate	S	6,565.63			
Final Repair Cost	S	2,875.00	(WGST)		
Loss of Use	S		days at \$ per day		
Rental (if any)	S	1,200.00	12 days at \$ 100.00 per day		
LTA / GIA Search Fee	S				
Others:	S				
	S				
Final Settlement Sum	S	3,870.00	GLOBAL SUM (ALL-IN)		
Payee Name: BH AUTO SERVICES PTE LTD					
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)					
A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)			
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: 28			
	BOLA Liability: 100 (%)	Assessed Liability (*): 100 (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks:					

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEFAOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and/or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: <u>Chong Kam Theng</u> Date: <u>09/02/19</u> 	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>CHAN TUN SHI</u> Date: <u>09/02/2019</u>
 Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date:	

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SFP8131Y

Date: 18/07/2019

M/s AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY POST ONLY

Vehicle No : SFP8131Y
Make/ Model : TOYOTA VIOS
Year of Manufacture : 2014
Chassis No. : MHFBT9F3406033820
Colour : BEIGE
D.O.A : 11/02/2019

QTY	ITEM/PARTICULARS	AMOUNT (\$\$)
-----	------------------	---------------

1. Repair Cost for Motor Vehicle No.SFP8131Y
Type of repair: LUMP SUM :\$\$ 2850.00

GST @ 7% : \$\$ 199.50

GRAND TOTAL:\$\$ 3049.50

Total : Singapore Dollars Three Thousand Forty-Nine Dollars And Fifty Cent Only.


Company's Stamp & Signature



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575636 TEL: (65) 6559 8944 FAX (65) 6269 2404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

VEHICLE RENTAL AGREEMENT

Owner: BH AUTO SERVICES PTE LTD ("the owner") Date: 12-02-2019

Hirer: FAIR CHRM INDUSTRIES PTE LTD Tel / HP: 9785 1153

NRIC / Co. Reg No: 198002546 C FAX: _____

Address: _____

Owner and Hirer have agreed to this Vehicle Rental Agreement for the motor vehicle described below and upon the Terms and Conditions contained on both sides of this document. Hirer acknowledges having read and understood all the Terms and Conditions and signifies acceptance upon signing.

Owner Vehicle No.	<u>SFP 8431 Y</u>		
Vehicle Reg. No.	<u>SGU 1984</u>	Rental:	_____
Odometer:	_____		
Date & Time Out:	<u>12-02-2019</u> <u>14:45 PM</u>	Hirer's Signature:	
Date & Time In:	<u>28-02-2019</u> <u>19:00 PM</u>	Hirer's Signature:	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 2000k comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first S\$ 2000k excess for collision or damage to first party (owner) and shall pay additional plus loss of earnings while damaged vehicle is under repair.

BH AUTO SERVICES PTE LTD

Authorised Signature



Hirer's Signature



明輝汽車服務私人有限公司
BH AUTO SERVICES PTE LTD

NO. 212, KRAVU ROAD, SINGAPORE 739465 TEL: (65) 6558 8844
FAX: (65) 6518 2144 CO. REG. NO.: 200917312K GST REG. NO.: 200917312K

Reference No.: CS04552

Invoice No.: _____

Customer Name: FAIR CHEM INDUSTRIES PTE LTD

Date/ Time: _____

Address: _____

Mobile Number: 9757153

Car Make & Model: SFP8131Y

Car Plate No: SFP8131Y

SN	Services Provided	Brand	Qty	Unit Price	Amount
1	Towing Service				S\$
2	Battery				S\$
3	Tyres				S\$
4	Others: Rental	S\$41984	16	\$100	S\$ 1600.00
Total Amount (inclusive of GST):					S\$ 1712.00

Special Remarks

Service Done by:

Acknowledged by:

Received by:

Sales Person Name & Signature

Customer Name & Signature

Finance Department



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-023159

Date of Request: 13/02/2019

Your Ref No:

Online Purchase

H Auto Services Pte Ltd
1k 1 Sin Ming Industrial Estate Sector C
01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Enquiry Date 13/02/2019
Enquiry By Kelvin Lim Khan Hong
TP Vehicle No. SMC9049G
Accident Date 12/02/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMC9049G	AXA Insurance Pte Ltd	27/07/2018-26/07/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-023159

Date of Request: 13/02/2019

Your Ref No:

Online Purchase

H Auto Services Pte Ltd
1k 1 Sin Ming Industrial Estate Sector C
01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Enquiry Date 13/02/2019
Enquiry By Kelvin Lim Khan Hong
P Vehicle No. SMC9049G
Accident Date 12/02/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002742/Kgb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 03-10-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 9049G	Veh. Inspected	SFP 8131Y
Policy No.	VPA/P2157838	Coverage (\$)	0.00
Claim No.	S9M01DHC	Excess (\$)	0.00
Assign From		Assign Date	14/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS E	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MHFBT9F3406033820	Colour	METALLIC GOLD
Odometer	49137	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	9 mm
L/H Front Tyre	185/60 R15	MICHELIN	9 mm
R/H Rear Tyre	185/60 R15	MICHELIN	9 mm
L/H Rear Tyre	185/60 R15	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2019	Inspection Date	20/02/2019
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFP 8131Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER GRILLE (WCP) (CONSISTENT)	CRACKED	90.00	90.00
1	FRONT BUMPER (WCP) (CONSISTENT)	BUCKLED	170.00	170.00
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRT BUMPER REINF (WCP) (CONSISTENT)	NOT NECESSARY	120.00	-
1	TOWING HOOK COVER (WCP) (CONSISTENT)	MISSING	22.00	22.00
1	L/G GRILLE TRIM (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	R/GRILLE TRIM (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT MANUFACT BADGE (WCP) (CONSISTENT)	MISSING	25.00	25.00
1	LEFT HEADLAMP ASSY (WCP) (CONSISTENT)	MTG CRACKED	180.00	180.00
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT)	NOT NECESSARY	180.00	-
1	LOCK CARRIER STRUT (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	55.00	-
1	FRONT PANEL CPL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	200.00	-
1	REAR BUMPER (WCP) (CONSISTENT)	BUCKLED	170.00	170.00
1	L/R INN BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	12.00	-
1	R/R INN BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	12.00	-
1	L/R OUT BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	38.00	-
1	R/R OUT BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	38.00	-
1	REAR BUMPER REINF (WCP) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR PANEL (WCP) (CONSISTENT)	BENT	210.00	210.00
1	BOOT SEAL (WCP) (CONSISTENT)	CUT	60.00	60.00
1	L/R HINGE (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	R/R HINGE (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	REAR LOCK STRIKER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	10.00	-
1	BOOTLID LOCK (WCP) (CONSISTENT)	DENTED	40.00	40.00
1	BOOT MOULDING (WCP) (CONSISTENT)	CRACKED	85.00	85.00
1	RR MANUFACTURE (WCP) (CONSISTENT)	NECESSARY	20.00	20.00

Report Ref No. CC4/ASM19002742/Kgb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	L/R LAMP ASSY (WCP) (CONSISTENT)	MTG CRACKED	110.00	110.00
1	R/R LAMP ASSY (WCP) (CONSISTENT)	NOT NECESSARY	110.00	-
1	L/R REFLECTOR (WCP) (CONSISTENT)	SERVICEABLE	65.00	-
1	R/R REFLECTOR (WCP) (CONSISTENT)	SERVICEABLE	65.00	-
1	L/R SIDE PANEL (WCP) (CONSISTENT)	BUCKLED	370.00	370.00
1	R/R SIDE PANEL (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	370.00	-
1	BOOTLID TRIM (WCP) (CONSISTENT)	SERVICEABLE	150.00	-
1	RR LUGG COMPART TRIM(WCP) (CONSISTENT)	NOT NECESSARY	95.00	-
1	CLIP (WCP) (CONSISTENT)	NECESSARY	12.00	12.00
1	SENSOR (WCP) (CONSISTENT)	DENTED	250.00	200.00
2	CLIP (WCP) (CONSISTENT)	NECESSARY	2.00	2.00
1	SHIELD LH (WCP) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SHIELD RH (WCP) (CONSISTENT)	NOT NECESSARY	22.00	-
1	LETTERING VIOS (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
	COST PLUS 15%		553.50	282.90
			4,243.50	2,168.90
	LABOUR			
	261.0 WU X 45.00 SGD/H.		1,174.50	801.00
	LABOUR COST 117.0 WU X 45.00 SGD/H.INCLUSIVE OF THE REPAI OF LOCK CARRIER STRUT,FRONT PANEL CPL,L/R HINGE,R/R HINGE,REAR LOCK STRIKER AND R/R SIDE PANEL.		526.50	418.50
	MATERIAL COST.		191.60	163.63
			1,892.60	1,383.13
GRAND TOTAL			6,136.10	3,552.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CC4/ASM19002742/Kgb3q2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59ND1DHC
Reference	CCA/ASMI9002742/Kgb242
Loss Date	11 February 2019
Report Date	14 Feb 2019 8:45:00 AM
Request Date	11 September 2019
Due Date	

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SFW8131Y
Make	TMVD TOYOTA
Model	VQ05-LS E (A)
Service Address	

Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Primary Contact/Insured	
TOH TUCK CHEE	
BLK 805C KEAT HONG CLOSE, #06-7B, 683805, Singapore	
91380128	

Claim Handler	
NG Stacey	
6568804351	
stacey.ng@axa.com.sg	

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (2).pdf	Invoice		LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019

IMAGE RENTAL RECEIPT.pdf	Forms / Claim Documents	SUB-TYPE Others	AMK AUTO CONSULTANTS PTE LTD (TP)	DATE 11 October 2019
 LKK Inspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
 PASSE COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2019
 TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2019
 MANDATE IA DO 25072019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2019
 TP GIA REPORT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2019
 SMC1582K GIA REPORT.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 February 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SMCY04RG INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 February 2019
 EMAIL FROM WORKSHOP FOR TP REG.mng	Letters and Correspondence	Others	NIKAM Santosh Pandurang	14 February 2019