

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 28 Feb 2019

**Preliminary Advice**

Vehicle No	: SLJ2808D	Accident Date	: 27/01/2019
Make	: LOTUS ELISE	Policy No.	: DMPCSN1901751900
Assignment Date	: 27/02/2019	Excess	: S\$4,000.00
Date of Inspection	: 14/02/2019	Est. Duration of Repair	: 12.00
Inspection At	: EUROSPOITS AUTO PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	66,862.16
Revised Amount	:S\$	58,118.00
Check Items (Estimated)	:S\$	2,510.00
Total	:S\$	60,628.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	31,014.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,986.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : According to repairer,due to the extensive damage on the chassis.  
If we have to replace the chassis, the total repair cost will be above \$90,000.