

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle: SLJ2808D / Lotus Elise

Policy: DMPCSN1901751900

Accident Date: 27/01/2019

Own Damage Claim

09-02-19**Repair Quotation****PARTS**

1	H120B0010J	Front Body ClamShell	\$	33,904.00 <i>new</i>
2	C117B0193F	Bracket, centre front clamshell	\$	222.00 ?
3	B100W6372F	Fastener Spirenut, M5	\$	45.00 <i>new</i>
4	C117B0163F	Bracket, Sides front clamshell (pair)	\$	228.00 ?
5	A116B0460K	Bracket Shim for front Clam Shell 0.5mm	\$	44.00 ?
6	A116B0461K	Bracket Shim for front Clam Shell 1.0mm	\$	44.00 ?
7	B120B0088F	Bracket, Front liner panel mounting (pair)	\$	192.00 ?
8	A082W6512F	Pop Rivet, fastener	\$	32.00 <i>new</i>
9	A122B0126F	Mounting, Front Towing strut	\$	420.00 <i>bt</i>
10	G117B0114F	Center Front Grille	\$	333.00 <i>mis</i>
11	G117B0117F	LH front grille	\$	316.00 ?
12	G117B0118F	RH front grille	\$	316.00 <i>de</i>
13	A117B6003F	Clips for center grille	\$	72.00 <i>new</i>
14	A117B0328F	Clips for ClamShell	\$	168.00 <i>new</i>
15	A117B6004F	Fasteners Griller Spigots	\$	72.00 <i>new</i>
16	A117W5268F	Screws for outer grilles	\$	36.00 <i>new</i>
17	C117B0235F	Clips for outer grilles	\$	72.00 <i>new</i>
18	B075U6054V	Sealers for grilles	\$	144.00 <i>new</i>
19	A117U0170F	Front LOGO - Lotus	\$	610.00 <i>new</i>
20	B120B0190J	Fronts Crash Structure Assembly	\$	8,490.00 <i>new</i>
21	B117B0237F	Front undeshield Panel	\$	930.00 <i>bt</i>
22	B100W6372F	Spirenuts for undershield	\$	54.00 <i>new</i>
23	A111B0531F	Alloy Plate LH	\$	84.00 ?
24	A111B0530F	Alloy Plate RH	\$	102.00 ?
25	A085W6259F	Pop Rivet for Plates	\$	72.00 ?
26	A075W4000Z	Washer for Plates	\$	48.00 ?
27	A120B0062F	Side impact foam LH	\$	300.00 ?
28	A120B0062F	Side impact foam RH	\$	342.00 ?
29	A117B0556F	Brackets for foams	\$	360.00 ?
30	A117W6734F	Pop Rivets for brackets	\$	96.00 ?
31	A117B0466F	Grilles for Crash structure	\$	60.00 ?
32	A082B6281F	BetaSeal for Crash structure	\$	600.00 <i>new</i>
		Subtotal for Parts	\$	48,808.00

Labor Charges

Dismantle, Re Fitting and Repair (8 Days) x \$960	\$ 7,680.00 6720
Respray for front body clamshell 1100	\$ 4,500.00 4000
Sealers for Body attachment	\$ 1,200.00 800
Aircon Gas Remove and Refill <i>plus to #</i>	\$ 300.00 ✓
<u>Subtotal for Labor</u>	\$ 13,680.00

GST \$ 4,374.16

Total **\$ 66,862.16**

- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.


Lamborghini Singapore

Workshop Contact:

Richard Harjanto

Service Advisor

97999593



09/02/19

Tanflm 97495749/674/8434

Ex \$4000

12 days.

Not Authorise

14/2/19 @ 1715

Resurvey before paint.

Resurvey duck items

sure@lkbauto.com

<8117

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: