

ASS. REC. BY:

REF: 01/FCI 19002745/Ksd3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Karen Tun

of

FCI

Date/Time:

11:30am @ 12/12/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 9813H

Insured:

SHA 7366H

at Workshop m/s

Ah Lim Motor

Tel:

68431244

of

No. 10 Amk Ind. Park 2A # 01-09

Policy No:

Claim No:

D19000964MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

08/02/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

2:57pm @ 12/12/19

Person Contacted:

Zila

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLZ 9813H -x

SHA 7366H -x

22/02/19

@ 11:19 a.m. revised PA to Karen via email.

3/5

83230.68 Confirmed by email

(82,931.28 red - 48%)

REF: FC1

S.S.K. N.V. N.V.

Date: 15/2/19

Estimated Date:

① (C) TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLZ 9813H

at Work/dep m/s: Ah Lim. Motor

at: No. 10 AMK Ind. Park 2A #01-09

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Date: 15/2/2019 1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

881k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B-1%

3 Val.: Yes. or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No

SLZ 9813H

V Regn

05 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Handp⁹ Veral

C.C.

1496

Colour

M. D. Blue

A/C

Insured / Std / NI / NA

Sp Reading

22292

T/Radio: Insured / Std / NI / NA

Eng No:

C/Nr

R41

1210667

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

min

R/Bal.

min

L/Bal.

min

L/Bal.

min

D.O.A.

8/2/19

D.O.I.

15/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

07/05/19

1)

Type: 4

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. t: (\$

3,230.68 P/P)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1) C + P: 2

2) Photo

3) Other

4) Total

TOTAL

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Adv. (\$

☐

Weekend (\$

145

50

50

17

262



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000964MFSH

Date: 22 February 2019

Our Ref: CS/FCI19002745/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 9813H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/02/2019 at the premises of M/s Ah Lim Motor Company and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,161.96</u> .
Revised Estimate Amount	: S\$ <u>1,450.00</u> .
"Check" Items Amount	: S\$ <u>57.04</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000964MFSH
Accident Date	08-02-2019	Claim Type. Third Party
Insured Vehicle	SHA7366Z	Third Party Vehicle. SLZ9813H
Survey Location	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT	
Contact Person.	ZILA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 February 2019 11:19 AM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19000964MFSH/1
Attachments: SLZ 9813H - Preli Advise .pdf

Dear Karen,

Enclosed preliminary revised of vehicle SLZ 9813H.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 14 February 2019 12:59 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000964MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 14 February 2019 11:32 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000964MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

3199X

Vehicle Details

Vehicle No.:

SLZ9813H

Vehicle to be Exported:

No

Intended Deregistration Date:

12 Feb 2019

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X CVT

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

L15B4410669

Chassis No.:

RU11210667

Maximum Power Output:

96.0 kW (128 bhp)

Open Market Value:

\$20,874.00

Original Registration Date:

24 May 2018

First Registration Date:

24 May 2018

Transfer Count:

0

Actual ARF Paid:

\$11,224.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 May 2028

PARF Rebate Amount:

\$8,418.00

Intended COE Rebate Details

COE Expiry Date:

23 May 2028

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$38,039.00

COE Rebate Amount:

\$34,334.00

Total Rebate Amount:

\$42,752.00

The information contained herein is correct as at 12 Feb 2019

OK

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5100918488
The Policyholder	: 3D SERVICES BLK 471C #11-83 FERNVALE STREET SINGAPORE 793471

Period of Insurance	: 24 May 2018 To 23 May 2019
Sum Insured	: Market Value of Insured Vehicle at Time of Loss
Premium (inclusive GST)	: S\$1,594.77

Interest Insured

Cover Type	: drive CLASSIC	
Primary Driver	: N/A	
Named Driver (1)	: N/A	
Named Driver (2)	: N/A	
Make/Model	: HONDA/VEZEL	Capacity : 1500cc
Registration Number	: To Be Advised	Registration Year : 2018
Chassis Number	: RU11210667	Off-peak Car : No
Repair at Owner's Preferred Workshop	: No	Insure with COE : Yes
Excess (Section 1)	: S\$2,000	NCD Entitlement : 10%
Excess (Section 2)	: S\$1,500	NCD Protection : No
Windscreen Excess	: S\$100	
Additional Excess	: N/A	
Unnamed Driver Excess	: Please refer to Terms and Conditions	
Hire Purchase Company	: HONG LEONG FINANCE LTD	

Optional Cover

Transport Allowance	: No
Excess Waiver	: No

Memo A : 1) The Policy does not cover any driver who is below 22 years old or with less than 2 years driving experience.
2) Section 1 clause 8 on Unnamed driver excess will not apply.

Endorsement Operative : N/A

Agency	: KHC HOLDINGS PTE LTD (00000613934)
Date of Issue	: 23 May 2018 09:15 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7715577E**

Name: **KOH MENG HUAT LEONARD (GU MINGFA)**

Birth Date: **11 Jun 1977**

Issue Date: **04 Nov 2008**

001671789E



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7715577E



Name: **KOH MENG HUAT LEONARD (GU MINGFA)**
辜明发

Race: **CHINESE**

Date of birth: **11-06-1977**

Sex: **M**

Country of birth: **SINGAPORE**

S7715577E



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

PASS DATE: **04 Nov 2008**

NP 428A

Licence No: **S7715577E**



4066690



NRIC No: **S7715577E**



Date of issue: **03-07-2007**

APT BLK 471C FERNVALE STREET #11-83
SINGAPORE 793471

NRIC No: **S7715577E** Date: **22/05/2015**

Particular of Insured / Driver & Details of the Accident

(Pls circle where applicable)

Location of Accident: Foch Road Date & Time of Accident: 08/02/19 1.50am

Purpose when vehicle was used at the time of accident: Going home
(eg. Going Home)

Details of Own Vehicle

Vehicle Registration Number: SLZ9813H Make / Model: Honda Vezel

Vehicle Category: _____

Claiming Own insurance: YES ☒ NO ☐ If No, Reporting only ☒ Third Party Claim ☐

Name of Preferred workshop: Ah Lim Motor Company Contact: 64831244

Insured / Policy Holder

Name of Registered Owner: 3D Services NRIC: 53233199X

Address: BLK 471C #11-83 Fernvale Street Singapore 793471

Mobile No: 94774771 Other Contact: Home No. / Office / Others: _____

Email: _____

Driver

Name of Driver: Koh Meng Huat Leonard NRIC/ Fin: S7715577E

Driving License Pass Date: 04/11/2008 DOB: 11/06/1977

Address: Apt BLK 471C Fernvale Street #11-83 Singapore 793471

Occupation: INDOOR ☒ OUTDOOR ☐ Mobile No: 94774771

Gender: ☒ MALE ☐ FEMALE Other Contact: Home No. / Office / Others: _____

Email: leonardkoh77@yahoo.com.sg

Driver an employee: YES / NO ☐ If no, what is relationship with the policyholder: _____
If Driver is a policyholder, please kindly ignore this question

Insurance Company

Fleet Policy: YES ☒ NO ☐ Policy Number: 5100918488 Type of Coverage: Comprehensive

General information of Accident

Type of Accident: HEAD-REAR / SIDE SWIPE / OTHERS: Major/Minor Road

Weather Conditions: ☒ CLEAR ☐ RAINING / OTHERS: _____

Road Surface: ☒ DRY ☐ WET

Any video captured by car camera?: YES / NO ☒ *Any witness?: YES / NO ☒

Any police report made: YES ☒ NO ☐ *Injured party: YES ☒ NO ☐ (*If Yes, pls provide name & tel)

For Injured Party details, it must be supported by police report

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : 3D SERVICES
 BLK 468 ANG MO KIO AVE 10 #02-982
 SINGAPORE 560468

Estimate No: MC1900121
Date: 12 Feb 2019
Policy No: 5100918488
Veh Reg No: SLZ9813H
Make/Model: HONDA VEZEL 1.5X
 CVT

ATTN:

Your Ref No: SLZ9813H
 Claim Type: Third Party
 Accident Date: 08/02/2019
 TP Veh Reg No: SHA7366Z

LKK
 1pm

Not withark
 Return B&Paint

4 days

Estimate Repair Cost to Vehicle No :SLZ9813H

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR DOOR RH	1 PC	930.60	✓
2 REAR DOOR RUBBER (AT DOOR) - FRONT	1 PC	17.20	✓
3 REAR DOOR RUBBER (AT DOOR) SIDE	1 PC	39.20	✓
4 REAR DOOR RUBBER (AT DOOR) REAR	1 PC	14.90	✓
5 REAR DOOR RUBBER (AT BODY)	1 PC	95.20	X
6 REAR DOOR INNER LOCK	1 PC	195.80	X
7 REAR DOOR INNER TRIMBOARD	1 PC	635.00	X
8 ROCKER PANEL RH	1 PC	660.00	X
9 SIDE SKIRT RH	1 PC	140.00	✓
10 SIDE SKIRT CLIPS	10 PC	45.00	✓
11 REAR FENDER RH	1 PC	931.80	X
12 REAR FENDER WHEEL ARCH RH	1 PC	153.00	✓
		3,857.70	
	Less 20%	771.54	3,086.16
Special Nett			
13 SPORT RIM RHR	1 PC	765.80	✓
14 TYRE RHR - CHECK PRICE	1 PC	0.00	X
		765.80	765.80
LABOUR			
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
16 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
17 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	80.00	601
18 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	801
19 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	301
20 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD ROCKER PANEL LH, REAR FENDER RH. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	601
21 TO SPRAY REAR DOOR RH, ROCKER PANEL RH, REAR FENDER RH.	1 PC	900.00	601
		2,310.00	2,310.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : 3D SERVICES
BLK 468 ANG MO KIO AVE 10 #02-982

SINGAPORE 560468

ATTN:

Estimate No: MC1900121
Date: 12 Feb 2019
Policy No: 5100918488
Veh Reg No: SLZ9813H
Make/Model: HONDA VEZEL 1.5X
CVT

Your Ref No: SLZ9813H
Claim Type: Third Party
Accident Date: 08/02/2019
TP Veh Reg No: SHA7366Z

Estimate Repair Cost to Vehicle No :SLZ9813H

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 6,161.96
		Add GST @ 7%	431.34
		Total Amount Payable	S\$ 6,593.30

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED NINETY THREE AND CENTS THIRTY ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002745/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7366Z	Veh. Inspected	SLZ 9813H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000964MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	RU11210667	Colour	METALLIC DARK BLUE	
Odometer	22292	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2019	Inspection Date	15/02/2019	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 9813H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR RH	BENT	930.60	930.60
1	REAR DOOR RUBBER (AT DOOR)-FRONT	SERVICEABLE	17.20	-
1	REAR DOOR RUBBER (AT DOOR)-SIDE	SERVICEABLE	39.20	-
1	REAR DOOR RUBBER (AT DOOR)-REAR	SERVICEABLE	14.90	-
1	REAR DOOR RUBBER (AT BODY)	SERVICEABLE	95.20	-
1	REAR DOOR INNER LOCK	TO REPAIR SEE LABOUR	195.80	-
1	REAR DOOR INNER TRIMBOARD	SERVICEABLE	635.00	-
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	660.00	-
1	SIDE SKIRT RH	MTG CRACKED	140.00	140.00
10	SIDE SKIRT CLIPS	NECESSARY	45.00	45.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	931.80	-
1	REAR FENDER WHEEL ARCH RH	BENT	153.00	153.00
	LESS 20% DISCOUNT		-771.54	-253.72
			3,086.16	1,014.88
<u>SPECIAL NETT ITEMS</u>				
1	SPORT RIM RHR (SN)	DENTED	765.80	765.80
1	TYRE RHR (NPA)(SN)	SERVICEABLE	-	-
			765.80	765.80
<u>LABOUR</u>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR FACILITATE REPAIR.		80.00	60.00
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		120.00	80.00

Report Ref No. CS/FCI19002745/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		90.00	30.00
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD ROCKER PANEL LH,REAR FENDER RH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR DOOR INNER LOCK,ROCKER PANEL RH AND REAR FENDER RH.		1,000.00	600.00
	TO SPRAY REAR DOOR RH,ROCKER PANEL RH,REAR FENDER RH.		900.00	600.00
			2,310.00	1,450.00
GRAND TOTAL			6,161.96	3,230.68
RECOMMENDED COST OF REPAIRS				3,230.68

Report Ref No. CS/FCI19002745/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.