

ASS. REC. BY:

REF: CS/FCI19002748/A/d3

n2

Special Instruction:

Surveyor:

Adnon

ASSIGNMENT (Office)

From (Person):

Biphen

of

FCI

Date/Time:

2:56pm @ 11/2/19

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 2710Y

Insured:

SHA 8533B

at Workshop m/s

Zero Gravity

Tel:

67477100

of

2 Kenti Bkt Ave 2 # 01-25

Policy No:

Claim No:

D19006470 MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/2/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:03am @ 11/2/19

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SGV 2710Y-NA/CT119002418/FA
	SHA 8533B-NA/CT119002418/KA
11/2-	Report pending estimate
	Lump Sum \$4100/- (Red: 4239.04 : 50%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: S6V2710Y Yr Regn: 2007, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lanesc.c. 1584Colour: GreenA/C: Insured / Std / Nil / NASp. Reading 250080T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JMYSNCS3A74008896Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/45 R17

R:

215/45 R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/02/19

Survey held at

Zero GravityDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / 1st Cap.COE Expiry: 10/06/27MV: 48KMV: 48000/-PV: 43.1KLTA: 43,090/-Nett: 4.9KNV: 4910/-

RECEIVED 03 JUN 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 316 Typist

3)

5)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Other's

TOTAL

160505046306

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000970MFSH
Accident Date	10-02-2019	Claim Type. Third Party
Insured Vehicle	SHA8533B	Third Party Vehicle. SGV2710Y
Survey Location	2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB	
Contact Person.	TIFFANY	
Contact No.	67412845/ 67477100	Fax No. 67412170
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZERO GRAVITY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 15 February 2019 5:05 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000970MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGV 2710Y on 14/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 February 2019 11:29 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000970MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOption of any
workshop

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [3 ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5e



2.38%p.a Lowest Interest @ Gv
Cars Financing \$1500
Downpayment Monthly From
\$468
Gv Credit Insurance StarAd



**CERTIFIED PRE-OWNED
MERCEDES-BENZ**

[View our cars](#)

Browse by Category

[Save Search](#)[Print](#)

* Back (1 2 3) Next *

Sort by Date Posted

20 results/page

50 vehicles

Search

Lancer

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Lancer Any Any > 10 year(s) old Any Any Any Available



☐ Mitsubishi Lancer 1.6M GLX
(COE till 05/2021)

\$17,000

\$7,410 /yr

10-Jul-2006

1,584 cc

-

Sedan

Available

Cheap And Modded Lancer. S90 Throttle Body, Open Pod Hurricane Filter, Drift Racing Exhaust. Mods Will Go With The Car. Whatsapp Or Call To Book An Appointment For Viewing! High Loans And Trade-ins Av...

Monster Motors Pte Ltd

PREMIUM AD



☐ Mitsubishi Lancer 1.6M GLX
(COE till 08/2021)

\$18,500

\$7,270 /yr

27-Sep-2006

1,584 cc

123,000 km

Sedan

Available

Cheap And Modded Lancer. A Pair Of Bride Low Max Seat, Open Pod Apexi Filter, Drift Racing Exhaust. Mods Will Go With The Car. Whatsapp To Book An Appointment For Viewing! No Joyrides Or Test Drive. C...

Car Empire Automobils Pte Ltd Mitsubishi Lancer, 1.6M GLX, 123,000 km, 1,584 cc, 27-Sep-2006, \$18,500, \$7,270 /yr, 123,000 km, 1,584 cc, 27-Sep-2006, 1,584 cc, 123,000 km, Sedan, Available

DIRECT OWNER



☐ Mitsubishi Lancer 1.6M GLX
(COE till 08/2021)

\$24,000

\$9,430 /yr

18-Oct-2006

1,584 cc

190,000 km

Sedan

Available

Very Low Petrol Consumption Easy Maintenance! Well Maintained By Previous Owner Tuned Before For Better Fuel Consumption. High Loan Available.

Car Empire Automobils Pte Ltd



☐ Mitsubishi Lancer 1.6M GLX
(COE till 12/2021)

\$18,500

\$6,490 /yr

21-Dec-2006

1,584 cc

-

Sedan

Available

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Mitsubishi Lancer 1.6A GLX
(COE till 03/2022)

\$41,288

\$5,110 /yr

12-Mar-2007

1,584 cc

105,888 km

Sedan

Available

Perfect Working Condition, No Modification Done, Serviced Regularly, Original Paintwork, Tyres Just Replaced In May 2016. Good For COE Renewal. SMS Only.

Posted By: [Name] Mitsubishi Lancer, 1.6A GLX, 105,888 km, 1,584 cc, 12-Mar-2007, \$41,288, \$5,110 /yr, 105,888 km, 1,584 cc, 12-Mar-2007, 1,584 cc, 105,888 km, Sedan, Available

DIRECT OWNER



☐ Mitsubishi Lancer 1.6A GLX
(COE till 03/2022)

\$18,000

\$5,810 /yr

22-Mar-2007

1,584 cc

171,000 km

Sedan

Available

Regularly Serviced, Accident Free. Schedule A Test Drive Today. Viewing Strictly By Appointment Only.

Caro

COMMISSION



☐ Mitsubishi Lancer 1.6A GLX
(COE till 05/2022)

\$20,888

\$6,430 /yr

15-May-2007


1,584 cc

-

Sedan

Available

Complete



[-> Back to OneMotoring](#)



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	465311
Vehicle Details	
Vehicle No.:	SGV2710Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	4G18J313
Chassis No.:	JMYSNCS3A7U008896
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$10,852.00
Original Registration Date:	11 Jun 2007
First Registration Date:	11 Jun 2007
Transfer Count:	2
Actual ARF Paid:	\$11,579.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jun 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,625.00
COE Rebate Amount:	\$43,090.00
Total Rebate Amount:	\$43,090.00

The information contained herein is correct as at 14 Feb 2019

OK

Sketch Plan #3





ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 5288887X

Attn: Adrian

QUOTATION

No : QT-000163

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Denise

Your Ref. : SHA8533B
 Vehicle No. : SGV2710Y
 Make & Model : MIT LANCER
 Chasis No. : JMYSNCS3A7U008896
 Engine No. : 4G18J313
 Accident Date : 10-02-2019
 Policy No. : DMPCSN3036631803
 Date : 16-02-2019
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BOOT <i>Dented</i>	1.0	PCS 576.00	✓ 576.00
2	REAR NUMBER PLATE GARNISH <i>cracked</i>	1.0	PCS 92.60	✓ 92.60
3	LAMP (NUMBER PLATE) <i>new</i>	2.0	PCS 58.00	X 116.00
4	REAR BOOT WEATHERSTRIP <i>new</i>	1.0	PCS 136.70	X 136.70
5	REAR BOOT INNER LOCK <i>Dented</i>	1.0	PCS 98.00	✓ 98.00
6	REAR BOOT LOCK STRIKER <i>new</i>	1.0	PCS 55.00	X 55.00
7	REAR BOOT CABLE	1.0	PCS 99.00	X 99.00
8	BUMPER BRACKET (L/H) <i>new</i>	1.0	PCS 45.00	✓ 45.00
9	BUMPER BRACKET (R/H) <i>new</i>	1.0	PCS 45.00	✓ 45.00
10	BUMPER BEAM <i>new</i>	1.0	PCS 174.00	X 174.00
11	REAR BUMPER <i>Deformed</i>	1.0	PCS 726.00	726.00
12	REAR BUMPER LIP <i>Deformed</i>	1.0	PCS 850.00	<i>650 (new)</i> X 850.00
13	BUMPER CLIP <i>new</i>	1.0	SET 40.00	✓ 40.00
14	REAR END PANEL <i>Dented</i>	1.0	PCS 398.00	✓ 398.00
15	REAR END PANEL GARNISH <i>Deformed</i>	1.0	PCS 141.00	✓ 141.00
16	TAIL LAMP BASE PANEL (R/H) <i>Repair</i>	1.0	PCS 97.00	X 97.00
17	LOGO <i>new</i>	1.0	PCS 36.00	✓ 36.00
18	LAMP (R/H/R) <i>cracked</i>	1.0	PCS 344.00	✓ 344.00
19	LAMP (L/H/R) <i>new</i>	1.0	PCS 344.00	X 344.00
20	CLIP (LAMP) <i>new</i>	4.0	PCS 12.00	<i>10</i> X 48.00
21	Discount 20 %			-892.26
22	SubTotal (L)			3,569.04
23	EXHAUST MUFFLER (LTA COMPLIANT) <i>Repair</i>	1.0	PCS 1,500.00	X 1,500.00
24	REAR END PANEL SEALANT <i>new</i>	1.0	BTL 50.00	✓ 50.00
25	REVERSE SENSOR <i>Damaged</i>	1.0	SET 280.00	<i>200</i> X 280.00
26	REVERSE CAMERA <i>new</i>	1.0	PCS 280.00	X 280.00

2551-60

2296.44.

S.N 650

250



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 52888887X

Attn: Adrian

QUOTATION

No : QT-000163

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Your Ref. : SHA8533B
 Vehicle No. : SGV2710Y
 Make & Model : MIT LANCER
 Chasis No. : JMYSNCS3A7U008896
 Engine No. : 4G18J313
 Accident Date : 10-02-2019
 Policy No. : DMPCSN3036631803
 Date : 16-02-2019
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	SubTotal (S)			2,110.00
28	PANEL BEAT & REPAIR REAR DAMAGE	1.0 X	0.00	800.00
29	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	0.00	800.00
30	TO PROVIDE UNDER TURFCODE	1.0 X	0.00	800.00
31	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X	0.00	800.00
32	TO REMOVE AND REPLACE DAMAGED EXHAUST SYSTEM	1.0 X	0.00	800.00
33	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X	0.00	300.00
34	TO REMOVE REVERSE SENSOR/CAMERA	1.0 X	1920	500.00
35	TO TRANSFER REAR BOOT FITTING	1.0 X		120.00
36	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X		50.00
37	SubTotal (Labour)			2,660.00

total 5116.44
 2/5: 4.1K
 06 Days
 8785.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval from insurance company
- Third party survey is on a "Without Prejudice" basis

SINGAPORE DOLLAR EIGHT THOUSAND THREE HUNDRED THIRTY NINE AND CENTS FOUR ONLY

E. & O.E

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

[Signature]

Customer's Signature/Co. Stamp

ZERO GRAVITY

Total S\$ 8,339.04
 Discount S\$ 0.00
 Net Total S\$ 8,339.04

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002748/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8533B	Veh. Inspected	SGV 2710Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000970MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JMYSNCS3A7U008896	Colour	GREEN	
Odometer	250080	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/02/2019	Inspection Date	14/02/2019	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 2710Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	DENTED	576.00	576.00
1	REAR NUMBER PLATE GARNISH	CRACKED	92.60	92.60
2	LAMP (NUMBER PLATE) @\$58.00	NOT NECESSARY	116.00	-
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	136.70	-
1	REAR BOOT INNER LOCK	DAMAGED	98.00	98.00
1	REAR BOOT LOCK STRIKER	NOT NECESSARY	55.00	-
1	REAR BOOT CABLE	NOT NECESSARY	99.00	-
1	BUMPER BRACKET (L/H)	NECESSARY	45.00	45.00
1	BUMPER BRACKET (R/H)	NECESSARY	45.00	45.00
1	BUMPER BEAM	NOT NECESSARY	174.00	-
1	REAR BUMPER	DEFORMED	726.00	726.00
1	SET BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR END PANEL	DENTED	398.00	398.00
1	REAR END PANEL GARNISH	DEFORMED	141.00	141.00
1	TAIL LAMP BASE PANEL (R/H)	TO REPAIR SEE LABOUR	97.00	-
1	LOGO	NECESSARY	36.00	36.00
1	LAMP (R/H/R)	CRACKED	344.00	344.00
1	LAMP (L/H/R)	NOT NECESSARY	344.00	-
4	CLIP (LAMP) @\$12.00	NECESSARY	48.00	10.00
	LESS 10% DISCOUNT		-361.13	-255.16
			3,250.17	2,296.44
1	REAR BUMPER LIP (SN)	DEFORMED	850.00	650.00
	LESS 10% DISCOUNT		-85.00	-
			765.00	650.00
SPECIAL NETT ITEMS				
1	EXHAUST MUFFLER (LTA COMPLIANT)(SN)	TO REPAIR SEE LABOUR	1,500.00	-
1	BTL REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00

Report Ref No. CS/FCI19002748/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE CAMERA (SN)	NOT NECESSARY	280.00	-
			2,110.00	250.00
	LABOUR			
	PANEL BEAT & REPAIR REAR DAMAGE.INCLUSIVE OF THE REPAIR OF TAIL LAMP BASE PANEL (R/H) AND EXHAUST MUFFLER (LTA COMPLIANT).		1,000.00	800.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		900.00	800.00
	TO PROVIDE UNDER TIRFCODE.		120.00	80.00
	TO REMOVE AND REFIT COMPONENTS/FACILITATE THE REPAIR.		150.00	80.00
	TO REMOVE AND REPLACE DAMAGED EXHAUST SYSTEM.		120.00	80.00
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		50.00	30.00
	TO REMOVE REVERSE SENSOR/CAMERA.		150.00	50.00
	TO TRANSFER REAR BOOT FITTING.	NOT NECESSARY	120.00	-
	TO CHECK WIRING SYSTEM,FOCUS LIGHTINGS.	NOT NECESSARY	50.00	-
			2,660.00	1,920.00
GRAND TOTAL			8,785.17	5,116.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/FCI19002748/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.