

REP CS/FCI 19002750/Kqd3/12

Special Instruction

SA/Vel/OT

(WS)

Kenneth
Sitharam

ASSIGNMENT (Office)

From (Person)

of

FCI

Date/Time

3:58pm @ 14/12/19

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MYTCs

To Inspect Vehicle No.

SJB 8572J

Insured

SHA 8012M

at Workshop m/s

Insurance's Auto

Tel.

90089959

of

BIK 5038, AMK Ave 3 # 01-405 Ind. park 2

Policy No.

Claim No.

D19001007MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement

Date/Time

10:20am 14/12/19

Person Contacted

Mr. Tan

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SJB 8572J - NA/INC 19001669/v3 DUA: 29/01/19
	SHA 8012M - NA/INC 19001669/v3 DUA: 29/1/19
15/01/19 @	11:45am revised to Sitharam by email
	11Ln 8850 email (Red \$7580.91, 75%)

REF: FCP

ASSIGNMENT

From: Date: 14/2/19

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To: Inspected Vehicle No: SJB 8572J

at: Workshop no: Insurance 3 Auto

of: Blk 5038, Amik Ave 3 # 01-405

Insured: Ind. park 2

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 820k

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: 03 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: 11/2 Person Contacted:

Vehicle: IN / OUT

Veh No: SJB 8572J Regn: 01 08

Type: ☒ Car / ☐ Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios^A C.C. 1497

Colour: M. Green A/C Insured / Std / Nil / NA

Sp Reading: 215835 T/Radio Insured / Std / Nil / NA

Eng/Mo:

C/N: MR053HY 930 5046241

Gen Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A. 24/1/19

Survey held at: 14/2/19

Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 FEB 2019

Date/Time: File Pass to?

1) 26/2/19

Date/Time: File Return to?



Preli. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Weekend \$

Report Format:

Lump Sum / L.E. 15

TP
850

Survey Fee:

Transportation

1) S + P 0

2) Photos

3) Other

4) Total

TOTAL

130

50

50

11

241



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001007MFSH

Date: 15 February 2019

Our Ref: CS/FCI19002750/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJB 8572J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/02/2019 at the premises of M/s INSURANCE'S AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,430.91 .
Revised Estimate Amount	: S\$ 1,072.99 .
"Check" Items Amount	: S\$ 334.50 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	12-02-2019	Our Ref No. D19001007MFSH
Accident Date	24-01-2019	Claim Type. Third Party
Insured Vehicle	SHA8012M	Third Party Vehicle. SJB8572J
Survey Location	BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO INDUSTRIAL PARK 2	
Contact Person.	MELODY	
Contact No.	90089959/ 90089959	Fax No. 63373700
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	INSURANCE'S AUTO	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 15 February 2019 11:45 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001007MFSH/1
Attachments: CSFCI19002750Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SJB 8572J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 14 February 2019 10:17 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001007MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 13 February 2019 3:58 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001007MFSH/1

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2568F
Vehicle Details	
Vehicle No.:	SJB8572J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX684874
Chassis No.:	MR053HY9305046241
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,498.00
Original Registration Date:	25 Jan 2008
First Registration Date:	25 Jan 2008
Transfer Count:	4
Actual ARF Paid:	\$13,748.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$15,922.00
Total Rebate Amount:	\$15,922.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Feb 2019.

OK

Not Withheld
61 Pgs 8850p
Presny After Point
3 days

Ting Siew Kim

LKK Auto Consultants hence notify
the Repairer of the following:

- To insure against spray painting
- To insure against corrosion recovery
- To insure against rust
- To insure against paint
- To insure against
- To insure against

is subject to the terms and conditions of the

Acknowledged by Repairer:
Signature:
Date:

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1	Front Grille Chrome Moulding	Per \$70.00		✓
1	Front Bumper	Per cm \$328.10		✓
1 set	Front Bumper Clips	Per \$40.00		✓
1	Front Reinforcement	R \$267.00		X
1	Front sponge	Per \$79.00		X
2	Headlamp Assy RH/LH	Per \$447.60	\$223.80	X
1	Front Support Panel	R \$480.30		X
1	Front Grille	Per \$254.35		✓
1	Front Grille Emblem	Per \$38.20		✓
2	Front Bumper side retainer RH/LH	Per \$70.00	\$35.00	X
			\$2,074.55	
		Less 25%	\$518.64	
			\$1,555.91	

To remove and replace damage parts including straightening repositioning replacement parts.

2001
\$750.00

Supply Paint Material and necessary items. To respray replaced and other affected panels

28a
\$700.00

Reconnect wiring at the damage section and check for proper functions. To focus headlamp height.

\$75.00 *x n n*

To carry out antirust treatment on affected panels.

n n \$80.00 *x*

To perform diagnostic checks on control units. Reset to factory specification.

n n \$180.00 *x*

Special Nett Item

Front Number Plate

B1 \$45.00 } *45 n*
\$45.00 }

Front Number Plate Holder

Grand Total :

\$3,430.91



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002750/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-02-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8012M	Veh. Inspected	SJB 8572J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001007MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053HY9305046241	Colour	METALLIC GREEN	
Odometer	215835	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2019	Inspection Date	14/02/2019	
Survey held at	INSURANCE'S AUTO BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 8572J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT GRILLE CHROME MOULDING	DENTED	70.00	70.00
1	FRONT BUMPER	BUCKLED / CRACKED	328.10	328.10
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT REINFORCEMENT	TO REPAIR SEE LABOUR	267.00	-
1	FRONT SPONGE	SERVICEABLE	79.00	-
2	HEADLAMP ASSY RH/LH @\$223.80	SERVICEABLE	447.60	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	480.30	-
1	FRONT GRILLE	DENTED / SCRATCHED	254.35	254.35
1	FRONT GRILLE EMBLEM	NECESSARY	38.20	38.20
2	FRONT BUMPER SIDE RETAINER RH/LH @\$35.00	SERVICEABLE	70.00	-
	LESS 25% DISCOUNT		-518.64	-182.66
			1,555.91	547.99
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN) }	BENT	45.00	45.00
1	FRONT NUMBER PLATE HOLDER (SN) }	BENT	45.00	-
			90.00	45.00
LABOUR				
	TO REMOVE AND REPLACE DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT AND FRONT SUPPORT PANEL.		750.00	200.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		700.00	280.00
	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.TO FOCUS HEADLAMP HEIGHT.	NOT NECESSARY	75.00	-
	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS.	NOT NECESSARY	80.00	-