

INS. CASE OWNER:

CC 3, CTI 1900 2751, 19ja3n2

LKK:

IDAC:

Survivor:

Amk

DOI:

ASSIGNMENT

13/1/19

Date / Time:

13/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBA 2105 C

Name of Insured:

Budget Cars plc

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SHB 4132X



INSRS:

WSP:

Tel:

Liability:

RMKS:

COBE 10000



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHB 4132X - COB/AXA 1300 4286 / M12F305, DOA: 21/1/19
GBA 2105 C, 4/CTI18016220 / T1262, DOA: 16/8/18

BOTH REVERSING.

21-6-19

2PM W/MR. TARK, TO
SEND LETTER BY
EMAIL.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

20-6-19 XY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

☒☐

After call ltr to OI:

☒☐

Authorisation To Act:

☒☐

Release Voucher:

☒☐

Final Repair Bill:

☒☐

Car Rental Invoice:

☒☐

Towing Invoice:

☒☐

LTA / GIA:

☒☐

Medical Bill:

☒☐

PIR:

☒☐

Mandate/Reject Instruction:

☒☐

LOD

☒☐

Payment Breakdown Form:

☒☐

Post-Repair Photos:

☐☐

Others:

☐☐

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

802.50

S\$

401.25

(GST)

Loss of Rental (LOR):

287.50

S\$

143.75

(2.5 days)

Loss of Use (LOU):

125

S\$

62.50

(2.5 days)

Loss of Income (LOI):

125

S\$

62.50

(2.5 days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

GIA/LTA Search

7.49

S\$

7.49

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

1,222.49

S\$

614.99

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

614.99

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19002751/K1ja3

Date: 15/02/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 4132X

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.02.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	2,169.06
Revised Estimate Amount	: S\$	750.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	750.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4132X

DATE 12/2/2019 14:46

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
				\$ 185.70
	Labour Charge			210
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 730.00
	ESTIMATE TOTAL			\$ 2,169.06
Ka Li (16/11/19) 13/2/19 1120 L 2 Rep. 4s After Repair plz				
EEK Auto Centre, Parts for the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CMM1A

Chang

Nett
Nett

200

200

X12

30

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4132X

DATE 12/2/2019 14:46

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover ✕			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Rubber Mat ✓			\$ 50.00 Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70 Nett
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 ^{2.0}
	Spray Painting Charge			\$ 250.00 ^{2.0}
	Wiring Charge			\$ 50.00 ✕
	Remove/Refix Reverse Sensor			\$ 80.00 ^{3.0}
	TOTAL LABOUR			\$ 730.00
	ESTIMATE TOTAL			\$ 2,169.06
<i>Ka Sri (K)</i> <i>13/2/19 1120 G</i> <i>2 Rm.</i> <i>4s</i> <i>After Repair plz</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CMM1A

Chong

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline - 65 6383 6280 Facsimile - 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 758158
383 Sin Ming Drive Singapore 575717 7 Bungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 501 Yishun Industrial Park A Singapore 758158

Date/Time: 12.02.2019 13:46 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305267689


CUSTOMER:	REGN NO.: SHB4132X	MILEAGE
MR/MS	MAKE: HYUNDAI	FUEL
CUSTOMER NO. 7010045	MODEL I-40	E.....1/2.....
ADDRESS 383 SIN MING DRIVE	YR OF MANU. 22.10.2015	DATE/TIME IN 12.02.2019 10:20
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU079460	TARGET DATE
TEL (R) 65508755 (O)		COMPLETION DATE/TIME:
DISCOUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 08.02.2019
NATURE: 3P 08.02.2019

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Vehicle No.: SHB4132X
CHIANG

Vehicle No.: SHB4132X

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Use returned to Service Advisor with collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305267689
Date : 14/02/19

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHB4132X

Fax :

08/02/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA GBH2105C
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: **Final Lumpsum Repair cost**
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature :
Name :
Date : 18/2/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19002751/K1ja3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-06-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 2105C	Veh. Inspected	SHB 4132X
Policy No.	DMCVSN1808841800	Coverage (\$)	0.00
Claim No.	SNM19D200659	Excess (\$)	0.00
Assign From		Assign Date	13/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU079460	Colour	BLUE
Odometer	490918	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	7 mm
L/H Front Tyre	205/60 R16	CAMPEON	7 mm
R/H Rear Tyre	205/60 R16	CAMPEON	7 mm
L/H Rear Tyre	205/60 R16	CAMPEON	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2019	Inspection Date	13/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4132X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	SERVICEABLE	160.60	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	SERVICEABLE	71.20	-
1	REAR BUMPER SPONGE	SERVICEABLE	103.50	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	228.00	-
	LESS 20% DISCOUNT		-313.34	-115.00
			1,253.36	460.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			185.70	50.00
<u>LABOUR</u>				
	PANEL BEATING.		350.00	200.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			730.00	430.00
GRAND TOTAL			2,169.06	940.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				750.00

Report Ref No. CC3/CTI19002751/K1ja3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.