

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : QUEK KIAH MENG
 BLK 246 SERANGOON AVE 3
 #07-216
 SINGAPORE 550246

Estimate No: MC1900122
 Date: 12 Feb 2019
 Policy No: P10011000R01
 Veh Reg No: SGJ6177Z
 Make/Model: HONDA ACCORD 2.0A

ATTN:
 Your Ref No: SGJ6177Z
 Claim Type: Third Party - AIG
 Accident Date: 06/02/2019
 TP Veh Reg No: SMF2160Y

Estimate Repair Cost to Vehicle No :SGJ6177Z

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT / BT	1 PC	752.80	
2 REAR BOOT HINGE X NN	2 PC	111.40	
3 REAR BOOT EMBLEM / MC.	1 PC	27.10	
4 REAR BOOT CHROME MOULDING TOP X NN	1 PC	159.80	
5 REAR BOOT CHROME MOULDING LOWER / Re.	1 PC	159.80	
6 REAR BOOT ACCORD LOGO / MC.	1 PC	28.70	
7 REAR BOOT IVTEC LOGO / MC.	1 PC	45.50	
8 REAR BOOT LAMP ?	2 PC	408.00	
9 REAR BOOT INNER LOCK / Im	1 PC	269.00	
10 REAR BOOT RUBBER (AT BODY) ?	1 PC	91.00	
11 REAR BOOT INSULATOR ?	1 PC	178.00	
12 REAR BOOT INSULATOR CLIPS / MC.	10 PC	23.00	
13 TAILAMP LH / CRA.	1 PC	283.50	
14 REAR BUMPER / Re.	1 PC	797.60	
15 REAR BUMPER SIDE RETAINERS LH-Re, RH X NN	2 PC	33.60	
16 REAR BUMPER CLIPS / MC.	15 PC	58.50	
17 REAR BUMPER CHROME MOULDING / MC.	2 PC	225.40	
18 REAR BUMPER REVERSE SENSOR - RM 2PCS.	4 PC	907.60	
19 REAR END PANEL ?	1 PC	422.80	
20 REAR END PANEL TOP GARNISH ?	1 PC	81.80	
21 SPARE TYRE PANEL X Repair	1 PC	140.40	
22 SPARE TYRE PANEL TOP GARNISH ?	1 PC	232.60	
		5,437.90	
	Less 20%	1,087.58	4,350.32

Special Nett

23 NUMBER PLATE / SR.



1 PC 35.00
 35.00 35.00

LABOUR

24 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	30
25 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	40
26 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	?
27 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	400.500

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : QUEK KIAH MENG
BLK 246 SERANGOON AVE 3
#07-216
SINGAPORE 550246

Estimate No: MC1900122
Date: 12 Feb 2019
Policy No: P10011000R01
Veh Reg No: SGJ6177Z
Make/Model: HONDA ACCORD 2.0A

ATTN:
Your Ref No: SGJ6177Z
Claim Type: Third Party
Accident Date: 06/02/2019
TP Veh Reg No: SMF2160Y

Estimate Repair Cost to Vehicle No :SGJ6177Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
28 TO SPRAY REAR BOOT,REAR BUMPER,END PANEL, SPARE TYRE PANEL,REAR FENDER LH.	1 PC	1,000.00	650.
		2,200.00	2,200.00
Total			S\$ 6,585.32
Add GST @ 7%			460.97
Total Amount Payable			S\$ 7,046.29

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FORTY SIX AND CENTS TWENTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

5 Days.
lumpsum Repair.
After repair photos.
Gao Q: up - 82880282
14/2/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: