

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	SLF1033A		
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover	Vehicle Scheme:	Normal
Vehicle Attachment 1:	With Sun Roof		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	NISSAN	Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Chassis No.:	JN1JANT32Z0002324	Engine No.:	MR20887832B
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	6
Engine Capacity:	1997 cc	Power Rating:	-
Maximum Power Output:	106.0 kW (142 bhp)		
Unladen Weight:	1626 kg	Maximum Laden Weight:	2190 kg
Primary Colour:	Green	Secondary Colour:	-
First Registration Date:	12 Aug 2016	Original Registration Date:	12 Aug 2016
Manufacturing Year:	2016	Open Market Value:	\$22,572.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$11,800.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$2,572.00 (140%)
Actual ARF Paid:	\$23,601.00		

Owner Particulars

Owner Name:	ERIC TEO TRANSPORT
Owner ID Type:	Business
Owner ID:	53342903W
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	673A
Registered Street Name:	CHOA CHU KANG CRESCENT
Registered Unit No.:	# 16 - 411
Registered Building Name:	-
Registered Postal Code:	681673
COE No. / Expiry Date:	2016090103000131H / 11 Aug 2026
COE Bid Category:	B - Car (above 1600cc or 97kW (130bhp))
QP Paid:	\$57,903.00

Transaction Details

Business Transaction Ref. No.:	20160812144818197126
--------------------------------	----------------------

- Pre repair inspection request - SLF1033A VS SJW4546B (OI) DOA 01/02/2019

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinnul
Sent: 13/2/2019 11:58:59 AM
Attachments: SKM_284e18021310330.pdf

Hi,

Please refer to the enclosed request from Alan's United Auto pte Ltd.

Claim no : 7995889592SG003
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations - Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]
Sent: Wednesday, February 13, 2019 11:01 AM

To: Azlan, Syazairdina

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW4546B AND SLF1033A ON 01/02/2019

Dear Syazairdina

Thank you for sending us SJE, we have decided to let LKK Auto Consultants Pte Ltd. Mr. Kenneht Kong to conduct the pre survey.

Regards

kenny

Alan's United Auto pte Ltd

64538686

From: Azlan, Syazairdina
Sent: Wed, 13 Feb 2019 02:33:03 +0000
To: kennychan@alanutd.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinnul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW4546B AND SLF1033A ON 01/02/2019
Without Prejudice

Your Reference : SLF1033A
Our Reference : 7995889592SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd

12:34pm @ 13/2/19
person @ kenny
vehicle in
SUR @ Kenneth

Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: AIG SGP, Claims-Survey

Sent: Wednesday, February 13, 2019 10:24 AM

To: Azlan, Syazairdina

Subject: FW: ATTACHED SLF1033A REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRE SURVEY

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]

Sent: Wednesday, February 13, 2019 10:14 AM

To: AIG SGP, Claims-Survey

Subject: ATTACHED SLF1033A REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRE SURVEY

Dear Motor Claims Dept.

Attached our client vehicle SLF1033A repair estimate , GIA report to request joint expert surveyor list for us to choose surveyor to conduct pre survey , claiming your insured vehicle S/W4546B accident on 01-02-2019 thank you .

Regards

Kenny

Alan's United Auto pte Ltd

64538686

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ERIC TEO TRANSPORT

c/o Blk 7 Sin Ming Industrial Estate

#01-76

Singapore 575642

Date: 23-4-2019

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIMS DEPT.

78 SITION WAY

#07-16 AIG BUILDING

SINGAPORE 079120

LKK

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SLF 1033A AND SJW 4546 B
 ALONG SEMBAWANG RD / LOR. CHEN CHUAN ON 01-02-2019

I / We, the owner of Vehicle No. SLF 1033A which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | | |
|---|---|------------------------------|
| 1. Costs of repair | - | \$34,240.00 |
| 2. Loss of Use /Rental fees <u>45 days</u> | - | \$ 8100.00 |
| 3. Police / GHA report / LTA fees | - | \$ 7.65 |
| 4. Surveyor report fees | - | |
| 5. Others | - | <u>INJURY SUMM BY DRIVER</u> |
| Total: | | <u>\$42347.65</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,



ERIC TEO TRANSPORT
 REG. NO. 53342903W

Hsiao Tong (LKKAUTO)

From: alan khong chin wah <alanauto@gmail.com>
Sent: Thursday, 2 May 2019 10:23 AM
To: Hsiao Tong (LKKAUTO)
Subject: ATTACHED SLF1033A (OUR) POLICE PIR FOR YOUR REF. CLAIMING SJW4546B
Attachments: SKM_284e19050210280.pdf

Hi Hsiao Tong

Enclosed our client vehicle SLF1033A driver received letter from traffic police PIR for your reference .

Regards
Kenny
Alan's United Auto pte Ltd
64538686

Hsiao Tong (LKKAUTO)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Monday, 6 May 2019 10:51 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: <SEEK MANDATE> AIG Ref: 7995889592SG *LKK Ref: CC4/AIG19002759/Kpb3 [ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019]

Dear Hsiao Tong,

Mandate given as below.

COR	\$28,890.00
Rental	\$2,940.00 (21 days x \$140)
LTA fee	\$7.45
Total	\$31,837.45

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 4 May 2019 12:50 PM
To: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Subject: [EXTERNAL] <SEEK MANDATE> AIG Ref: 7995889592SG *LKK Ref: CC4/AIG19002759/Kpb3 [ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019]

This message is from an external sender; be cautious with links and attachments.

AIG Ref: **7995889592SG**
LKK Ref: CC4/AIG19002759/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019

We refer to the above matter.

The accident occurred when our insured driver was making a right turn and collided with third party who was driving straight on the opposite direction. Liability is not in our driver's favour. In addition, third party had submitted a copy of police investigation result to show that OID was being charged for inconsiderate driving.

According to surveyor, the nett value/ Economical Repair Value of third party vehicle is \$27,000.00(estimated). Detail as follows: -

Market Value	: \$ 88,000.00 (est)
LTA Rebate	: \$ 61,049.00 (est)
Nett Value/ Economical Repair value	: \$ 26,951.00 (est)

We have informed third party on the nett value/ economical repair value on the vehicle. However third party insisted to claim for repair cost at \$32,000.00(as per estimate marking of our surveyor).

The summary of claim is as follows: -

	Claimed Amount	Revised Amount (Based on repair cost)	Revised Amount (Based on repair cost)
1. Cost of Repair (w/GST)	\$ 52,232.14(Repairer's Estimate)	\$ 34,240.00	\$ 28,800.00
2. Loss of Rental (45days x \$180.00)	\$ 8,100.00	\$ 3,360.00(21days x \$160.00)	\$ 3,360.00
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45	\$ 7.45
Total	\$ 60,339.59	\$ 37,607.45	\$ 32,167.45

**16days recommendation for repair + 3Sunday + 2PRS = 21days

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate/instruction in Merimen.

Please call me if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 4 May 2019 12:50 PM
To: Loh, Chee-Heng
Subject: <SEEK MANDATE> AIG Ref: 7995889592SG *LKK Ref: CC4/AIG19002759/Kpb3 [ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019]

AIG Ref: **7995889592SG**
LKK Ref: CC4/AIG19002759/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019

We refer to the above matter.

The accident occurred when our insured driver was making a right turn and collided with third party who was driving straight on the opposite direction. Liability is not in our driver's favour. In addition, third party had submitted a copy of police investigation result to show that OID was being charged for inconsiderate driving.

According to surveyor, the nett value/ Economical Repair Value of third party vehicle is \$27,000.00(estimated). Detail as follows: -

Market Value	: \$ 88,000.00 (est)
LTA Rebate	: \$ 61,049.00 (est)
Nett Value/ Economical Repair value	: \$ 26,951.00 (est)

We have informed third party on the nett value/ economical repair value on the vehicle. However third party insisted to claim for repair cost at \$32,000.00(as per estimate marking of our surveyor).

The summary of claim is as follows: -

	Claimed Amount	Revised Amount (Based on repair cost)	Revised Amount (Based on Nett Value)
1. Cost of Repair (w/GST)	\$ 52,232.14(Repairer's Estimate)	\$ 34,240.00	\$ 28,890.00
2. Loss of Rental (45days x \$180.00)	\$ 8,100.00	\$ 3,360.00(21days x \$160.00)	\$ 3,360.00 (21days x \$160.0)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45	\$ 7.45
Total	\$ 60,339.59	\$ 37,607.45	\$ 32,257.45

****16days recommendation for repair + 3Sunday + 2PRS = 21days**

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate/instruction in Merimen.

Please call me if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 9 May 2019 8:11 AM
To: alan khong chin wah
Subject: RE: ATTACHED SLF1033A CLAIM DOCUMENT FOR SUBMISSION OF MANIDATE APPROVAL //LKK REF: CC4/AIG19002759/Kpb3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 28,890.00
2. Loss of Rental (21 days x \$140.00)	\$ 2,940.00
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 31,837.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alan khong chin wah <alanauto@gmail.com>
Sent: Tuesday, 23 April 2019 4:01 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: ATTACHED SLF1033A CLAIM DOCUMENT FOR SUBMISSION OF MANIDATE APPROVAL

Hi Hsiao Tong

Attached SLF1033A claims document for your submission of the mandate approval , thank you.

Regards
Kenny

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2019 Edit Reg		13 Feb 2019 00:00 Edit Adj Rpt	S\$27,000.00 Edit Estimates	S\$27,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	YEO LIAN SIM , ID: S0160140G		
Main Claimant:	ERIC TEO TRANSPORT , Co. Reg. No.: 53342903W		
Vehicle Reg. No.:	SLF1033A	Date of Loss:	01/02/2019 08:00 - :59 [29 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7995889592SG	Policy/Cover Note No.:	2100200457 (Comprehensive) Coverage: 26/03/2018 - 25/03/2019
Vehicle Reg. No. (Insured):	SJW4546B	Policy No. (Claimant):	18-MH000914-R02
		Excess:	
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/02/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (06/05/2019): Alert - Adj Mandate Approved (S\$31837.45) - SLF1033A - Claim Handler: Loh, Chee-...


































ALL ASSOCIATED TASKS
















































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)























Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLF1033A (7995889592SG)**
[SJW4546B]
TP
ERIC TEO TRANSPORT
Feb 1 2019 8:00AM
[YEO LIAN SIM]
Alan's United Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
2	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
3	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
4	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
5	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
6	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
7	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
8	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
9	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
10	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
11	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
12	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
13	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
14	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
15	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
16	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
17	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
18	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
19	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
20	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
21	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
22	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
23	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
24	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
25	12/04/19 11:59	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	
26	12/04/19 11:59	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	
27	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
28	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
29	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
30	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
31	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	
32	12/04/19 11:59	General View	 Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/04/19 11:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/04/19 12:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/04/19 12:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/19 15:16	EMAIL FROM AIG DD 1302201	 Load PDF	
2	14/02/19 15:16	TP EST & GIA REPORT	 Load PDF	
3	14/02/19 16:14	TP ESTIMATE- MARKED	 Load PDF	
4	15/04/19 16:32	LETTER TO OI	 Load PDF	
5	04/05/19 12:08	PIR FROM TP	 Load PDF	
6	04/05/19 12:09	RENTAL RECEIPT & AGREEMENT.	 Load PDF	
7	04/05/19 12:10	Authorisation to Act	 Load PDF	
8	04/05/19 12:52	Email to AIG_mandate dd 040519	 Load PDF	
9	19/08/19 15:55	RELEASE VOUCHER	 Load PDF	
10	19/08/19 15:55	WORKSHOP INVOICE	 Load PDF	
11	19/08/19 15:55	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/02/19 14:50	OI GIA REPORT	 Load PDF	
2	22/02/19 08:10	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJW4546B (Insd veh)	Model:	NISSAN X-TRAIL 2.0 CVT (A)
	SLF1033A (TP veh)		
Date of Accident:	01/02/2019		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				52,232.14
Final Repair Cost	:	\$				28,890.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				21 days
LTA / GIA Search Fee	:	\$				7.45
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				31,837.45

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)					
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: ____					
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Alan's United Auto Pte. Ltd.	: \$	31,837.45
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

19 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002759/KPB3S2

Date: 19/08/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100200457
Claimant Vehicle No :	SLF1033A	Insured Vehicle No :	SJW4546B
Date of Loss:	01/02/2019	Nature of Claim:	TP
		Claim No:	7995889592SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF1033A	Engine No:	MR20887832B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0002324
Reg. Date:	12/08/2016 (Man. Year: 2016)	Odometer:	216598 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,680.08	36,662.46	7,017.62	16.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,135.00	3,850.00	1,285.00	25.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,815.08	40,512.46	8,302.62	17.01
Approved Total (Overridden) (S\$)		27,000.00		
(S\$)	48,815.08	27,000.00	21,815.08	44.69
+ GST 7.00/7.00% (S\$)	3,417.06	1,890.00	1,527.06	44.69
Nett Amount (S\$)	52,232.14	28,890.00	23,342.14	44.69
+ Car Rental (21.0 x S\$140.00/day) (S\$)		2,940.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		31,837.45		

INSPECTION

Date of Assignment:	13/02/2019	
Date Inspected:	13/02/2019	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	16.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT W/S GLASS	Cracked	1,281.00 FN	*1,281.00 FN
2	1		*FRONT W/S GLASS MOULDING	Necessary	134.60 FN	*134.60 FN
3	1		*O/S ROOF AIR BAG	Burst	1,621.40 FN	*1,621.40 FN
4	1		*ROOF LINING	Deformed	860.20 FN	*860.20 FN
5	1		*FRONT INSTRUMENT PANEL	Torn	1,566.80 FN	*1,566.80 FN
6	1		*INSTRUMENT PANEL CENTRE COVER	Serviceable	156.90 FN	*- FN
7	1		*PASSENGER AIR BAG	Burst	2,390.20 FN	*2,390.20 FN
8	1		*STEERING AIR BAG	Burst	2,026.80 FN	*2,026.80 FN
9	1		*DRIVER SEAT SIDE AIR BAG	Burst	1,154.30 FN	*1,154.30 FN
10	1		*DRIVER SEAT COVER	Torn	2,504.80 FN	*2,504.80 FN
11	1		*DRIVER SEAT REAR BOARD	Serviceable	52.50 FN	*- FN
12	2		*FRONT W/S GLASS PILLAR TRIM	Serviceable	249.40 FN	*- FN
13	1		*BONNET	Bent	901.90 FN	*901.90 FN
14	1		*BONNET CABLE	Distorted	40.90 FN	*40.90 FN
15	1		*BONNET LOCK	Distorted	93.20 FN	*93.20 FN
16	2		*BONNET HINGE	Distorted	83.60 FN	*83.60 FN
17	1		*BONNET PULL HANDLE	Distorted	59.10 FN	*59.10 FN
18	1		*O/S BONNET STOPPER	Missing	12.00 FN	*12.00 FN
19	2		*BONNET RUBBER (SHORT)	Serviceable	60.00 FN	*- FN
20	1		*BONNET RUBBER (LONG)	O/s Cut	70.00 FN	*35.00 FN
21	1		*BONNET INSULATOR	Serviceable	154.70 FN	*- FN
22	10		*BONNET INSULATOR CLIP	Not Necessary	50.00 FN	*- FN
23	2		*FRONT FENDER	Buckled	1,166.80 FN	*1,166.80 FN
24	1		*FRONT FENDER ARCH GARNISH	O/s Buckled	340.00 FN	*170.00 FN
25	1		*FRONT FENDER INNER SHIELD	O/s Torn	163.20 FN	*81.60 FN
26	1		*FENDER INNER SHIELD LOW GARNISH	O/s Cracked	131.20 FN	*65.60 FN
27	1		*FRONT O/S FENDER INNER PANEL	Repair	175.20 FN	*- FN
28	2		*FRONT AIR INTAKE DUCT CLIP	Missing	9.00 FN	*9.00 FN
29	2		*HEADLAMP	Broken	4,704.00 FN	*4,704.00 FN
30	2		*HEADLAMP TOP PANEL	Bent	90.40 FN	*90.40 FN
31	1		*FRONT SUPPORT TOP PANEL	Bent	233.60 FN	*233.60 FN
32	1		*FRONT SUPPORT PANEL LOWER MEMBER	Bent	353.30 FN	*353.30 FN
33	1		*AUTO OIL COOLER	Punctured	360.00 FN	*360.00 FN
34	1		*RADIATOR GRILLE	Cracked	390.30 FN	*390.30 FN
35	4		*RADIATOR GRILLE CLIP	Necessary	22.00 FN	*22.00 FN
36	1		*RADIATOR GRILLE LOGO	Necessary	69.70 FN	*69.70 FN
37	1		*ENGINE UNDER COVER	Cracked	584.40 FN	*584.40 FN
38	1		*FRONT BUMPER FASCIA	Torn	534.70 FN	*534.70 FN
39	1		*FRONT BUMPER LOWER CHROME	Cracked	153.10 FN	*153.10 FN
40	1		*FRONT BUMPER LOWER GRILLE	Distorted	199.50 FN	*199.50 FN
41	1		*FRONT BUMPER REINFORCEMENT	Bent	453.10 FN	*453.10 FN
42	1		*REINFORCEMENT CENTRE BRACKET	Bent	86.60 FN	*86.60 FN
43	1		*FRONT BUMPER SPONGE	Torn	291.60 FN	*291.60 FN
44	2		*FRONT BUMPER SIDE RETAINER	Distorted	45.80 FN	*45.80 FN
45	1		*FRONT BUMPER FOG LAMP COVER	O/s Missing	161.80 FN	*80.90 FN
46	2		*FRONT STABILIZER BAR LINK	Distorted	64.60 FN	*64.60 FN
47	2		*FRONT LOWER ARM	Bent / Distorted	449.00 FN	*449.00 FN
48	1		*AIR BAG CONTROL UNIT	Necessary	1,445.00 FS	*1,445.00 FS
49	1		*STEERING AIR BAG COIL SPRING	Necessary	206.00 FS	*206.00 FS
50	2		*FRONT SAFETY BELT	Jammed	1,388.40 FS	*1,388.40 FS
51	2		*FRONT AIR BAG SENSOR	Necessary	1,206.60 FS	*1,206.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT W/S GLASS WASHER TANK	Cracked	248.40 FS	*248.40 FS
53	1		*W/S GLASS WASHER TANK NECK	Dented	35.00 FS	*35.00 FS
54	1		*FRONT AIR INTAKE DUCT	Cracked	116.40 FS	*116.40 FS
55	1		*FRONT ENGINE MANIFOLD	Serviceable	864.70 FS	*- FS
56	1		*HEADLAMP LOWER BRACKET	O/s Bent	55.00 FS	*27.50 FS
57	1		*SUPPORT LOWER MEMBER COVER	Cracked	94.50 FS	*94.50 FS
58	1		*RADIATOR	Bent	687.40 FS	*687.40 FS
59	1		*RADIATOR FAN COWLING	Cracked	267.50 FS	*267.50 FS
60	1		*RADIATOR FAN BLADE	Distorted	98.10 FS	*98.10 FS
61	1		*RADIATOR FAN MOTOR	Jammed	377.10 FS	*377.10 FS
62	1		*RADIATOR TOP HOSE	Serviceable	47.30 FS	*- FS
63	1		*RADIATOR LOWER HOSE	Cut	53.10 FS	*53.10 FS
64	1		*RADIATOR TOP COVER	Cracked	81.00 FS	*81.00 FS
65	1		*RADIATOR SPARE TANK	Dented	123.50 FS	*123.50 FS
66	1		*AIR CON CONDENSER	Bent	743.20 FS	*743.20 FS
67	1		*AIR CON CONDENSER FAN BLADE	Distorted	98.10 FS	*98.10 FS
68	1		*AIR CON CONDENSER FAN MOTOR	Jammed	377.10 FS	*377.10 FS
69	2		*AIR CON CONDENSER SIDE GUIDE	Cracked	81.00 FS	*81.00 FS
70	1		*AIR CON DISCHARGE HOSE	Punctured	130.00 FS	*130.00 FS
71	1		*AIR CON LIQUID PIPE	Serviceable	95.20 FS	*- FS
72	1		*AIR CON SUCTION HOSE	Serviceable	189.20 FS	*- FS
73	1		*HORN	O/s Dented	191.00 FS	*95.50 FS
74	1		*AIR CON COMPRESSOR	Dented / Jammed	953.20 FS	*953.20 FS
75	1		*STATER MOTOR	Serviceable	1,156.80 FS	*- FS
76	1		*ALTERNATOR	Cracked	1,889.80 FS	*1,889.80 FS
77	1		*FRONT BUMPER FOGLAMP	O/s Missing	643.20 FS	*321.60 FS
78	2		*FRONT SHOCK ABSORBER	Bent	730.00 FS	*730.00 FS
79	2		*FRONT KNUCKLE ARM	Bent	963.60 FS	*963.60 FS
80	2		*FRONT KNUCKLE BEARING HUP	Necessary	545.00 FS	*545.00 FS
81	1		*FRONT STABILIZA BAR	Serviceable	406.30 FS	*- FS
82	1		*FRONT ENGINE CROSS MEMBER	Serviceable	537.50 FS	*- FS
83	1		*FRONT N/S DRIVE SHAFT	Repair	966.20 FS	*- FS
84	1		*FRONT O/S DRIVER SHAFT	Repair	966.20 FS	*- FS
85	1		*FRONT NO. PLATE WITH BOX	Missing	50.00 FS	*45.00 FS
86	1		*FRONT W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
87	1		*FRONT W/S GLASS SOLAR FILM	Necessary	300.00 FS	*200.00 FS
88	1		*FRONT W/S GLASS SOLAR FILM (TOP)	Necessary	35.00 FS	*35.00 FS
89	1		*ERP IU BRACKET	Necessary	26.00 FS	*26.00 FS
90	1		*RADIATOR COOLANT	Necessary	30.00 FS	*30.00 FS
91	2		*AUTO GEAR OIL (50%)	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	46,355.80	39,205.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	2,675.72	2,542.54
Total Parts (\$\$)	43,680.08	36,662.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOWING.	New	100.00	100.00
2	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM, RESET & PROGRAMME.	New	120.00	60.00
3	TO REMOVE & RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	150.00	120.00
4	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.	New	250.00	150.00
5	TO REMOVE AIR CON CONDENSER, PIPES AND DRIER, VACUUM AND TO RECHARGE GAS.	New	120.00	100.00
6	TO APPLY UNDERSEALING.	New	80.00	80.00
7	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING.	New	200.00	200.00
8	TO REMOVE AND LEFT UP ENGINE ASSY.	New	400.00	0.00
9	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE.	New	250.00	200.00
10	TO CHECK AND ADJUST WHEEL ALIGNMENT.	New	65.00	60.00
11	TO PUTTY AND SPRAY REPLACED PARTS.	New	1,400.00	1,200.00
12	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.	New	1,800.00	1,400.00
13	TO REMOVE & RENEW AIR BAG, SAFETY BELT, ECU, SENSOR, PROGRAMME & RESET AIR BAG SYSTEM.	New	200.00	180.00
Gross Labour Cost (S\$)			5,135.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >