Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 4 May 2019 12:50 PM

To: Loh, Chee-Heng

Subject: <SEEK MANDATE> AIG Ref: 7995889592SG *LKK Ref: CC4/AIG19002759/Kpb3 [ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP)

ON 01/02/2019]

AIG Ref: 7995889592SG

LKK Ref: CC4/AIG19002759/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJW 4546B(OI) AND SLF 1033A(TP) ON 01/02/2019

We refer to the above matter.

The accident occurred when our insured driver was making a right turn and collided with third party who was driving straight on the opposite direction. Liability is not in our driver's favour. In addition, third party had submitted a copy of police investigation result to show that OID was being charged for inconsiderate driving.

According to surveyor, the nett value/ Economical Repair Value of third party vehicle is \$27,000.00(estimated). Detail as follows: -

Market Value	: \$ 88,000.00 (est)
LTA Rebate	: <u>\$ 61,049.00 (est)</u>
Nett Value/ Economical Repair value	: <u>\$ 26,951.00 (est)</u>

We have informed third party on the nett value/ economical repair value on the vehicle. However third party insisted to claim for repair cost at \$32,000.00(as per estimate marking of our surveyor).

The summary of claim is as follows: -

	Claimed Amount	Revised Amount (Based on repair cost)	Revised Amount (Based on Nett Value)
1. Cost of Repair (w/GST)	\$ 52,232.14(Repairer's Estimate)	\$ <mark>34,240.00</mark>	<mark>\$ 28,890.00</mark>
2. Loss of Rental (45days x \$180.00)	\$ 8,100.00	\$ 3,360.00(21days x \$160.00)	\$ 3,360.00 (21days x \$160.0)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45	\$ 7.45
Total	\$ 60,339.59	<u>\$ 37,607.45</u>	\$ 32,257.4 <u>5</u>

**16days recommendation for repair + 3Sunday + 2PRS = 21days

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate/instruction in Merimen.

Please call me if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)