

INS. CASE OWNER:

CC 3 / ASM 1900

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Motor:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: DS 2000

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: ksc

Repair Cost:

45

S\$ 7,200

(5 days)

Reduction:

75 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 13-06-19

Confirm with JASMINE

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

21/51

S\$ 7,104.00

3 VEH (LOI AND

Loss of Rental (LOR):

S\$ 625.95

(7-5 days)

x + 83.96

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ 375.00

(\$ 30

x

1-5 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☒

(Tick only one)

GIA/LTA Search

S\$ 7.44

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 8,712.44

Global Sum S\$:

FINAL PAYMENT

Date/Time: 13-06-19

Confirm with: JASMINE

Email ☒Call ☐

Payee 1:

S\$ 8,712.44

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF:

A/A/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

BV \$48k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 98252

Yr Regn:

04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White 1R

A/C:

Insured / Std / NI / NA

Sp. Reading

383962

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 277391

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

FALCON

Front

R/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

6/2/19

Rear

R/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

13/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

61 Pny R 72006

(RED: 21,510-15 75%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. SI

Fishes

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Trans-cab Auto Services Pte Ltd

AAD1902-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9825L

VF1ABL15AUC277391

RENAULT

LATITUDE

6.2.2019

AXA

25/4/2014

PART**LIST**

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMEP R BRACKET SIDE RH REAR |
| 5 | 1 BUMEP R RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMEP R BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 OUTER PANEL REAR (End Panel) |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 BOOT REAR |
| 16 | 1 TAILLAMP RH |
| 17 | 1 TAILLAMP PANEL RH |
| 18 | 1 TAILLAMP LH |
| 19 | 1 TAILLAMP PANEL LH |

\$	Bu	1,108.46	✓
\$	B+RD	768.84	✓
\$	DI	113.47	✓
\$	SL	135.97	X
\$	SL	44.99	X
\$	SL	43.61	X
\$	SL	135.97	X
\$	SL	44.99	X
\$	CM	43.61	✓
\$	B	777.52	✓
\$	B	225.95	✓
\$	R	225.95	X
\$	B	1,471.77	✓
\$	SL	404.56	X
\$	B	2,872.68	✓
\$	SL	552.55	X
\$	R	986.70	X
\$	SL	552.55	X
\$	R	986.70	X

\$	11,496.85	11496.84
10% \$	1,149.69	
\$	10,347.17	10347.16

Special Nett

- | | |
|---|------------------------------|
| 1 | 1SET PARKING AID |
| 2 | 1SET REAR BUMPER CLIP |
| 3 | 1SET BUMPER BRACKET CTR CLIP |

\$	phas	700.00	600.00
\$	re	66.00	✓
\$	re	33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1902-042**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
12	1 WINDSCREEN MOULDING	\$	nn	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
14	1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	30sn
15	1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	30sn
TOTAL		\$		605.82	1404.82
TOTAL PARTS		\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601

Trans-cab Auto Services Pte Ltd

AAD1902-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

TOTAL \$ 7,410.00

Over All Total \$ 28,710.15

19161-48

(LUMP SUM)

Repair Days

10-DAYS

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



MANDATE IA (S9M01DDE / SLW 376X)

Type

🔗 Question

Message

Liability: Insured involved in 3 vehicle chain collision insured was the 2nd vehicle. Spoken to insured and he aware that his NCD may affected and AXA to settle at best. Settlement: Repair Cost : \$7,704.00 (w/GST) Loss of Rental: \$625.95 (7.5days x \$83.46) Loss of Income: \$375.00 (7.5days x \$50) LTA Search: \$7.49 Total: \$8,712.44 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (07/05/2019)

Reply



Pls proceed DS with quantum as proposed

Type

🔔 Question

Message

LOR is subject to rental agreement.

Reply

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1902-042

Your Ref : SLL9557X, SLW1376X

Date : 09.April 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

**ACCIDENT INVOLVING SHD9825L AND SLL9557X, SLW1376X ON 06/02/19 01:05 PM
ALONG PIE TOWARDS TUAS**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	7,704.00
2.	Loss of Rental for <u>14</u> days @ \$ <u>83.46</u> per day	\$	1,168.44
3.	Loss of Income for <u>14</u> days @ \$ <u>50.00</u> per day	\$	700.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	9,579.93

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL 9557X (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHD 9825L (TP veh)		
Date of Accident:	06/02/2019		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	20,503.32	
Final Repair Cost	:	\$	7,704.00	
Loss of Token Sum	:	\$	375.00	7.5 days at \$50.00 per day
Rental (if any)	:	\$	625.95	7.5 days
LTA / GIA Search Fee	:	\$	7.49	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	8,712.44

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
		28		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ 0 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD				
NO.2 ANG MO KIO ST 63 SINGAPORE 569111				

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 8,712.44

NUR SHAQILAH BTE ABDOL
WAHAB

24/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC3/ASM19002762/Kea3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 24-06-2019		
ATTN: PETER WANG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 9557X	Veh. Inspected	SHD 9825L	
Policy No.	VPA/P1922878	Coverage (\$)	0.00	
Claim No.	S9M01DDE	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	13/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC277391	Colour	METALLIC WHITE / RED	
Odometer	383962	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	FALKEN	8 mm	
L/H Front Tyre	215/60R16	FALKEN	8 mm	
R/H Rear Tyre	215/60R16	FALKEN	8 mm	
L/H Rear Tyre	215/60R16	FALKEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2019	Inspection Date	13/02/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9825L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	BENT / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	SERVICEABLE	404.56	-
1	BOOT REAR (CONSISTENT)	BENT	2,872.68	2,872.68
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
	LESS 10% DISCOUNT		-1,149.68	-738.23
			10,347.16	6,644.07
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-

Report Ref No. CC3/ASM19002762/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	30.00
			1,404.82	825.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. THE INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR, TAILLAMP PANEL RH AND TAILLAMP PANEL LH.		3,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALING REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,410.00	1,500.00
	GRAND TOTAL		19,161.98	8,969.07

Report Ref No. CC3/ASM19002762/Kea3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,200.00
---	--	--	----------

Report Ref No. CC3/ASM19002762/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.