

AAD1902-042

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9825L

VF1ABL15AUC277391

RENAULT

LATITUDE

6.2.2019

AXA

25/4/2014

PART

LIST

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 BOOT REAR
- 16 1 TAILLAMP RH
- 17 1 TAILLAMP PANEL RH
- 18 1 TAILLAMP LH
- 19 1 TAILLAMP PANEL LH

\$	Bu	1,108.46	✓
\$	Bu	768.84	✓
\$	Di	113.47	✓
\$	SL	135.97	X
\$	SL	44.99	X
\$	SL	43.61	X
\$	SL	135.97	X
\$	SL	44.99	X
\$	CM	43.61	✓
\$	Bu	777.52	✓
\$	Bu	225.95	✓
\$	R	225.95	X
\$	Bu	1,471.77	✓
\$	SL	404.56	X
\$	Bu	2,872.68	✓
\$	SL	552.55	X
\$	R	986.70	X
\$	SL	552.55	X
\$	R	986.70	X

\$ 11,496.85

10% \$ 1,149.69

\$ 10,347.17

Special Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP

\$	Shas	700.00	6000
\$	ru	66.00	✓
\$	ru	33.00	✓

Not Noticing
6/1 Sep @ 7200
Book Value ??

Trans-cab Auto Services Pte Ltd**AAD1902-042**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11 2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
12 1 WINDSCREEN MOULDING	\$	nn	100.00	X
13 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
14 1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	3050
15 1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	3050
TOTAL	\$		605.82	
TOTAL PARTS	\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	600
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	600
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	600

Trans-cab Auto Services Pte Ltd**AAD1902-042**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9825L

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X**TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days**~~10 DAYS~~*5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: