

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9984K

AAD1902-037

*Not authorized
 U/Sing @ ?
 Book Value ??*

Vehicle No.: **SHD 9984K**
 Chassis No.: VF1ABL15AUC278130
 Vehicle Make: RENAULT
 Vehicle Model: LATITUDE
 Date of Accident : 2.2.2019
 Third Party Insurer : **AXA**
 Date of Registration : 13/6/2014

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buc/cm</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>cm</i> 150.77	✓
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	X
1	HEADLAMP RH	\$	<i>ngem</i> 1,184.43	✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>cm</i> 278.84	✓
1	FENDER BRACKET LOWER RH	\$	<i>R</i> 15.79	X
1	FENDER INSULATOR RH	\$	<i>Sm</i> 130.84	X
1	TOW COVER FRT	\$	<i>Sm</i> 28.61	} X
1	RADIATOR GRILLE	\$	<i>Sm</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
1	HORN	\$	<i>Sm</i> 314.17	
1	HORN BRACKET	\$	<i>R</i> 40.45	
1	HEADLAMP RH	\$	<i>ngem</i> 1,184.43	
1	HEADLAMP PANEL FRT RH	\$	<i>Sm</i> 152.15	
1	SUBFRAME OUTER FRT	\$	<i>Sm</i> 2,652.45	
1	SUBFRAME BRACKET OUTER RH	\$	<i>R</i> 92.36	
1	ENGINE UNDERTRAY	\$	<i>Sm</i> 564.98	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9984K

AAD1902-037

1	DOOR PANEL FRT RH	\$	R ₁ 2,844.66	✓
1	DOOR HINGE UPPER RH	\$	R ₁ 261.28	✓
1	DOOR HINGE LOWER RH	\$	R ₁ 300.55	✓
1	DOOR CHECK FRT RH	\$	Diy 194.77	✓
1	DOOR LOCK FRT RH	\$	N ₁ 908.75	✓
1	DOOR CATCH FRT RH	\$	N 131.23	X
1	DOOR HANDLE OUTER FRT RH	\$	S ₁ 477.76	X
1	DOOR HANDLE COVER FRT RH	\$	S ₁ 13.22	X
1	DOOR HANDLE MODULE FRT RH	\$	S ₁ 133.60	X
1	DOOR REGULATOR FRT RH	\$	R ₁ 505.19	✓
1	DOOR REGUALTOR MOTOR FRT RH	\$	T ₁ 796.46	✓
1	DOOR REGULATOR GUIDE FRT RH	\$	S ₁ 120.97	X
1	DOOR PANEL REAR RH	\$	R ₁ 2,844.66	✓
1	DOOR GUIDE REAR RH	\$	S ₁ 176.82	X
1	DOOR HINGE UPPER RH	\$	N 274.50	X
1	DOOR HINGE LOWER RH	\$	R ₁ 300.55	✓
1	DOOR CHECK REAR LH/RH L70Y	\$	S ₁ 203.06	X
1	DOOR MIRROR ASSY RH	\$	CM 1,483.40	✓
1	ROCKER PANEL INNER GARNISH RH	\$	S ₁ 466.51	} X
1	ROCKER PANEL INNER RH	\$	N 1,024.79	
1	ROCKER PANEL CENTER RH	\$	N 990.25	
1	FRONT DOOR HARNESS WIRE	\$	S ₁ 2,670.00	
1	BONNET	\$	N 1,941.63	
1	BONNET INSULATOR	\$	S ₁ 405.73	
1	BONNET STRUT LH	\$	S ₁ 88.61	
1	BONNET STRUT RH	\$	S ₁ 88.61	
1	BONNET HINGE LH	\$	N 348.31	
1	BONNET HINGE RH	\$	N 348.31	
1	BONNET LOCK	\$	N 305.48	
1	BONNET CABLE	\$	S ₁ 119.19	
1	BONNET CABLE COVER	\$	S ₁ 161.03	
1	BONNET SEAL OUTER	\$	S ₁ 92.36	
1	BONNET SEAL INNER	\$	S ₁ 157.28	
1	SUBFRAME OUTER FRT	\$	S ₁ 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	S ₁ 92.36	
1	SUBFRAME BRACKET OUTER RH	\$	S ₁ 92.36	
1	ENGINE UNDERTRAY	\$	S ₁ 564.98	
1	A/C CONDENSER	\$	S ₁ 2,020.37	

Trans-cab Auto Services Pte Ltd

AAD1902-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9984K

1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	X
1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	X
1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	X
1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	X
1	LOWER ARM RH	\$	DIT	685.76	✓
1	KUNCKLE ARM RH	\$	Bz	846.98	✓
1	ABSORBER FRT RH	\$	Bz	360.54	✓
1	STABILIZER BAR FRT	\$	Bz	604.65	✓
1	DRIVESHAFT RH	\$		1,747.45	?
1	WIPER RESERVOIR	\$		348.25	?
1	WIPER RESERVOIR NECK	\$	Sn	136.11	X
1	WIPER RESERVOIR MOTOR	\$	Sn	270.06	X
		\$		47,516.26	
		10% \$		4,751.63	
		\$		42,764.63	

Special Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
2	WINDSCREEN SEALANT	\$	na	253.80	405m
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR ADVERTISEMENT STICKER	\$	na	300.00	150m
1	REAR DOOR ADVERTISEMENT STICKER	\$	na	300.00	150m
1	ROCKER PANEL ADVERTISEMENT STICKER	\$	na	200.00	100m
2	ABSORBER BOLT L70Y	\$	Sn	44.01	X
2	ABSORBER NUT L70Y	\$	Sn	17.56	X
1	DOOR CHECK BOLT	\$	Sn	22.69	X
1	DOOR GUIDE SCREW	\$	Sn	10.85	X
1	DOOR HINGE BOLT	\$	Sn	10.85	X
1	DOOR HINGE NUT RH	\$	Sn	14.60	X
1	DOOR CHECK BOLT	\$	Sn	22.69	X

Trans-cab Auto Services Pte Ltd

AAD1902-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9984K

1	DOOR CHECK NUT	\$	<i>nn</i> 3.75 X
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12 X
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06 X
1	FRONT RIGHT TYRE RIM	\$	<i>Pr</i> 380.00 ✓
1	FRONT RIGHT TYRE	\$	<i>Pr</i> 330.00 <i>70/16</i>

TOTAL	\$	2,235.00
--------------	-----------	-----------------

TOTAL PARTS	\$	44,999.63
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>1200l</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>1540l</i>
To rust-proofing of the affected areas.	\$	170.00	<i>120l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>100l</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>60l</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>20l</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>30l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of windscreen fittings, attachment and perform water seepage test.	\$	380.00	<i>120l</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	<i>120l</i> <i>60l</i>

Trans-cab Auto Services Pte Ltd

AAD1902-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9984K

To transfer of Rear door fittings, attachment and perform water seepage test.	\$		380.00	<i>601</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	<i>2501</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i>	380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>na</i>	170.00	<i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i>	170.00	<i>X</i>
TOTAL	\$		13,110.00	
Over All Total	\$		58,109.63	

LUMP SUM (REPAIR DAY)~~**30 DAYS**~~*11 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: