

REF: NTUL

Hwee Jie

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLQ 4070P Yr Regn: 7 Jul 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Honda Vezel c.c. 1496
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 98024 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: RV31213220
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/60 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 12/2/19 D.O.I. 14/2/19 @ 0209P
 Survey held at World Auto
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/3/19	Confirmed P/P \$4340/- with 5 days of repair. - Hwee Jie (red. 406.30% 48%)
RECEIVED 19 MAR 2019	

5/8/19 Refinalised to \$4460/- part my part Celine 1/8/19
 1st close date 25/3/19 * resurvey ref only

Date/Time: File Pass to? : Preli. Report
 : Final Report
 1) 193 Typst
 Date/Time: File Return to?

Days Of Repair: 5
 Resurvey No. of Trip: 1

Survey Fee:	250
Transportation:	
_____ S + PS. _____ \$	
) Photos	
) Other	
TOTAL	250

Report Format: TP
 Lump Sum / I.B.I.: 4340/-

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

TOKIO MARINE INSURANCE SINGAPORE LTD
 20 McCLUM STREET,
 #09-01 TOKIO MARINE CENTRE 069046

Attention : Motor Claim Department
 Contact : 6221 6111 Fax No. : 6221 2101

Estimate : ES190069

Date : 13/02/2019
 Vehicle Num. : SLQ 4070P (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 12/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID DEF	1100	4,250.00 ✓
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL) NEC	56	89.00 ✓
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL) NEC	56	89.00 ✓
4.	1	REAR WINDSCREEN GLASS MOULDING NEC	150	250.00 ✓
5.	2	REAR BOOT REFLECTOR LAMP NM	580.00	1,160.00 X
6.	1	REAR BOOT LOCK ASSY Svc		330.00 X
7.	1	REAR BOOT HAND GRIP COVER DEF		78.00 ✓
8.	1	REAR BUMPER DEF	760	900.00 ✓
9.	1	REAR END PANEL DO	700	860.00 ✓
10.	1	REAR END PANEL TOP GARNISH NM		260.00 X
11.	1	REAR BOOT WEATHER STRIP NM		180.00 X
List TotalS\$:				5,446.00
20.00% Discount S\$:				1,089.20
				4,356.80

SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT NEC	60	100.00 ✓
2.	1	REAR BUMPER CLIP NEC	30	40.00 ✓
3.	1	REAR END PANEL TOP GARNISH CLIPS NM		40.00 X
4.	1	REVERSE SENSOR Shorted	200	280.00 ✓
Special Nett Total S\$:				460.00

LABOUR :
 TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES
 REMOVE & REFIT REAR WINDSCREEN GLASS

50 180.00 ✓

120. ✓

CONTINUE / ...

Check

with ok
Simon

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

TOKIO MARINE INSURANCE SINGAPORE LTD
 20 McCLUM STREET,
 #09-01 TOKIO MARINE CENTRE 069046

Attention : Motor Claim Department
 Contact : 6221 6111 Fax No. : 6221 2101

Estimate : ES190069

Date : 13/02/2019
 Vehicle Num. : SLQ 4070P (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 12/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	30	180.00 ✓
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	700	1,100.00 ✓
		PUTTY AND SPRAY PAINT & ALL AFFECTED AREAS(INNER&OUTER)	600	1,000.00 ✓
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	30	180.00 ✓
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	200	450.00 ✓
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)	120	450.00 ✓
		Labour Total S\$:		3,540.00

E. & O.E.

Total S\$:

8,356.80

Total - \$4340

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jia - LKK

14/2/19

2/8 5 days

esi

Denise

tgttan@worldauto.com.sg

From: tgttan@worldauto.com.sg
Sent: Monday, 18 March 2019 12:55 PM
To: 'Hwee Jie (LKK Auto)'
Subject: RE: SLQ 4070P Our ref: TP/2466/19

22/3/19

Hi Hwee Jie

We cannot agree on your proposal for rear end panel at \$550.

We can only agree at \$700.

Therefore we append our calculations as follows:-

COR	:	\$2900
20%		<u>\$ 580</u>
		\$2320
SN		\$ 290
Labour		<u>\$1730</u>
		<u>\$4340</u>

Kindly confirm.

Rdgs
Sophia

From: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Sent: Monday, 18 March 2019 11:01 AM
To: tgttan@worldauto.com.sg
Cc: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: SLQ 4070P Our ref: TP/2466/19

Hi Sophia,

Finalized amount is P/P repair \$4,220/- with 5days.
Please let me know if you're agree with this amount so I can proceed with finalize, thank you.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tgttan@worldauto.com.sg [<mailto:tgttan@worldauto.com.sg>]
Sent: Monday, 25 February, 2019 11:34 AM
To: Hwee Jie (LKK Auto)
Subject: SLQ 4070P Our ref: TP/2466/19

Hi Hwee Jie

Can we finalise?

tgttan@worldauto.com.sg

From: tgttan@worldauto.com.sg
Sent: Monday, 1 April 2019 2:56 PM
To: 'Hwee Jie (LKK Auto)'
Subject: FW: SLQ 4070P Our ref: TP/2466/19

Hi Hwee Jie

Has been brought to my attention that the labour to remove & refit rear windscreen glass has been omitted.

We are claiming \$120.

Therefore the labour will be \$1850 (\$1730 + \$120).

Total finalised COR \$4460.

Kindly revert.

Rdgs
Sophia

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>
Sent: Friday, 22 March 2019 4:18 PM
To: 'Hwee Jie (LKK Auto)' <hweejie@lkkauto.com>
Subject: RE: SLQ 4070P Our ref: TP/2466/19

Hi Hwee Jie

Kindly revert.

Rdgs
Sophia

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>
Sent: Monday, 18 March 2019 12:55 PM
To: 'Hwee Jie (LKK Auto)' <hweejie@lkkauto.com>
Subject: RE: SLQ 4070P Our ref: TP/2466/19

Hi Hwee Jie

We cannot agree on your proposal for rear end panel at \$550.

We can only agree at \$700.

Therefore we append our calculations as follows:-

COR	:	\$2900
20%		<u>\$ 580</u>
		\$2320
SN		\$ 290
Labour		<u>\$1730 + \$120 = \$1850</u>
		<u>\$4340 (\$4460)</u>

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

TOKIO MARINE INSURANCE SINGAPORE LTD
 20 McCLUM STREET,
 #09-01 TOKIO MARINE CENTRE 069046

Attention : Motor Claim Department
 Contact : 6221 6111 Fax No. : 6221 2101

Estimate : ES190069

Date : 13/02/2019
 Vehicle Num. : SLQ 4070P (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 12/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID DEF	1200	1,200.00 ✓
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL) NEC	69.00	69.00 ✓
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL) NEC	89.00	89.00 ✓
4.	1	REAR WINDSCREEN GLASS MOULDING NEC	250.00	250.00 ✓
5.	2	REAR BOOT REFLECTOR LAMP MM	580.00	1,160.00 X
6.	1	REAR BOOT LOCK ASSY Svc		330.00 X
7.	1	REAR BOOT HAND GRIP COVER DEF		78.00 ✓
8.	1	REAR BUMPER DEF	300.00	300.00 ✓
9.	1	REAR END PANEL DD	800.00	800.00 ✓ 700.00
10.	1	REAR END PANEL TOP GARNISH MM		260.00 X
11.	1	REAR BOOT WEATHER STRIP MM		180.00 X
List Total S\$:				5,448.00
20.00% Discount S\$:				1,089.20
				4,358.80

SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT NEC	100.00	100.00 ✓
2.	1	REAR BUMPER CLIP NEC	40.00	40.00 ✓
3.	1	REAR END PANEL TOP GARNISH CLIPS MM		40.00 X
4.	1	REVERSE SENSOR Shorted	200	200.00 ✓
Special Nett Total S\$:				460.00

LABOUR : TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES 50 180.00 ✓

REMOVE & REFIT REAR WINDSCREEN GLASS 120 (omitted)

20% 2750
 450
 2200
 SW 290
 Labour 1730
 4220

CONTINUE / ...
 2900
 580
 2320
 SW 250
 Labour 1730 + 120 = 1850
 4340 + 120 = 4460

WORLD AUTO PTE LTD

47-Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

TOKIO MARINE INSURANCE SINGAPORE LTD
 20 McCLUM STREET,
 #09-01 TOKIO MARINE CENTRE 069046

Attention : Motor Claim Department
 Contact : 6221 6111 Fax No. : 6221 2101

Estimate : ES190069

Date : 13/02/2019
 Vehicle Num. : SLQ 4070P (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 12/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

30 180.00 ✓

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.

700 1,100.00 ✓

PUTTY AND SPRAY PAINT & ALL AFFECTED AREAS(INNER&OUTER)

600 1,000.00 ✓

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS

30 180.00 ✓

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)

200 450.00 ✓

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

120 450.00 ✓

Labour Total S\$:

3,540.00

1850

E. & O.E.

Total S\$:

8,356.80

=====

6221-6111

847680

[Signature]
2/2/19

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jia - LKK

14/2/19

2/8 5 days

[Signature]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4070P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	DEFORMED	1,250.00	1,100.00
1	REAR BOOT HYBRID EMBLEM (VEZEL)	NECESSARY	89.00	56.00
1	REAR BOOT VEZEL EMBLEM (VEZEL)	NECESSARY	89.00	56.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	250.00	150.00
2	REAR BOOT REFLECTOR LAMP @\$580.00	NOT NECESSARY	1,160.00	-
1	REAR BOOT LOCK ASSY	SERVICEABLE	330.00	-
1	REAR BOOT HAND GRIP COVER	DEFORMED	78.00	78.00
1	REAR BUMPER	DEFORMED	900.00	760.00
1	REAR END PANEL	DENTED	860.00	700.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	260.00	-
1	REAR BOOT WEATHER STRIP	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-1,089.20	-580.00
			4,356.80	2,320.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			460.00	290.00
<u>LABOUR</u>				
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	50.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	TO APPLY RUST-PROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	30.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT / WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		1,100.00	700.00
	PUTTY AND SPRAY PAINT & ALL AFFECTED AREAS (INNER&OUTER).		1,000.00	600.00

Report Ref No. CS/INC19002766/Jtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START / STOP UNIT CAPACITORS.		180.00	30.00
	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES).		450.00	200.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINSTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	120.00
			3,660.00	1,850.00
	GRAND TOTAL		8,476.80	4,460.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,460.00

Report Ref No. CS/INC19002766/Jtd3e2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.