



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Insured CHUAN LIM CONSTRUCTION PTE LTD
Policy CV1/GA343533/1

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 13/2/2019
Our Case Ref. SC19/01/023/4CL-OD
Accident Date 29/1/2019

Damaged Vehicle No: XD5793G

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	FRONT WINDSCREEN CRA	1 PC	\$1,888.00	10.00%	\$1,699.20 ✓
2	SEALANT NEC	8 PC	\$49.00	-	\$392.00 ✓
3	SUN VISOR CRA	1 PC	\$386.10	10.00%	\$347.49 ✓
4	TOP MARKER LAMP LHS CRA	1 PC	\$136.62	10.00%	\$122.96 ✓
5	WINDSCREEN GARNISH LHS	1 PC	\$225.00	10.00%	\$202.50 ?
6	WIPER BLADE	1 PC	\$88.92	10.00%	\$80.03 ?
7	WIPER ARM	1 PC	\$500.94	10.00%	\$450.85 ?
8	FRONT CAB CORNER CRA	1 PC	\$1,065.15	10.00%	\$958.64 ✓
9	HEADLAMP LHS CRA	1 PC	\$772.47	10.00%	\$695.22 ✓
10	FRONT BUMPER CORNER LHS DEF	1 PC	\$1,329.30	10.00%	\$1,196.37 ✓
11	FRONT BUMPER BRACKET BUC	1 PC	\$596.85	10.00%	\$537.17 ?
12	MUDGUARD LHS BUC	1 PC	\$1,628.46	10.00%	\$1,465.61 ✓
13	BOARDING STEP STRUCTURE CRA DEF	1 PC	\$1,412.46	10.00%	\$1,271.21 ✓
14	STEP PLATE CRA	1 PC	\$607.65	10.00%	\$546.89 ✓
15	TOP EXTERIOR MIRROR CRA	1 PC	\$252.65	10.00%	\$227.39 ✓
16	TIE ROD BT	1 PC	\$382.50	10.00%	\$344.25 ✓
Labour Charges					
1	LABOUR FOR WIRING	1	\$200.00	- 840	\$200.00 ✓
2	LABOUR FOR FRONT PORTION	1	\$5,120.00	- 2000	\$5,120.00 ✓
3	SPRAY PAINTING	1	\$1,800.00	- 1000	\$1,800.00 ✓
4	LABOUR FOR FRONT WINDSCREEN	1	\$700.00	- 400	\$700.00 ✓



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Insured CHUAN LIM CONSTRUCTION PTE LTD
Policy CV1/GA343533/1

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 13/2/2019
Our Case Ref. SC19/01/023/4CL-OD
Accident Date 29/1/2019

Damaged Vehicle No: XD5793G

S/no	Description	QTY	Price	Disc	Amount
5	LABOUR FOR UNDERCARRIAGE	1	\$1,280.00	250	\$1,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


15/2/19
hwee.jie@lkkauto.com
91803151

Sub Total \$ 19,637.78

Authorised Signature

not authorise. 14/2/19
4/5 days