

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

302

TO : 200810030D

FIRST HIACE (S) PTE LTD
NO 53 UBI AVENUE 1
05-12 PAYA UBI INDUSTRIAL PARK
SINGAPORE
TEL : 81390855 FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00005084
Date : 13/02/2019
Case No : AD00010236
Vehicle No : SKM2475B
Chassis : MNTBBAB17Z0009634
Year of Mfr : 2013
Policy No :
Model : NISSAN SYLPHY 1.6
CVT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT DOOR RH <i>3.550</i>	1.0	876.40	10	788.76
2	FRONT DOOR TOP STICKER RH <i>me</i>	1.0	27.30	10	24.57
3	FRONT DOOR INNER LOCK RH	1.0	231.10	10	207.99
4	FRONT DOOR PROTECTOR MOULDING RH <i>31</i>	1.0	191.80	10	172.62
5	REAR DOOR RH <i>2/3rd</i>	1.0	876.40	10	788.76
6	REAR DOOR TOP STICKER RH <i>me</i>	1.0	27.30	10	24.57
7	REAR DOOR HINGE TOP RH <i>17</i>	1.0	56.10	10	50.49
8	REAR DOOR HINGE BOTTOM RH	1.0	56.10	10	50.49
9	FRONT DOOR INNER RUBBER RH <i>me</i>	1.0	85.30	10	76.77
10	FRONT DOOR HANDLER SENSOR LOCK	1.0	96.70	10	87.03
11	ROCKER PANEL REAR STICKER <i>me</i>	1.0	88.10	10	79.29
Nett Price - Parts Sub Total					2,351.34
12	REAR DOOR PILLAR CENTER PILLAR RH - REPAIR <i>2x</i>	1.0			
13	FRONT DOOR PILLAR CENTER PILLAR RH - REPAIR <i>2x</i>	1.0			
14	ROCKER PANEL RH - REPAIR <i>2x</i>	1.0			
15	REAR FENDER RH - REPAIR <i>2x</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					2,351.34
16	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0 <i>520</i>	800.00
17	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0 <i>800</i>	900.00
18	ANTI-RUST COATING	1.0	250.00	0 <i>80</i>	250.00
Labour 1 Sub Total					1,950.00
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED TWO AND CENTS FORTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		4,301.34
			GST 7.00%		301.09
			TOTAL		4,602.43

Date of accident : 12/02/2019 05:20 PM Place : EXIT OF 53 PAYA UBI INDUSTRIAL PARK

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

CUSTOMER SIGNATURE

Date:

AUTHORISED SIGNATURE