



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

SJU 601 L
NISSAN LATIO

Not Adm
hlar
H/S 5000/2
14/1/19
The H. H. H. H.

ATTN:			QTY	PRICE
NO.	DESCRIPTION - PARTS			
1	REAR WINDSCREEN RUBBER MOULDING	neu 66-10	1	\$ 145.30
2	BOOTLID	ms/3rd 787.50	1	\$ 995.20
3	BOOTLID DAMPER	17	2	\$ 382.40
4	BOOTLID INNER LOCK	su	1	\$ 357.60
5	BOOTLID STRIKER	17	1	\$ 38.20
6	BOOTLID OPENER SWITCH	17	1	\$ 289.20
7	BOOTLID HINGE	12	2	\$ 115.20
8	BOOTLID WEATHERSTRIP	12/1 88.40	1	\$ 174.90
9	BOOTLID LOGO	neu 50.70	1	\$ 110.00
10	BOOTLID EMBLEM "LATIO"	neu 80.90	1	\$ 84.50
11	BOOTLID INNER TRIM	17	1	\$ 446.10
12	REAR BUMPER	7.5 532.40	1	\$ 694.50
13	REAR BUMPER SIDE RETAINER	su/cm 32.50	2	\$ 158.40
14	REAR BUMPER BRACKET	12	2	\$ 199.60
15	REAR BUMPER BEAM	NS	1	\$ 518.00
16	SMART ENTRY ANTENNA	17	1	\$ 457.20
17	TAILLAMP	MS 320 277.50	2	\$ 858.00
18	TAILLAMP PANEL	MS 145.00	2	\$ 700.80
19	REAR FENDER LH	300g/Buc 1052.70	1	\$ 1,152.60
20	REAR FENDER INNER TRIM LH	De 254.90	1	\$ 328.00
21	REAR FENDER COWLING LH	Re 38.60	1	\$ 186.00
22	REAR END PANEL	3.5g 434.40	1	\$ 585.00
23	REAR END PANEL TOP GARNISH	17	1	\$ 298.00
24	REAR FLOOR PANEL	12	1	\$ 974.60
25	REAR FLOOR PANEL BOARD	cm	1	\$ 495.00
26	REAR EXHAUST PIPE	17	1	\$ 754.60
27	REAR EXHAUST MOUNTING	17	1	\$ 56.00
			4336.60	SUBTOTAL
			3902.94	LESS 10%
				PARTS TOTAL
				\$ 11,409.60
				\$ 1,140.96
				\$ 10,268.64
SPECIAL NETT			QTY	PRICE
1	REAR NUMBER PLATE	17	1	\$ 100.00
2	REVERSE SENSOR	8mm	2	\$ 300.00
3	REAR END PANEL SEALANT	neu	1	\$ 120.00
4	SPARE WHEEL PANEL SEALANT	17	1	\$ 120.00
5	SPARE WHEEL	17	1	\$ 600.00
6	REAR BUMPER CLIPS	neu	10	\$ 100.00
7	REAR FENDER COWLING CLIPS	17	10	\$ 100.00
8	REAR FENDER INNER TRIM CLIPS	17	10	\$ 100.00

X
200
50
X
X
30
X
X

