

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

14 FEB 2019

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 50114
Date Estimated : 14/02/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -

Hu Chee Woon
63 Kovan Road

Singapore
Singapore 548150

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX827A	0G74172	31/07/2015	X4 xDrive20i	0

DESCRIPTION

VALUE

Replacing rear bumper panel and attachments, tailgate, rework tailpanel, etc to knock out dents caused by the accident

2550 3,400.00

Spray rear bumper, tailgate and tailpanel *photo*

2473 2,749.00

To supply rear emboss number plate.

63 83.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

photo ? 451 531.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To replace rear windscreen glass.

488 574.00

To conduct water leak tests.

63 75.00

To replace front seat crash-active head restraint air bags including reset and conduct check for function.

photo ? 451 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries

? 150.00

To supply and install rear windscreen solar film.

451 531.00

Total Labour 1: 9,190.00

DESCRIPTION	QTY	PRIC	VALUE
SCREW SELF TAPPING	4	1.10	? 4.40