



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE SINGAPORE PTE LTD

Address: 8 Shenton Way #24-01 Singapore 068811

Telephone: 6338 7288 Fax: 6880 4838

Email: motor.survey@axa.com.sg

Make/ Model : NISSAN CABSTAR

Date: 14-02-19

Chassis No : JN1SF4F23Z0861625

Vehicle No: GZ 7000 J

Date/Time of Accident : 12-02-19 10:50

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

| ITEMS | PARTS DESCRIPTION | QTY | LIST PRICE \$ | PARTS DISCOUNT | FINAL PRICE \$ |
|-------|--|-----|---------------|----------------|----------------|
| 1 | TAIL GATE <i>DN</i> | 1 | \$ 1,399.80 | 30% | \$ 979.86 ✓ |
| 2 | TAIL GATE HINGE <i>Repair</i> | 3 | \$ 170.50 | 30% | \$ 119.35 X |
| 3 | TAIL GATE LOCK <i>BT</i> | 2 | \$ 190.00 | 30% | \$ 133.00 ✓ |
| 4 | TAIL GATE LOWER MOUNTING <i>BT</i> | 2 | \$ 35.00 | 30% | \$ 24.50 ✓ |
| 5 | TAIL GATE SIDE LOCK <i>NN</i> | 2 | \$ 373.20 | 30% | \$ 261.24 X |
| 6 | TAIL LAMP <i>CRA</i> | 2 | \$ 317.40 | 30% | \$ 222.18 ✓ |
| 7 | TAIL LAMP BRACKET <i>DEF</i> | 2 | \$ 97.80 | 30% | \$ 68.46 ✓ |
| 8 | REAR NUMBER PLATE BRACKET <i>BT</i> | 1 | \$ 48.90 | 30% | \$ 34.23 ✓ |
| 9 | REAR NUMBER PLATE LAMP <i>NN</i> | 1 | \$ 73.50 | 30% | \$ 51.45 X |
| 10 | REAR SPARE TYRE CROSS MEMBER <i>NN</i> | 2 | \$ 468.60 | 30% | \$ 328.02 X |
| 11 | REAR SPARE TYRE REGULATOR GEAR <i>NN</i> | 1 | \$ 195.50 | 30% | \$ 136.85 X |

| SPECIAL ITEMS | PARTS DESCRIPTION | QTY | PRICE \$ | FINAL PRICE \$ |
|---------------------------------|---|-----|-----------|----------------------------|
| 1 | TAIL GATE STICKER "13 PAX" | 1 | \$ 25.00 | \$ 25.00 ✓ |
| 2 | TAIL GATE STICKER "NISSAN" } <i>NEC</i> | 1 | \$ 75.00 | \$ 75.00 ✓ |
| 3 | TAIL GATE STICKER "70KM/H" } <i>NEC</i> | 1 | \$ 25.00 | \$ 25.00 ✓ |
| 4 | REAR NUMBER PLATE <i>DEF</i> | 1 | \$ 40.00 | \$ 40.00 ✓ |
| 5 | REVERSE SENSOR <i>CRA</i> | 2 | \$ 450.00 | \$ 200 450.00 ✓ |
| Total Special Items Cost | | | | \$ 2,974.14 |

| Labour Works/ Panel Beating Related Works | | Quotation |
|---|--|----------------------------|
| Job Scope | | |
| TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS | | \$ 550 800.00 ✓ |
| Spray Painting | | Quotation |
| Job Scope | | |
| TO RESPRAY AFFECTED AREAS | | \$ 450 600.00 ✓ |
| Others Cost (Accident Repair Related Expenses) | | Quotation |
| Job Scope | | |
| TO TUFFCOAT AFFECTED AREA | | \$ 100 250.00 ✓ |
| TO REMOVE/ REFIT WIRING CHECKS | | \$ 30 60.00 ✓ |

| | | |
|---|-------|-------------|
| TO REMOVE/ REPLACE REVERSE SENSORS | \$ 20 | 120.00 ✓ |
| TO REMOVE AND REPLACE TAIL GATE MECHANISM | \$ 50 | 100.00 ✓ |
| Total Others Cost | \$ | 530.00 |
| GRAND TOTAL | | \$ 4,904.14 |



CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Cecilia Chong
 Job Title: Operation Executive
 Direct Contact: 65 9023 6692
 Email: cecilia@carzauto.com.sg

Hwee Jie - LKK
 15/2/19
 L/S 4 days



- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: