

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

VSKYBAM 2040049960

MAKOTO-YA (S) PTE LTD
No. 9 Kaki Bukit Road 2
Gordon Warehouse Building,
#01-05, Singapore 417842

TP AXA
Vic

Date :01.03.2019
Vehicle no :GBC 6806 M
Make/Model :NISSA NNV200
Accident date :31.01.2019

No	DESCRIPTION	Qty	Amount (\$)
Nett Items			
1	Rear LH door <i>Distorted</i>	1	\$ 1409.2 ✓
2	Rear LH Nissan emblem <i>3 New</i>	1	\$ 71 ✓
3	Rear LH NV200 emblem <i>3 New</i>	1	\$ 137.6 ✓
4	Rear LH door handle <i>Dehd</i>	1	\$ 369.6 ✓
5	Rear LH door hinges @ \$115.60 <i>3 New</i>	2	\$ 231.2 ✓
6	Rear LH door inner lock <i>Jammed</i>	1	\$ 122.3 ✓
7	Rear LH door inner board <i>New</i>	1	\$ 243.3 ✓
8	Rear LH door inner handle <i>New</i>	1	\$ 104.6 ✓
9	Rear RH door <i>Distorted</i>	1	\$ 1057 ✓
10	Rear RH door DCI emblem <i>New</i>	1	\$ 61.8 ✓
11	Rear RH door hinges @ \$115.60	2	\$ 231.2 ✓
12	Rear RH door inner lock <i>Jammed</i>	1	\$ 122.3 ✓
13	Rear RH door inner board <i>New</i>	1	\$ 171.2 ✓
14	Rear RH door side rubber <i>ut</i>	1	\$ 116.6 ✓
15	Rear end inner panel <i>Dented</i>	1	\$ 972.4 <i>794.40</i>
16	Rear end panel topgarnish <i>cracked</i>	1	\$ 93.5 ✓
17	Rear bumper <i>Dehd</i>	1	\$ 695.9 ✓
18	Rear bumper side holder @ \$38.70 <i>New</i>	2	\$ 77.4 ✓
19	Rear bumper reflector @ \$73.30 <i>cracked</i>	2	\$ 146.6 ✓
20	Rear end panel outer panel <i>Dented</i>	1	\$ 270.8 ✓
21	Rear floor panel <i>Repair</i>	1	\$ 2032.8 ✓
22	Rear lamp @ \$284.60 <i>cracked</i>	2	\$ 569.2 ✓
23	Rear spare tyre carriage <i>Bent</i>	1	\$ 305.3 ✓
24	Rear door centre lock pump <i>Painted</i>	1	\$ 172.6 ✓
			\$ 9785.4
		Less 10% Disc	\$ 978.54
		Total	\$ 8806.86

Special Nett Items

1	Rear LH door 70KM sticker <i>Free</i>	1	\$ 48 <i>15</i>
2	Rear RH door 6pax sticker <i>Free</i>	1	\$ 48 <i>15</i>
3	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 380 <i>200</i>
		Total	\$ 476

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MAKOTO-YA (S) PTE LTD
No. 9 Kaki Bukit Road 2
Gordon Warehouse Building,
#01-05, Singapore 417842

Date :01.03.2019
Vehicle no :GBC 6806 M
Make/Model :NISSA NNV200
Accident date :31.01.2019

No	DESCRIPTION	Qty	Amount (\$)
Labour Cost			
1	To supply rear widnscreen sealant		\$ 100 80.
2	Remove & reinstall rear windscreen		\$ 250 200
3	Remove & reinstall floor mat		\$ 100 50
4	Remove, repalce & repair consistent to the accident	2590	\$ 2000 1200.
5	Respray painting		\$ 1800 1000.
6	Tuff kote		\$ 150 60.
	Total		\$ 4400
	Grand Total		\$ 13682.86

total: 8961.87.
H/S: 7.1K
09 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: