

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7044K

DATE 13/2/2019 16:48

MAKE :

MODEL : HYUNDAI i40

AXA / FZ PP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 553.00
	Rear Wheel Hup-Cap (LH) <i>X repair</i>			\$ 107.10
	SUB TOTAL			\$ 660.10
	LESS 20%			\$ 132.02
	DISCOUNTED TOTAL			\$ 528.08
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>me</i>			\$ 80.00
				\$ 130.00
	Labour Charge			
	Panel Beating-Repair Rear LH Fender & Rear LH Door			\$ 350.00 <i>200</i>
	Spray Painting Charge			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 30.00 <i>X 43</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>X 43</i>
	Rear Wheel Alignment			\$ 80.00 <i>X 43</i>
	TOTAL LABOUR			\$ 1,290.00
	ESTIMATE TOTAL			\$ 1,948.08

Kalvin 10064
M 14/2/19 1146hr.
2 hrs
PIP
After Repair p/h

LKH Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.