

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0204/2019/GW
Date : 16-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKJ 9133 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Phua Hwee Chay, Derrick
Address : 62 Mei Hwan Drive
#07-05
Singapore 568427
Telephone : HP +65 96691008
Type of Claim : Third Party Claims
Policy No. : 5092331500-01
Vehicle No : **SBW 1282 B**
Model Code : A4 Sedan 1.4 TFSI
Model / Year : 1/7/2016
Engine No : CVN 012777
Chassis No : WAUZZZF49GA100707
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Feb-19
Place of Accident : Along PIE towards Changi After Exit 15

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBW 1282 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	
2	To dismantle and renew rear bumper. Re-organsie crash management components. Reinstall all parts removed.	\$ 900.00	
3	To respray rear bumper	\$ 800.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
SUB- TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBW 1282 B

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURNG STRIP	\$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	
5	REAR LIGHT REFLECTOR-LH/RH	2 \$ 76.00	
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION-LH	\$ 40.00	
9	REAR BUMPER GUIDE SECTION -RH	\$ 41.00	
10	REAR BUMPER UPPER GUIDE SECTION-LH	\$ 20.00	
11	REAR BUMPER UPPER GUIDE SECTION-RH	\$ 20.00	
12	REAR SENSOR	2 \$ 462.00	
13	REAR SENSOR SEAL RING	4 \$ 12.00	
16	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 4,326.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 6,578.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant