

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD /0175/2019/KK
Date : 11-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Stella Pe Peck Luan
Address : 17 Walmer Drive
#12-446
Singapore 555042
Telephone : HP +65 91802639
Type of Claim : Own Damage Claims
Policy No. : 2100406194-03
Vehicle No : **SKR 9815 G**
Model Code : Audi Q7 3.0 TFSI QU
Model / Year : 20/3/2015
Engine No : CJT 213633
Chassis No : WAUZZZ4L1FD001436
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Feb-19
Place of Accident : Khiang Guan Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 9815 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✓	
2	To dismantle and renew lhs front door and lhs rear door. To inspect lhs B-pillar for further damages. Re-organise crash management components. Reinstall all parts removed.	\$ 2,400.00 ✓	1000 1000
3	To respray lhs front door, lhs rear door and door covers. ✓ ✓	\$ 2,900.00 ✓	1500 550 x 2 = 1100 Protector 2 x 200 = 400 <u>1500</u>
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 9815 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - LH <i>Revised</i>	\$ 4,045.00	✓
2	FRONT DOOR ATTACHMENT PARTS ?	\$ 88.00	<i>Not</i> ?
3	FRONT OUTER DOOR SEAL <i>new</i>	\$ 229.00	✓
4	FRONT REINFORCEMENT - LH/RH <i>new</i>	\$ 281.00	+
5	FRONT DOOR INSULATION STRIP ?	\$ 14.00	?
6	REAR DOOR - LH <i>Revised</i>	\$ 4,045.00	✓
7	REAR OUTER DOOR SEAL <i>new</i>	\$ 295.00	✓
8	REAR DOOR ATTACHMENT PARTS ?	\$ 90.00	?
9	SIDE DOOR REINFORCEMENT <i>new</i>	\$ 153.00	+
10	REAR INSULATION STRIP ?	\$ 14.00	?
11	FRONT DOOR COVER PRIMED - LH ? <i>new</i>	\$ 343.00	✓
12	REAR DOOR COVER PRIMED - LH	\$ 405.00	✓
13	DOOR CLIP <i>new</i>	12 \$ 78.00	✓
14	DOOR HINGE <i>new</i>	\$ 203.00	+
15	THREADED PLATE ? <i>new</i>	\$ 9.00	+
16	RETAINING PLATE	\$ 15.00	+
17	DOOR UPPER HINGE - LH <i>new</i>	\$ 138.00	+
18	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 10,945.00	
TOTAL LABOUR CHARGES		\$ 6,052.00	
GRAND TOTAL		\$ 16,997.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *14/02/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant