

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0178/2019/GW
Date	:	12-Feb-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mdm . Cai Yun Zhen @Chua Luan Fong Elsie
Address	:	30 Springleaf Garden Singapore 788190
Telephone	:	HP +65 96473198
Type of Claim	:	Own Damage Claims
Policy No.	:	2100260344-07
Vehicle No	:	SCU 6655 A
Model Code	:	A7 SB 2.8 FSI Qu
Model / Year	:	27/5/2011
Engine No	:	CHV 001545
Chassis No	:	WAUZZZ4G3BN006516
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Feb-19
Place of Accident	:	30 SpringLeaf Garden

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCU 6655 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs headlight, lhs front fender and bonnet. Re-organise front crash management components. Reinstall all parts removed. ✓ ✓	\$ 3,150.00 1750.	
3	To respray front bumper, lhs front fender, hinges and bonnet. ✓ X	\$ 2,800.00 1650.	
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>6,902.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCU 6655 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>schnd</i>	\$ 2,909.00	✓
2	FRONT BUMPER CLOSING ELEMENT	\$ 202.00	✗
3	FRONT BUMPER CLOSING ELEMENT-LH/RH <i>2</i>	\$ 184.00	✗
4	FRONT BUMPER FIXING PARTS	\$ 249.00	✗
5	FRONT BUMPER AIR GUIDE GRILLE	\$ 139.00	?
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>~</i>	\$ 191.00	✗
7	FRONT BUMPER SPOILER <i>new</i>	\$ 227.00	✗
8	RADIATOR GRILLE <i>new</i>	\$ 1,301.00	✗
9	RADIATOR GRILLE INSCRIPTION "QUATTRO" <i>new</i>	\$ 87.00	✗
10	RADIATOR GRILLE COVER <i>3 new</i>	\$ 26.00	✗
11	RADIATOR LICENCE PLATE HOLDER	\$ 390.00	✗
12	FRONT BUMPER GRILLE-LH <i>new</i>	\$ 224.00	✓
13	FRONT BUMPER END CAP-LH <i>new</i>	\$ 53.00	✗
14	FRONT BUMPER SIDE REINFORCEMENT <i>3 new</i>	\$ 754.00	✗
15	FOAM FILLER PIECE	\$ 90.00	✗
16	FRONT BUMPER GUIDE PIECE-LH <i>2 new</i>	\$ 40.00	✓
17	FRONT BUMPER COVER	\$ 116.00	?
18	FRONT BUMPER SENSOR <i>new</i>	\$ 210.00	✗
19	FRONT BUMPER SEAL RING-INNER / OUTER <i>new</i>	\$ 5.00	✗
20	AIR CONDITIONER STICKER <i>Not new ?</i>	\$ 18.00	✗ ?
SUB TOTAL SPARE PARTS CHARGES		\$ 7,415.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCU 6655 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER-LH <i>Dented.</i>	\$ 1,558.00	✓
22	FRONT FENDER ATTACHMENT PARTS-LH ?	\$ 38.00	?
23	FRONT FENDER STONE CHIP GUARD-LH <i>new</i>	\$ 104.00	✓
24	FRONT FENDER BRACE-LH ?	\$ 75.00	?
25	FRONT FENDER SEALING ELEMENT-LH ?	\$ 36.00	?
26	FRONT FENDER SEAL-LH ?	\$ 18.00	?
27	FRONT WHEEL HOUSING LINER-LH <i>new</i>	\$ 256.00	✗
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>new</i>	\$ 72.00	✗
29	FRONT WHEEL SPOILER-LH <i>new</i>	\$ 210.00	✗
30	BONNET <i>Dented</i>	\$ 5,579.00	✓
31	BONNET ATTACHMENT PARTS ?	\$ 130.00	?
32	BONNET LID HINGE-LH ?	\$ 146.00	✗
33	BONNET LID HINGE-RH ?	\$ 146.00	✗
34	BONNET GAS FILLED STRUT <i>not</i>	2 \$ 217.00	✗
35	FRONT EDGE PROTECTION <i>new</i>	\$ 25.00	✗
36	BONNET CATCH HOOK	\$ 127.00	✗
37	BONNET LOCK BAR	\$ 45.00	✗
38	BONNET LOCK LATCH HOOK	\$ 16.00	✗
39	BONNET LOCK COVER	2 \$ 7.00	✗
40	BONNET LID LOCK WITH MICRO SWITCH <i>new new</i>	\$ 196.00	✗
SUB- TOTAL SPARE PARTS CHARGES		\$ 9,001.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCU 6655 A

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
41	BONNET BOWDEN CABLE-CENTER <i>3 1/4</i>	\$	53.00 *
42	BONNET COVER	\$	9.00 *
43	HEADLIGHT MOUNTING-LH ?	\$	107.00 ?
44	HEADLIGHT COVER-LH <i>Del'd</i>	\$	39.00 ✓
45	HEADLIGHT DISCHARGE-LH <i>crack'd</i>	\$	3,257.00 ✓
46	HEADIGHT LIFT CYLINDER-LH ?	\$	216.00 ?
47	FRONT AIR GUIDE-LH <i>seen</i>	\$	35.00 *
48	FRONT NO PLATE <i>not in</i>	S/N \$	25.00 *
49	FRONT RIM - LH <i>seen</i>	S/N	TBC *.
50	SUNDRIES ?	\$	800.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 20,957.00
TOTAL LABOUR CHARGES			\$ 6,902.00
GRAND TOTAL			\$ 27,859.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *14/02/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not Authorised, 06 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant