

22/03/2012

ASS. REC. BY:

REF:

CS/FCI19002834/Dvd372

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Eileen Lee (CWS) of FCI Date/Time: 14/2/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBG 4659M Insured: SHC 8668Kat Workshop m/s SG 98 Motor Tel: 6452 4898of BLC 4001 AWC #01-21Policy No: _____ Claim No: D19000914-MESH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6/2/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FBG 4659M-X</u>
	<u>SHC 8668K - CCH / ASM18000690 / K1wb392 DOA: 6/1/2018</u>
<u>20/2/19</u>	<u>Email preli revised to FCI</u>

REF

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No. _____

at Workshop no. _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value _____

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen _____

Consistent? : Yes or No

Est. Repairs _____

3

days

Res.: Yes or No

Lump Sum _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date _____

Person Contacted _____

Vehicle: IN / OUT

Veh No. FBG 4659M Regn 2012 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CBR 250R E.C. 250

Colour: Red/white A/C Insured / Std / NI / NA

Sp. Reading T/Radio Insured / Std / NI / NA

Eng/No: MC41E2019410

C/No: MLHMC41A02BS002941

Gen. Cond: Good / Fair / Poor / Burnt


Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size: F: 110/70 R17

R: 140/70 R17



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. mm L/Bal. mm

D.O.A. 06/02/2019 D.O.I. 15/02/2019

Survey held at SG 98 Motor AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front O/S Body O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 8668K

21/05/19 Jomful 2/5 2600/- - to 31yrs 7 rev (Red 1476, 369)

RECEIVED 22 MAY 2019

Date/Time: File Pass to:



: Preli. Report

By _____



: Final Report

Date/Time: File Return to:

By _____

22/5- typist

Report Format:

Lump Sum / I.B.L. (\$) CWS 2600p

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) G + PS \$1

) Photos

) Other

TOTAL

Add Fee:



Site Insp (\$) _____



Interview (\$) _____



Tech. Insp (\$) _____



Weekend (\$) _____

135
50
50+50
75
360



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: D19000914MFSH

Our ref: CS/FCI19002834/Dvd3

Date: 14/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FBG 4659M


We thank you for your instruction on 14/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/2/2019 at the premises of M/s SG 98 MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,275.00
Revised Estimate Amount	: S\$2,490.00
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion, o/s rear portion and o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	08-02-2019	Our Ref No. D19000914MFSH
Accident Date	06-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8668K	Third Party Vehicle. FBG4659M
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 0	Fax No. 64526898
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 20 February 2019 3:47 PM
To: 'CWS Motor Claims'
Cc: EileenLee@msfirstcapital.com.sg; SUR
Subject: RE: SURVEY ASSESSMENT - D19000914MFSH/1, FBG 4659M
Attachments: FBG 4659M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBG 4659M
Date of survey: 15/2/2019
Number of days : 3 days

Some of the parts pending for parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 3:42 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19000914MFSH/1

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 14 February 2019 4:23 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000914MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 15 February 2019

To : LKK

By Fax: 6256-4315

Attn :

Tel :

VEHICLE NO : FBG 4659M

Honda CBR 250

ACCIDENT DATE: 6 February 2019

Description	Qty	Quotation \$
1 Front Mudguard <i>crack</i>	1	135.00 ✓
2 Head Light <i>crack</i>	1	250.00 ✓
3 Handle Bar RH <i>1st</i>	1	75.00 ✓
4 Mirror RH <i>broken</i>	1	75.00 ✓
5 Brake Lever <i>cut</i>	1	60.00 ✓
6 Front Head Fairing <i>1st</i>	1	250.00 ✓
7 Front RH Side Fairing <i>broken</i>	1	145.00 ✓
8 Rear RH Tail Panel <i>broken</i>	1	90.00 ✓
9 Leo Vince Exhaust <i>cut 1st</i>	1	1,200.00 ✓
10 Lower Belly Pan Undertray <i>broken</i>	1	135.00 ✓
11 Rear RH Signal <i>broken</i>	1	85.00 ✓
12. <i>Front</i> Rear RH foot rest <i>cut</i>		Sub-Total ✓ 2,500.00
		Less 10% 250.00
13. <i>Rear</i> Exhaust Guard <i>cut</i>		Sub-Total 2,250.00
2nd fork <i>1st</i>		✓

VEHICLE NO : FBG 4659M

Honda CBR 250

Nett items

- 1 Towing fee
- 2 Remove & replace parts, align & etc
- 3 Remove & replace front fork & rim
- 4 Putty & respray paint work & decal sticker

5- Rear number plate cut

450.00

50.00 40/-
300.00 180/-
180.00 150/- 50/-
480.00 180/-

Sub-Total

1,010.00

Nett Total

3,260.00 4076

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

2475.00

847 816.00
3291.00

4/3 2600/-

15/02/2019 @ 1700hrs

HA Andri

2/Srm

3 1/2
2KK Auto

8

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4896 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 20 February 2019

To : LKK

By Fax: 6256-4315

Attn: Mr. Bryan.
Tel :

VEHICLE NO : FBG 4659M
ACCIDENT DATE: 6 February 2019

Honda CBR 250

Supplementary Items

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front RH Footrest Cnt	1	130.00 ✓
2 Exhaust Guard Cnt	1	280.00 ✓
3 Fork Assy damaged 1st	1 set	480.00 ✓
	Sub-Total	890.00
	Less 10%	89.00
	Sub-Total	801.00

Nett items

1 Rear number plate broken	15.00 ✓
	Sub-Total 15.00
	Nett Total 816.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD


LKK Auto



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002834/Dvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8668K	Veh. Inspected	FBG 4659M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D1900914MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CBR250R	c.c	250	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	MLHMC41A0B5002941	Colour	RED / WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	PIRELLI	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	PIRELLI	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT,O/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2019	Inspection Date	15/02/2019	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 4659M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT MUDGUARD	CRACKED	135.00	135.00
1	HEAD LIGHT	MOUNTING CRACKED	250.00	250.00
1	HANDLE BAR RH	BENT	75.00	75.00
1	MIRROR RH	BROKEN	75.00	75.00
1	BRAKE LEVER	CUT	60.00	60.00
1	FRONT HEAD FAIRING	NOT NECESSARY	250.00	-
1	FRONT RH SIDE FAIRING	BROKEN	145.00	145.00
1	REAR RH TAIL PANEL	BROKEN	90.00	90.00
1	LEO VINCE EXHAUST	CUT / BENT	1,200.00	1,200.00
1	LOWER BELLY PAN UNDERTRAY	BROKEN	135.00	135.00
1	REAR RH SIGNAL	BROKEN	85.00	85.00
1	FRONT RH FOOTREST (ADDITIONAL)	CUT	130.00	130.00
1	EXHAUST GUARD (ADDITIONAL)	CUT	280.00	280.00
1	SET FORK ASSY (ADDITIONAL)	DISTORTED / BENT	480.00	480.00
	LESS 10% DISCOUNT		-339.00	-314.00
			3,051.00	2,826.00
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (ADDITIONAL)(SN)	BROKEN	15.00	15.00
			15.00	15.00
LABOUR				
	TOWING FEE.		50.00	40.00
	REMOVE & REPLACE PARTS,ALIGN & ETC.		300.00	180.00
	REMOVE & REPLACE FRONT FORK & RIM.		180.00	50.00
	PUTTY & RESPRAY PAINT WORK & DECAL.		480.00	180.00
			1,010.00	450.00
GRAND TOTAL			4,076.00	3,291.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00



Report Ref No. CS/FCI19002834/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.