

ASS. REC. BY:

REF:

CS/FCI9002835/Dvd3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Marina Chia San San of FCI Date/Time: 14/2/2019

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FD 8068K Insured: SHC913E

at Workshop m/s SG98 Motor Tel: 64524898

of Blk 4001 AMK #01-21

Policy No: Claim No: D19001096MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 23/1/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FD 8068K - X
	SHC 913E - X
22/11/19	Email preli revised to FCI
note:	MV: \$6K (EST) LTA: \$1065 NV: \$4935


Surveyor

ASSIGNMENT

OE Feb 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **FD8068 K** Yr Regn: **April 1985**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Yamaha RXZ** c.c. **133**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **N.A.** T/Radio: Insured / Std / NI / NA
 Eng/No: **55K000713**
 C/No: **55K000713**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: **2.75 - 18**
 R: **3.00 - 18**



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Pirelli**

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **6** days Res.: Yes or No
 Lump Sum: **200** % 3 Val.: Yes or No

Front Rear
 R/Bal. **2** mm R/Bal. **2** mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **23/01/2019** D.O.I. **15/02/2019**
 Survey held at **8698 Motor AMK**

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Portion y o/s Print
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital SHC 913E
	MV 6K
	LIA 1K
	NL 5K

RECEIVED 22 NOV 2019

22/11/19 **Janan HS 3650/- w.t badge from (Reel 2730.50, 4310)**

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) **22/11 - typist**

Days Of Repair: **6**
 Resurvey No. of Trip: **1**

Report Format: **CWS**
 Lump Sum / I.B.I: (\$ **3650/-**)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: **145**
 Transportation: **50**
 S + RS: \$ **50**
 Photos: **64**
 Others: _____
 TOTAL: **309**



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001096MFSH

Our ref: CS/FCI19002835/Dvd3

Date:22/11/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO FD 8068K


We thank you for your instruction on 14/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/2/2019 at the premises of M/s SG 98 MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,380.50
Revised Estimate Amount	: S\$3,650.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s portion and o/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	14-02-2019	Our Ref No. D19001096MFSH
Accident Date	23-01-2019	Claim Type. Third Party
Insured Vehicle	SHC0913E	Third Party Vehicle. FD8068K
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 0	Fax No. 64526898
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 22 November 2019 2:40 PM
To: CWS Motor Claims
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001096MFSH/1-FD 8068K
Attachments: FD 8068K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FD 8068K
Date of survey: 15/2/2019
Number of days (estimated) : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 14 February 2019 4:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001096MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5628A
Vehicle Details	
Vehicle No.:	FD8068K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Black
Manufacturing Year:	1985
Engine No.:	55K000713
Chassis No.:	55K000713
Maximum Power Output:	-
Open Market Value:	\$0.00
Original Registration Date:	02 Apr 1985
First Registration Date:	02 Apr 1985
Transfer Count:	14
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,952.00
COE Rebate Amount:	\$1,065.00
Total Rebate Amount:	\$1,065.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtc incentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 20 Feb 2019

OK

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 February 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FD 8068K

Yamaha RXZ 135

ACCIDENT DATE: 23 January 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front Head Cowling <i>broken</i>	1	235.00 ✓
2 Head Lamp <i>broken</i>	1	295.00 ✓
3 Front Signal <i>broken</i>	2	140.00 ✓
4 Head Lamp Stay <i>bt</i>	1	135.00 ✓
5 Handle Bar <i>broken</i>	2	170.00 ✓
6 Handle Bar Cone Bearing <i>bt</i>	1	95.00 ✓
7 Mirror <i>broken / dislodged</i>	1 set	135.00 ✓
8 Brake Lever <i>NN</i>	1	75.00 X
9 Clutch Lever <i>broken</i>	1	90.00 ✓
10 Clutch Cable <i>tear</i>	1	165.00 ✓
11 Fork Tube <i>bt</i>	1 set	480.00 ✓
12 Fork Under Bracket <i>bt</i>	1	135.00 ✓
13 Front Mudguard <i>broken</i>	1	185.00 ✓
14 Mudguard Bracket <i>bt</i>	1	85.00 ✓
15 Balancer <i>cut</i>	1 set	125.00 ✓
16 Front Rim <i>NN</i>	1	320.00 X
17 Brake Disc <i>NN</i>	1	180.00 X
18 Gear Pedal <i>bt</i>	1	90.00 ✓
19 Rear RH Side Fairing <i>broken</i>	1	160.00 ✓
20 Exhaust Pipe <i>bt</i>	1	560.00 ✓
21 Tail Lamp <i>broken</i>	1	175.00 ✓
22 Seat <i>tear</i>	1	95.00 ✓
23 Rear LH Fairing <i>broken</i>	1	95.00 ✓
24 Rear Tail Cover <i>bt</i>	1	90.00 ✓
25 Rear LH Pillion Footrest Bracket <i>NN</i>	1	95.00 X
26 LH Pillion Footrest <i>bt</i>	1	75.00 ✓
27 Rear Mudguard <i>NN</i>	1	165.00 X
		<i>3810.00</i>
		<i>3429.00</i>
	Sub-Total	4,645.00
	Less 10%	464.50
	Sub-Total	4,180.50

VEHICLE NO : FD 8068K

Yamaha RXZ 135

Nett Items

1 Towing Fee <i>Nec</i>		50.00 30/-
2 Labour to remove & replace parts, align & etc		350.00 200/-
3 Remove & replace fork tube, rim & etc		250.00 80/-
4 Re-align body frame	830.00	450.00 100/-
5 Supply body decal sticker		120.00 80/-
6 Check electrical connection		80.00 30/-
7 To supply necessary oil		60.00 <i>NH</i>
8 Number plate - 1 set <i>1st / Nec</i>		30.00 ✓
9 Rear box <i>broken</i>		280.00 180/-
10 Box rack <i>1st</i>		180.00 100/-

Special Nett Items

1 Meter Assy <i>cut / broken</i>	350.00	350.00 ✓
----------------------------------	--------	----------

Sub-Total 2,200.00

Nett Total 6,380.50

4609.00

L/S 3650/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~ is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

15/02/2014 @ 1730hrs
N/A *Arthur*

2/1 same 6 dgs

[Signature]

LKK Auto

[Signature]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002835/Dvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 913E	Veh. Inspected	FD 8068K
Policy No.		Coverage (\$)	0.00
Claim No.	D19001096MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA RXZ	c.c	133
Engine No.	HIDDEN	Year of Reg.	1985
Chassis No.	55K000713	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	2.75-18	PIRELLI	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-18	PIRELLI	2 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/01/2019	Inspection Date	15/02/2019
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FD 8068K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT HEAD COWLING	BROKEN	235.00	235.00
1	HEAD LAMP	BROKEN	295.00	295.00
2	FRONT SIGNAL	BROKEN	140.00	140.00
1	HEAD LAMP STAY	BENT	135.00	135.00
2	HANDLE BAR	BROKEN	170.00	170.00
1	HANDLE BAR CONE BEARING	BENT	95.00	95.00
1	SET MIRROR	BROKEN / DISLODGE	135.00	135.00
1	BRAKE LEVER	NOT NECESSARY	75.00	-
1	CLUTCH LEVER	BROKEN	90.00	90.00
1	CLUTCH CABLE	TORN	165.00	165.00
1	SET FORK TUBE	BENT	480.00	480.00
1	FORK UNDER BRACKET	BENT	135.00	135.00
1	FRONT MUDGUARD	BROKEN	185.00	185.00
1	MUDGUARD BRACKET	BENT	85.00	85.00
1	SET BALANCER	CUT	125.00	125.00
1	FRONT RIM	NOT NECESSARY	320.00	-
1	BRAKE DISC	NOT NECESSARY	180.00	-
1	GEAR PEDAL	BENT	90.00	90.00
1	REAR RH SIDE FAIRING	BROKEN	160.00	160.00
1	EXHAUST PIPE	BENT	560.00	560.00
1	TAIL LAMP	BROKEN	175.00	175.00
1	SEAT	TORN	95.00	95.00
1	REAR LH FAIRING	BROKEN	95.00	95.00
1	REAR TAIL COVER	BENT	90.00	90.00
1	REAR LH PILLION FOOTREST BRACKET	NOT NECESSARY	95.00	-
1	LH PILLION FOOTREST	BENT	75.00	75.00
1	REAR MUDGUARD	NOT NECESSARY	165.00	-
	LESS 10% DISCOUNT		-464.50	-381.00
			4,180.50	3,429.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	METER ASSY (SN)	CUT / BROKEN	350.00	350.00
1	SET NUMBER PLATE (SN)	BENT / NECESSARY	30.00	30.00
1	REAR BOX (SN)	BROKEN	280.00	180.00
1	BOX RACK (SN)	BENT	180.00	100.00
			840.00	660.00
	LABOUR			
	TOWING FEE.		50.00	30.00
	LABOUR TO REMOVE & REPLACE PARTS,ALIGN & ETC.		350.00	200.00
	REMOVE & REPLACE FORK TUBE,RIM & ETC.		250.00	80.00
	RE-ALIGN BODY FRAME.		450.00	100.00
	SUPPLY BODY DECAL STICKER.		120.00	80.00
	CHECK ELECTRICAL CONNECTION.		80.00	30.00
	TO SUPPLY NECESSARY OIL.	NOT NECESSARY	60.00	-
			1,360.00	520.00
	GRAND TOTAL		6,380.50	4,609.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00

Report Ref No. CS/FCI19002835/Dvd3n2

MARKET VALUE: \$6,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,065.00=NETT VALUE: \$4,935.00

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.