

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 930A

AAD1902-084

Not Authoited

Assurvey By paint

83996.51

Vehicle No.: **SHD 930A**
 Chassis No.: VF1ABL15AUC283360
 Vehicle Make: RENAULT
 Vehicle Model: LATITUDE
 Date of Accident : 12.2.2019
 Third Party Insurer : **III**
 Date of Registration : 3/7/2017

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77	✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	X
1	HEADLAMP RH	\$	<i>Myem</i> 1,184.43	✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
1	FENDER PANEL FRT RH	\$	<i>B1</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84	} X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79	
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84	
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66	
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25	
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11	
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06	
1	RADIATOR GRILL	\$	<i>Sn</i> 1,707.78	
TOTAL		\$	11,824.17	
10%		\$	1,182.42	
		\$	10,641.75	

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i> 12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i> 10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-084

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 930A

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00 X
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nn</i> 50.00 X

\$	157.50
----	--------

TOTAL \$	10,799.25
----------	-----------

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>400l</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>440l</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-084

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 930A

To vacuum, replace, refix and recharge Air
Intercooler

\$ *~* 170.00 X

TOTAL \$ 8,210.00

Over All Total \$ 19,009.25

PART-BY-PART (REPAIR DAY)

~~10 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: