

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5404U**AAD1902-087**

Not Withheld
Recovery B4paint @ 1159.93

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5404U

JTDKB3FU503079145

RENAULT

LATITUDE

12.2.2019

AIG

25/1/2019

PART**LIST**

1	1 FRONT BUMPER	\$	<i>R</i> 499.90 ✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>R</i> 101.20 X
3	1 REINFORCEMENT, FRONT BUMPER	\$	<i>R</i> 696.40 X
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>R</i> 130.20 X
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	<i>R</i> 78.10 X
6	1 FRONT BUMPER SIDE RETAINER RH	\$	<i>R</i> 78.00 X
7	1 FRONT BUMPER SIDE RETAINER LH	\$	<i>R</i> 78.00 X
8	1 FRONT BUMPER SUPPORT	\$	<i>R</i> 81.70 X
9	1 EXTENSION, FRONT BUMPER, RH	\$	<i>R</i> 117.80 X
10	1 EXTENSION, FRONT BUMPER, LH	\$	<i>R</i> 117.80 X
11	1 FRONT LED LAMP (LOWER) RH	\$	<i>R</i> 907.75
12	1 FRONT LED LAMP (LOWER) LH	\$	<i>R</i> 907.75
13	1 FRONT HEADLAMP RH	\$	<i>R</i> 2,909.04
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>R</i> 492.30
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>R</i> 413.10
16	1 FRONT HEADLAMP LH	\$	<i>R</i> 2,909.04
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>R</i> 492.30
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>R</i> 413.10
19	1 FRONT BONNET	\$	<i>R</i> 950.50

\$ 12,373.98

25% \$ 3,093.50

\$ 9,280.49

Special Nett

4 1 FRONT NUMBER PLATE WITH MOULDING

\$ *Rm/ Dc* 200.00 *45sm***TOTAL \$ 200.00**

Trans-cab Auto Services Pte Ltd

AAD1902-087

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5404U

TOTAL PARTS	\$	9,480.49
--------------------	-----------	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00	X

TOTAL	\$	10,400.00
--------------	-----------	------------------

Over All Total	\$	29,160.97
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by insurance company is subject to final approval from insurance company

(PART-BY-PART) Repair Days

Acknowledged by Repairer

Signature:

Date:

3
14 days~~24 days~~