

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 14/02/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKH9259P		
MODEL	: BMW 120I 2.0A	Poh kin	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 8-Feb-19
		TIME	: 23:15HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del</i>	1	\$ 1,688.90	\$ 1,688.90
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 120.00	\$ 240.00
3	FRONT BUMPER LOWER GRILLE <i>cut</i>	1	\$ 158.90	\$ 158.90

TOTAL PRICE \$ 2,087.80

LESS 5% \$ 104.39

SUB TOTAL PRICE \$ 1,983.41

1847.80
1663.02

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP(SET) <i>n</i>	1	\$ 22.00	\$ 22.00

72 TOTAL \$ 72.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 600.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 600.00	200	

3	WIRING CHECK	\$ 30.00	✓	
4	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	✗	

430

TOTAL \$1,480.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,055.41
 TOTAL LABOUR COST : \$ 1,480.00
 TOTAL REPAIR COST : \$ 3,535.41

Adrian King
1/14/02/18
028yr

total: 2165.02
4/S: 1.7K.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: