

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : **SJY 6681U**
 Vehicle Model : **TOYOTA ALTIS**
 Accident Date : **13.02.2019**
 Original Reg Date : **23.09.2010**

Date : **13.02.2019**
 Chassis : **MR053ZEE106181239**
 TP Ins. : **AIG**

ESTIMATE

1	1 pc	Boot Lid		695.00	bt ✓
2	1 pc	Boot Lid Badge		56.00	net ✓
3	1 pc	Boot Lid Emblem (1.6)		52.00	net ✓
4	1 pc	Boot Lid Emblem (ELEGANCE)		52.00	net ✓
5	1 pc	Boot Lid Emblem (COROLLA)		52.00	net ✓
6	1 pc	Boot Lid Emblem (ALTIS)		52.00	net ✓
7	1 pc	Boot Lid Lamp RH		248.20	cut ✓
8	1 pc	Boot Lid Lamp Inner Sealer RH		38.00	X
9	1 set	Boot Lid Lamp Clips		25.00	X
10	4 pcs	Boot Lid Stopper	18.00	72.00	X
11	1 pc	Boot Lid Inner Lock		169.50	bt ✓
12	1 pc	Boot Lid Lock Catch		46.00	RY ✓
13	1 pc	Boot Lid Weatherstrip		190.00	cut ✓
14	1 pc	Rear Bumper		582.50	net ✓
15	2 pcs	Rear Bumper Side Retainers	70.00	140.00	net ✓
16	2 pcs	Rear Bumper Attachment Retainers	90.00	180.00	X RH net ✓
17	1 pc	Rear Bumper Reinforcement with Sponge		185.50	cut ✓
18	2 pcs	Rear Bumper Reinforcement Bracket	95.00	190.00	RY ✓
19	1 set	Rear Bumper Clips		30.50.00	net ✓
20	1 pc	Rear Bumper Reflectors RH		62.00	X
21	1 pc	End Panel		656.00	bt ✓
22	1 pc	End Panel Top Trim		210.00	net ✓
23	1 set	End Panel Top Trim Clips		30.00	net ✓
24	1 pc	Spare Tyre Panel Top Board with Cloth		395.20	X
25	1 pc	Taillamps RM		435.00	cut ✓
26	1 pc	Taillamps Inner Sealer		38.00	X
27	1 set	Taillamp Clips		25.00	net ✓
28	1 pc	Taillamps Bottom Retainers		70.00	X
29	1 pc	Rear Fender Inner Trims		335.00	X
30	1 set	Rear Fender Inner Trims Clips		30.00	X

C/F

5,361.90

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SJY 6681U

B/F

5,361.90

1	1 pc	Rear Exhaust Silencer		955.00	X
2	2 pcs	Rear Exhaust Mountings	38.00	76.00	X
3	1 pc	Rear Exhaust Gasket		46.00	X
4	1 pc	Rear Exhaust Heat Plate		167.30	X
				6,606.20	
				Less 25%	1,651.55
					4,954.65

Special Nett

1	1 pc	Rear Number Plate with Cover		70.00	X
2	1 set	Reverse Sensor		250.00	200nw ✓
3	1 pc	Body Panel Joint Sealer		120.00	40

Labour charge

Panel Beating		1,200.00	700
Spray painting		1,200.00	700
Check Wiring		40.00	30.
Anti rust		100.00	30.
Remove and install carpet and seat.		120.00	60
Remove and install reverse sensor		90.00	30.
Remove and install rear exhaust silencer.		120.00	X
		8,264.65	
		Less 20%	1,652.93
		Lump sum	6,611.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
"wp"

15/2/19 @ 1220

Resurvey after repair.

Sur @ Khantow.com

5 days

lump sum