



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 15.02.2019

India International Insurance Pte Ltd  
64 Cecil Street #04/#05  
IOB Building  
Singapore 049711

Attn: Motor Claims Dept

## RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2312X TOYOTA AXIO HYBRID (2016)

### To Supply

1 ) 1pc	Rear bumper <i>DE</i>	\$	700.00
2 ) 1set	Rear bumper clip <i>NE</i>	\$	30.00
3 ) 1pc	Rear bumper right side retainer <i>NE</i>	\$	60.00
4 ) 1pc	Rear bumper right bracket <i>NE</i>	\$	70.00
5 ) 1pc	Rear boot lid <i>PT</i>	\$	680.00
6 ) 1pc	Rear boot lid "corolla" emblem <i>PT</i>	\$	59.60
7 ) 1pc	Rear boot lid "Axio" emblem <i>NE</i>	\$	48.60
8 ) 1pc	Rear boot lid "Hybrid Synergy Drive" emblem <i>NEC</i>	\$	61.70
9 ) 1pc	Rear boot lid "Toyota" emblem <i>NE</i>	\$	60.00
10 ) 1pc	Rear boot lid weatherstrip <i>NE</i>	\$	120.00
11 ) 1pc	Rear end panel <i>PT</i>	\$	380.00
12 ) 1pc	Rear end panel top garnish <i>DE</i>	\$	180.00
13 ) 1set	Rear end panel top garnish clip <i>NE</i>	\$	30.00
14 ) 1pc	Right tail lamp <i>PRO</i>	\$	450.00
15 ) 1pc	Right tail lamp panel <i>PT</i>	\$	285.60
16 ) 1pc	Left tail lamp ?	\$	450.00
17 ) 1pc	Rear floor panel <i>repair</i>	\$	1,187.00

Sub total Parts	\$	4,852.50
Less: 25% discount	\$	1,213.12
	\$	3,639.38

### To Supply S.Nett Parts

1 ) 1pc	"Dial -A-Cab" sticker	\$	45.00 <i>NE</i>
2 ) 1pc	"Prime Taxi" sticker	\$	55.00 <i>NE</i>

- |         |                        |    |       |       |
|---------|------------------------|----|-------|-------|
| 3 ) 1pc | Anti slip mat          | \$ | 50.00 | NA ✓  |
| 4 ) 1pc | Rear license plate no. | \$ | 38.00 | CEA ✓ |

Sub total S.Nett Parts \$ 188.00

L/charges

- |     |  |    |                     |     |
|-----|--|----|---------------------|-----|
| 1 ) | To tuff kote   | \$ | <del>100.00</del>   | 60  |
| 2 ) | To remove rear boot lid trim board & mechanism parts   | \$ | 50.00               | ✓   |
| 3 ) | To remove rear bumper, cut/welding rear end panel & floor panel, replace rear boot lid, rear bumper, right & left tail lamp. Align rear boot lid & rear bumper | \$ | <del>1,000.00</del> | 800 |
| 4 ) | To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel & floor panel. To polish   | \$ | <del>1,000.00</del> | 850 |

Sub total L/charges \$ 2,150.00  
 Estimated Grand Total \$ 5,977.38

*Repar*  
 Hp 90010068  
 8 days  
 L/S  
 15/02/19 @ 1535  
 Respy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: