

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : FWD DATE : 13-Feb-19
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SJP5173Z
MODEL : HYUNDAI AVANTE 1.6A
CHASSIS NO

KMH0U41BR94718728.

Asher

ACCIDENT DETAILS DATE : 8-Feb-19
TIME : 17:40HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Replaced</i>	1	\$ 688.50	\$ 688.50 489
2	REAR BUMPER RETAINER <i>New</i>	2	\$ 52.60	\$ 105.20 70.

559
447.20

TOTAL PRICE \$ 793.70
LESS 20% \$ 158.74
SUB TOTAL PRICE \$ 634.96

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>re</i>	1	\$ 25.00	\$ 25.00
2	REVERSE SENSOR <i>Payd</i>	1	\$ 220.00	\$ 220.00 200

225

TOTAL \$ 245.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 400.00	<i>200</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 400.00	<i>200</i>	
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	<i>50</i>	

450.

TOTAL

\$950.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 879.96
TOTAL LABOUR COST : \$ 950.00
TOTAL REPAIR COST : \$ 1,829.96

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj
L/S 14/02/19
L/S: \$700.
032yr
Told 11/22/20
L/S: 700
(Nett
Value)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: