

AIG INSURANCE

Vehicle number	PC9396T
Make / Model	TOYOTA HIACE
Chassis number	KDH2230033343
Accident date	01 Feb 2019
Reference	1902-11

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER <i>ne</i>	799.34
1	FRONT BUMPER BRACKET <i>?</i>	211.20
1	FRONT REINFORCEMENT <i>?</i>	563.97
1	FRONT BUMPER RH RETAINER <i>ne</i>	98.60
1	FRONT RH HEADLAMP <i>SC</i>	1090.30
1	FRONT RH CORNER PANEL <i>X</i>	101.30
1	FRONT RH FOG LAMP <i>X</i>	468.10
1	FRONT RH FOG LAMP COVER <i>?</i>	168.00
1	FRONT GRILLE <i>SC</i>	410.80
1	FRONT SUPPORT PANEL <i>X</i>	680.50
1	FRONT RH DOOR PANEL <i>repair</i>	1090.30
1	FRONT RH STEP GARNISH <i>cut</i>	1820.80
		7503.21
Less 25 %		1874.80
Subtotal		5627.41
Balance C/F		5627.41
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		5627.41
1 SET	FRONT BUMPER CLIP <i>ne</i>	40.00
1 BOT	BRAKE FUILD <i>X</i>	50.00
1 BOT	COOLANT <i>X</i>	50.00
Subtotal		140.00
Balance C/F		5767.41
LABOUR AND MISCELLANEOUS CHARGES		
Balance B/F		5767.41
1	CHECK FRONT LIGHTNING AND WIRING SYSTEM	60.00 30
2	TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO N	200.00 60
3	PANEL BEATING ON AFFECTED AREAS	800.00 400
4	SPRAY PAINTING ON AFFECTED AREAS	800.00 500
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		2010.00
Grand total		7777.41

Rasul
Hp 90010068
4 days
4/5
02/05/19 @ 1410
Repair after repair