



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/02/2019

Attn: The Motor Claims Department
Your Insured veh no : GBA 5793 H
Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Towers
Singapore 189702

TP Lon Pac.
Joy

WITHOUT PREJUDICE

LKK

(By Email Only)

96893735

Dear Sir / Madam

fiona.shen@income.com.sg
MT/0948951-001

JN1MC2E2620006250

Estimate Repair Cost To Nissan NV 350 GBF 132 Y & GBA 5793 H on 09/02/2019 @07:35:00

To Supply :-

1pc	Rear windscreen glass	Shattered		\$ 837.00	nett ✓
2pcs	Rear bumper side bracket	rec	\$10.40	\$ 20.80	nett ✓
2pcs	Rear lamp LH	cut		\$ 416.00	nett ✓
1pc	Rear boot cover windscreen seal			\$ 55.00	nett ✓
1pc	Rear boot cover "Nissan " emblem			\$ 55.00	nett ✓
1pc	Rear boot cover "NV350" plate			\$ 89.00	nett ✓
1pc	Rear boot cover "UR VAN" plate			\$ 55.00	nett ✓
1pc	Rear boot cover 70km/h striket			\$ 24.00	nett ✓ 15(SN)
1pc	Rear boot cover rubber	cut		\$ 128.00	nett ✓
1pc	Rear boot cover inner lock	Jammed		\$ 228.10	nett ✓
1pc	Rear boot cover 8pax	rec		\$ 24.00	nett ✓ 15(SN)
1set	Reverse sensor	Damaged	2831-80	\$ 350.00	nett ✓ 200(SN)
1pc	Rear windscreen sealant	rec		\$ 40.00	nett ✓
1pc	Rear number plate chorme moulding	cut	2548-62	\$ 511.40	nett ✓ 370.90
1pc	Rear boot cover top brake lamp	cracked		\$237.00	nett ✓
1pc	Rear boot cover LH top mirror	cut	S.N. 230	\$225.00	nett ✓
1pc	Rear boot cover wiper arm	cut		\$75.00	nett ✓
				\$ 3,370.30	
			less	10%	\$ 337.03
					\$ 3,033.27



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/02/2019

Attn: The Motor Claims Department
Your Insured veh no : GBA 5793 H
Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Towers
Singapore 189702

WITHOUT PREJUDICE

(By Email Only)

fiona.shen@income.com.sg
MT/0948951-001

Dear Sir / Madam

Page .2

Estimate Repair Cost To Nissan NV 350 GBF 132 Y & GBA 5793 H on 09/02/2019 @07:35:00

To Supply :-			\$ 3,033.27
1pc	Rear boot cover	<i>Painted</i>	<i>3179.20</i> \$ 2,731.60 ✓ <i>2101.40</i>
1pc	Rear panel outter	<i>Beated</i>	\$ 168.60 ✓
1pc	Rear panel inner	<i>Repair</i>	\$ 461.60 ✓
1pc	Rear bumper	<i>Beated</i>	\$ 227.70 ✓ <i>690.60</i>
8pcs	Rear bumper clips	<i>~</i>	\$ 40.00 ✓
1pc	Rear bumper reinforcement	<i>Beated</i>	\$ 178.60 ✓
			\$ 4,308.10
		Less 30%	\$ 1,292.43
			\$ 3,015.67
1pc	Rear number plate	<i>lit</i>	<i>30</i> \$ 55.00 <i>S/nett</i> <i>30(SW)</i>
To dismanlte & replace damage parts,panel beat where necessaey.			\$ 950.00 <i>800</i>
To putty,apply primer & spray paint on the affecte portion.		<i>1700</i>	\$ 1,000.00 <i>700</i>
To remove reverse sensor.			\$ 80.00 <i>50</i>
Labour charge to move and refix windscreen			\$ 120.00 ✓
To check wiring functions.			\$ 60.00 <i>30</i>
			\$8,313.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 6734.06
A/S: 5350
Admining
4/5 14/02/19.
06 Days

5350