

Surveyor: UMP DOI: 14/12/19 Date/Time: 14/12/19 Registered in Merimen: -

Pre-assign / CCU / FTE



Insured Vehicle No.: 6BA 5793H  
Name of Insured: Technowest pte  
Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A: 9/2/19  
Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_


Claim No.: 18/19/19/V05/02142  
Policy No.: \_\_\_\_\_  
Make / Model : \_\_\_\_\_  
Place of Accident : \_\_\_\_\_

If NO, Driver Name / Age: \_\_\_\_\_ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
Driver Tel No.: \_\_\_\_\_ (VL: YES / NO) Insured Liability: % Final ? Yes / No

6BF 1324



INSRS: \_\_\_\_\_  
WSP: Kai Motor  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
<u>19/13</u> <u>507</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
<u>08/07/19</u>	Authorisation To Act:	<input checked="" type="checkbox"/>
<u>13/08/19</u>	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
<u>15/08/19</u>	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 02/07/19 Sent By: 507

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: L19 S\$ 5,530.00 ( 6 days) Reduction: 35 % Email  Call

FINAL SETTLEMENT Date/Time: 21/10/19 Confirm with: MS KIM Email  Call   
Final Liability: % 100 (Assessed / Assessed) BOLA S/N No.: 27  
Repair Cost: (w/acc) S\$ 5,724.50 If NO or B 28, Ass. Lia: COLD REPAIR-BANDD TP

Loss of Rental (LOR): S\$ 800.00 ( 8 days) X @ 100.00  
Loss of Use (LOU): S\$ - ( \$ x days)  
Loss of Income (LOI): S\$ - ( \$ x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]  
GIA/LTA Search S\$ 7.45

Medical: S\$ -  
Disbursement: S\$ - (e.g. Tow/ Independent )  
Legal Cost S\$ -

Total: S\$ 6,531.95 Global Sum S\$: 6,530.00  
1) Claim status: Normal/Reject/Private Settle  
2) Report Format:  
3) Survey fee: \$ 450.00

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: S\$ 6,530.00 Name 1: KAI MOTOR TRADING  
Payee 2: (Strike if N.A.) S\$ - Name 2: -  
Payee 3: (Strike if N.A.) S\$ - Name 3: -

COPY SENT 21/10/19

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBF132Y Yr Regn: 2016 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 c.c. 2788

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 110255 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1MC2E26Z0006250

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 4/02/19

Survey held at Kaiwlor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Lon Pac.

Lg \$5,350.00  
CRSB: \$2,963.94 (35%)

MV:

PV:

Nett:

5277H

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

- 1) \_\_\_\_\_
- 3) \_\_\_\_\_
- 5) \_\_\_\_\_
- Prel. Report: \_\_\_\_\_
- Final Report: \_\_\_\_\_

- 2) \_\_\_\_\_
- 4) \_\_\_\_\_
- 6) \_\_\_\_\_

IN | OUT

Basic & Add. \_\_\_\_\_  
 S + RS, SI \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_


## Joy Irene (LKKAuto)

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Tuesday, 2 July 2019 6:33 PM  
**To:** ONG LI LI; Mei Kwan (LKKAuto); MT\_Claim\_SG  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving GBA5793H (OI : LPC - 18/19/19/VC05/021412) AND GBF132Y (TP : LKK REF - CC6/LPC19002861/Aja3) on 09/02/2019 [External General]  
**Attachments:** PA - GBF132Y.pdf; GBF 132Y MARKED ESTIMATE.pdf

REF: 18/19/19/VC05/021412

Dear Li Li,

We attach herewith our PA and marked estimate for your records.

We will be requesting for mandate shortly.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

**From:** ONG LI LI [mailto:[llong@lonpac.com](mailto:llong@lonpac.com)]  
**Sent:** Monday, 18 March 2019 11:04 AM  
**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Cc:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: Direct Settlement - Accident Involving GBA5793H (OI : LPC - 18/19/19/VC05/021412) AND GBF132Y (TP : LKK REF - CC6/LPC19002861/Aja3) on 09/02/2019 [External General]

## Lonpac External - General

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



# 凱摩哆服務

## KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.  
 TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com  
 BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/02/2019

Attn: The Motor Claims Department  
 Your Insured veh no : GBA 5793 H  
 Lonpac Insurance Bhd  
 100 Beach Road  
 #19-00 Shaw Towers  
 Singapore 189702

TR Lon Pac.  
 Joy.

WITHOUT PREJUDICE

LKK

(By Email Only)

96893735

fiona.shen@income.com.sg  
 MT/0948951-001

JN1MC2E2620006250

Dear Sir / Madam

Estimate Repair Cost To Nissan NV 350 GBF 132 Y & GBA 5793 H on 09/02/2019 @07:35:00

To Supply :-

1pc	Rear windscreen glass	Shattered		\$	837.00	nett ✓
2pcs	Rear bumper side bracket	new	\$10.40	\$	20.80	nett ✓
2pcs	Rear lamp LH	cut		\$	416.00	nett ✓
1pc	Rear boot cover windscreen seal			\$	55.00	nett ✓
1pc	Rear boot cover "Nissan" emblem			\$	55.00	nett ✓
1pc	Rear boot cover "NV350" plate			\$	89.00	nett ✓
1pc	Rear boot cover "UR VAN" plate			\$	55.00	nett ✓
1pc	Rear boot cover 70km/h strike			\$	24.00	nett 15(SN)
1pc	Rear boot cover rubber	cut		\$	128.00	nett ✓
1pc	Rear boot cover inner lock	Jammed		\$	228.10	nett ✓
1pc	Rear boot cover 8pax	new		\$	24.00	nett 15(SN)
1set	Reverse sensor	changed	2831.80	\$	350.00	nett 20(SN)
1pc	Rear windscreen sealant	new		\$	40.00	nett ✓
1pc	Rear number plate chorme moulding	cut	2548.62	\$	511.40	nett → 370.50
1pc	Rear boot cover top brake lamp	checked		\$	237.00	nett ✓
1pc	Rear boot cover LH top mirror	cut	S/N 230	\$	225.00	nett ✓
1pc	Rear boot cover wiper arm	cut		\$	75.00	nett ✓
				\$	3,370.30	
			less	10%	\$ 337.03	
					\$ 3,033.27	



# 凱摩哆服務

## KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.  
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com  
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/02/2019

Attn: The Motor Claims Department  
Your Insured veh no : GBA 5793 H  
Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Towers  
Singapore 189702

WITHOUT PREJUDICE

(By Email Only)

fiona.shen@income.com.sg  
MT/0948951-001

Dear Sir / Madam

Page .2

Estimate Repair Cost To Nissan NV 350 GBF 132 Y & GBA 5793 H on 09/02/2019 @07:35:00

To Supply :-

			\$ 3,033.27
1pc	Rear boot cover <i>Painted</i>	3179.20	\$ 2,731.60 ✓ 2101.40
1pc	Rear panel outer <i>Painted</i>		\$ 168.60 ✓
1pc	Rear panel inner <i>Repair</i>	2225.44	\$ 461.60 ✓
1pc	Rear bumper <i>Replaced</i>		\$ 727.70 ✓ 690.60
8pcs	Rear bumper clips	\$5.00	\$ 40.00 ✓
1pc	Rear bumper reinforcement <i>Set</i>		\$ 178.60 ✓
			\$ 4,308.10
	Less	30%	\$ 1,292.43
			\$ 3,015.67

1pc Rear number plate *lt*

30  
\$ 55.00 s/nett 30 (sw)

- To dismantle & replace damage parts, panel beat where necessary.
- To putty, apply primer & spray paint on the affected portion.
- To remove reverse sensor.
- Labour charge to move and refix windscreen
- To check wiring functions.

1700  
\$ 950.00 800  
\$ 1,000.00 700  
\$ 80.00 50  
\$ 120.00 ✓  
\$ 60.00 30  
\$ 8,313.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Total: 6734.06  
A/S: 5350  
Adrian Ling  
4/5 14/02/19.  
06 Days

5350

## Mei Kwan (LKKAuto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 18 March 2019 11:04 AM  
**To:** Mei Kwan (LKKAuto); MT\_Claim\_SG  
**Cc:** Joy Irene (LKKAuto); CS A Team; Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBA5793H (OI: LPC - 18/19/19/VC05/021417) AND GBE132Y (TP: LKK REF - CC6/LPC19002861/Aja3) on 09/02/2019 [External:General]  
**Attachments:** GBA5793H 090219.PDF  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** FIMK

## Lonpac External - General

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6250 7385



*Lonpac External - General data is for internal / external use.*

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 18 March 2019 2:07 PM  
**To:** MT\_Claim\_SG  
**Cc:** ONG LI LI; GERALDINE WEE; Joy Irene (LKKAuto); CS A Team; Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBA5793H (OI: LPC - 18/19/19/VC05/021417) AND GBE132Y (TP: LKK REF - CC6/LPC19002861/Aja3) on 09/02/2019 [External:General]

Good afternoon,

Thank you for the email.

Dear Sir/Madam,

We refer to the above matter.

This is a direct settlement case.

We have reviewed the documents and we are satisfied with the settlement offer.

Kind regards,  
Ong Li Li

Please refer to the attached estimated costs for your records ready yet.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19002861/Aha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-10-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 5793H	Veh. Inspected	GBF 132Y
Policy No.	Z18VC05000497	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021412	Excess (\$)	0.00
Assign From		Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1MC2E26Z0006250	Colour	GREY
Odometer	110255	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2019	Inspection Date	14/02/2019
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 132Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT COVER	DENTED	2,731.60	2,101.40
1	REAR PANEL OUTER	DENTED	168.60	168.60
1	REAR PANEL INNER	TO REPAIR SEE LABOUR	461.60	-
1	REAR BUMPER	DEFORMED	727.70	690.60
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR BUMPER REINFORCEMENT	BENT	178.60	178.60
	LESS 30% DISCOUNT		-1,292.43	-953.76
			3,015.67	2,225.44
<b>NETT ITEMS</b>				
1	REAR WINDSCREEN GLASS (N)	SHATTERED	837.00	837.00
2	REAR BUMPER SIDE BRACKET @\$10.40 (N)	NECESSARY	20.80	20.80
2	REAR LAMP LH (N)	CUT	416.00	416.00
1	REAR BOOT COVER WINDSCREEN SEAL (N)	NECESSARY	55.00	55.00
1	REAR BOOT COVER "NISSAN" EMBLEM (N)	NECESSARY	55.00	55.00
1	REAR BOOT COVER "NV350" PLATE (N)	NECESSARY	89.00	89.00
1	REAR BOOT COVER "URVAN" PLATE (N)	NECESSARY	55.00	55.00
1	REAR BOOT COVER RUBBER (N)	CUT	128.00	128.00
1	REAR BOOT COVER INNER LOCK (N)	JAMMED	228.10	228.10
1	REAR WINDSCREEN SEALANT (N)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE CHROME MOULDING (N)	CUT	511.40	370.90
1	REAR BOOT COVER TOP BRAKE LAMP (N)	CRACKED	237.00	237.00
1	REAR BOOT COVER LH TOP MIRROR (N)	CUT	225.00	225.00
1	REAR BOOT COVER WIPER ARM (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-297.23	-283.18
			2,675.07	2,548.62
1	REAR BOOT COVER "70KM/H STRIKE (SN)	NECESSARY	24.00	15.00
1	REAR BOOT COVER 8 PAX (SN)	NECESSARY	24.00	15.00
1	SET REVERSE SENSOR (SN)	DAMAGED	350.00	200.00

Report Ref No. CC4/LPC19002861/Aha3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-39.80	-
			358.20	230.00
	<b>SPECIAL NETT ITEMS</b>			
1	REAR NUMBER PLATE (SN)	CUT	55.00	30.00
			55.00	30.00
	<b>LABOUR</b>			
	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF REAR PANEL INNER.		950.00	800.00
	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		1,000.00	700.00
	TO REMOVE REVERSE SENSOR.		80.00	50.00
	LABOUR CHARGE TO MOVE AND REFIX WINDSCREEN.		120.00	120.00
	TO CHECK WIRING FUNCTIONS.		60.00	30.00
			2,210.00	1,700.00
	<b>GRAND TOTAL</b>		<b>8,313.94</b>	<b>6,734.06</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,350.00</b>

Report Ref No. CC4/LPC19002861/Aha3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.