

INSURANCE CASE OWNER: Reker | CC AXA 1900 1867, Ebbw Vale LKK: IDAC:

Surveyor: STEVE DOI: ASSIGNMENT 18/1/19 Date / Time: 15/1/19
Registered in Meritum: _____

Pre-assign / CCU / FTE
 Insured Vehicle No.: SFM 6650U Claim No.: S9M0104x/98803
 Name of Insured: VOONLY MART LILANDI Policy No.: G204164/1
 Insured Tel No.: _____ HP: _____ Make / Model: Honda
 Excess Sec II :SS _____ D.O.A: 14/1/19 Place of Accident: HEMPT. AVE 6
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (VA: YES / NO) Insured Liability: % Final ? Yes / No

SJ7 7825F → → → →
 INSRs: WSP: Tel: Liability: RMKS: SUP MOTORING
 INSRs: WSP: Tel: Liability: RMKS: _____
 INSRs: WSP: Tel: Liability: RMKS: _____
 INSRs: WSP: Tel: Liability: RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>SJ7 7825F</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: <u>EMAIL 11.3.19</u>	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	FIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: CT
 Repair Cost: £ 3,350.00 (5 days) Reduction: 5% % Email Call

FINAL SETTLEMENT Date/Time: 09-04-19 Confirm with: SJDF Email Call
 Final Liability: %100 (Agreed / Assessed) BOLA S/N No.: 21 If NO or B 28, Ass. Lia:
 Repair Cost: SS 3,350.00 (1) RESAR ENDED TP
 Loss of Rental (LOR): SS 250.00 (5 days) x 4100
 Loss of Use (LOU): SS - (5 x days)
 Loss of Income (LOI): SS - (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: SS -
 Medical: SS -
 Disbursement: SS - (e.g. Tow/Independent)
 Legal Cost: SS -
 Total: SS 4,050.00 Global Sum SS:
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: *350

FINAL PAYMENT Date/Time: 09-04-19 Confirm with: SJDF Email Call
 Payee 1: SS 4,050.00 Name 1: SUP MOTORING SERVICES
 Payee 2: (Strike if N.A.) SS Name 2: _____
 Payee 3: (Strike if N.A.) SS Name 3: _____

COPIES SENT
10/4/19

Steve 18/2/19 12pm
 L/S with Justice
 Ring All sp4 to Dismantle
 5 days

Steve Chong L.R.A. No. 1277
 8322 8813

SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593
 HP 91004390/HP 91254449 Fax 64841482
 Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	18.02.2019
No 8 Shenton Way #27-02 AXA Tower	CAR NO	SJZ 7825 K
S068811 Tel 63387288 Fax 68804838	MAKE	Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
<u>Recommended Parts</u>				
1	pcs	Rear boot lid / DO	Nett	\$595.00 / 510 n
1	pcs	Rear boot lid Mitsubishi logo emblem / NEC	Nett	\$46.00 /
1	pcs	Rear boot lid 'Lancer' emblem / NEC	Nett	\$25.00 /
1	pcs	Rear boot lid 'MR' emblem / NEC	Nett	\$24.00 /
1	pcs	Rear boot lid top lock / IST	Nett	\$65.00 / 48 n
1	pcs	Rear boot lid lower lock x NAI	Nett	\$50.00 x
2	pcs	Rear boot lid number plate lamp x NAI	Nett	\$26.00 x \$52.00 x
1	pcs	Rear boot lid number plate garnish / CFA	Nett	\$197.00 / 141 n
2	pcs	Rear boot lid number plate lamp x RPT	Nett	\$26.00 x \$52.00 x
1	pcs	Rear boot lid weatherstrip / CR4	Nett	\$139.00 /
1	pcs	Rear bumper / DO	Nett	\$681.00 / 535 n
2	pcs	Rear bumper bracket @ LH / RH / BR	Nett	\$34.00 \$68.00 /
1	set	Rear bumper reverse sensor / BR	Nett	300 n \$350.00 / 700 n
1	pcs	Rear bumper reinforcement @ / IST	Nett	\$175.00 /
10	pcs	Rear bumper clips / NEC	Nett	\$5.00 30 n \$50.00 / 30 n
1	pcs	Rear bumper lower lip @ / BR	Nett	\$764.00 / 528 n
1/2	pcs	Tail lamp (left & right) 2 @ / RH @ / BR	Nett	\$379.00 \$794.00 / 379 n
1	pcs	Rear end panel @ / DO	Nett	\$141.00 /
1	pcs	Rear end panel top garnish / CUT	Nett	\$175.00 /
1	pcs	Spare tyre tank panel x R	Nett	876.00 x
				3164
				- 10%
				2847.60
			Total	


 SLP MOTORING SERVICES.

SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593
 HP 91004390/HP 91254449 Fax 64841482
 Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd DATE 18.02.2019
 No 8 Shenton Way #27-02 AXA Tower CAR NO SJZ 7825 K
 S068811 Tel 63387288 Fax 68804838 MAKE Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
		Continue from page one.		\$4,443.00
		To provide labour, workmanship to re-align, straightening rear two side mudguard, cutting rear end panel, dismantle & replace the above mentioned parts. <i>750 600/-</i>		\$1,300.00
		Labour for respray rear bumper, rear end panel, rear boot lid cover & rear two side mudguard. <i>150 750 6000/-</i>		\$1,200.00
		To install rear bumper sensor to new bumper include testing for functions. <i>20/-</i>		\$80.00
		Rust-proofing on the front accident affected portions. <i>50/-</i>		\$180.00
		<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>		
			Total	\$7,203.00

1570

flor

SLP MOTORING SERVICES.

Page 2 of 2

*L/S 3534.08
 = 3550*

SLP - Susan

*5 days
 27/2/19 4:30pm*

Steve 18/2/19 12pm
 L/S with Mr. Adite
 Rngy Aff spm & Dismantle
 5 at days

STEVE CHONG L.A.N. AMU 'L' 199
 8322 8813

SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593
 HP 91004390/HP 91254449 Fax 64841482
 Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	18.02.2019
No 8 Shenton Way #27-02 AXA Tower	CAR NO	SJZ 7825 K
S068811 Tel 63387288 Fax 68804838	MAKE	Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
<u>Recommended Parts</u>				
1	pcs	Rear boot lid / DO	Nett	\$595.00
1	pcs	Rear boot lid Mitsubishi logo emblem / NEC	Nett	\$46.00
1	pcs	Rear boot lid 'Lancer' emblem / NEC	Nett	\$25.00
1	pcs	Rear boot lid 'MR' emblem / NEC	Nett	\$24.00
1	pcs	Rear boot lid top lock / ST	Nett	\$65.00
1	pcs	Rear boot lid lower lock X NN	Nett	\$50.00
2	pcs	Rear boot lid number plate lamp X NN	Nett	\$26.00 \$52.00
1	pcs	Rear boot lid number plate garnish / CRA	Nett	\$197.00
2	pcs	Rear boot lid number plate lamp X RPT	Nett	\$26.00 \$52.00
1	pcs	Rear boot lid weatherstrip / CRA	Nett	\$139.00
1	pcs	Rear bumper / DO	Nett	\$681.00
2	pcs	Rear bumper bracket @ LH / RH / BR	Nett	\$34.00 \$68.00
1	set	Rear bumper reverse sensor / BR	Nett	2001/ \$350.00
1	pcs	Rear bumper reinforcement ? / ST	Nett	\$175.00
10	pcs	Rear bumper clips / NEC	Nett	\$5.00 30/ \$50.00
1	pcs	Rear bumper lower lip ? ✓ BR	Nett	\$764.00
1/2	pcs	Tail lamp (left & right) LH X RH ? ✓ BR	Nett	\$379.00 \$794.00
1	pcs	Rear end panel ? ✓ DO	Nett	\$141.00
1	pcs	Rear end panel top garnish / CUT	Nett	\$175.00
1	pcs	Spare tyre tank panel X R	Nett	2876.00



SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	18.02.2019
No 8 Shenton Way #27-02 AXA Tower	CAR NO	SJZ 7825 K
S068811 Tel 63387288 Fax 68804838	MAKE	Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
		Continue from page one.		\$4,443.00
		To provide labour, workmanship to re-align, straightening rear two side mudguard, cutting rear end panel, dismantle & replace the above mentioned parts. <i>750</i>	<i>600/-</i>	\$1,300.00
		Labour for respray rear bumper, rear end panel, rear boot lid cover & rear two side mudguard. <i>150</i>	<i>750/-</i> <i>600/-</i>	\$1,200.00
		To install rear bumper sensor to new bumper include testing for functions.	<i>20/-</i>	\$80.00
		Rust-proofing on the front accident affected portions.	<i>50/-</i>	\$180.00
<div data-bbox="404 1435 921 1861" data-label="Text" style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
			Total	\$7,203.00

◀ MANDATE IA (S9M01DYX)

Type

🔔 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$3,550.00 Loss of Rental: \$500.00 (5days x \$100) Total: \$4,050.00 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (11/03/2019)

Reply



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

LOR is subject to rental receipt proof.

Reply

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email:slpmotoring@gmail.com

(A)

27.02.2019.

Our Ref : SJZ 7825 K ✓

Your Ref : SFM 6650 U ✓

Rico Engineering Works Pte Ltd
C/o SLP Motoring Services

Attn: Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Dear Sir/Mdm,

RE: ACCIDENT INVOLVING SJZ 7825 K & SFM 6650 U ON 14.02.2019.

We are repairer of vehicle no. SJZ 7825 K which was involved in an accident with vehicle no. SFM 6650 U which is insured with you.

The accident was clearly caused by your insured's negligence. We are therefore seeking compensation from you for our client's financial losses as itemized below:-

Cost of Repair				\$3,550.00
Rental Fee	5	Days	\$120.00	\$600.00
Total				<u>\$4,150.00</u>


We enclose copies of the relevant documents to support our claim.

Your prompt settlement of our claim would be much appreciated.

You may contact Susan (HP : 91004390) or Fion (HP : 91254449) should you have any queries.

Thank you for your kind attention.

Yours faithfully,



SLP Motoring Services.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 11 March 2019 2:45 PM
To: 'YOONGNIANCHIANG@YAHOO.COM.SG'
Subject: ACCIDENT INVOLVING SFM 6650U AND SJZ 7825K ALONG CLEMENTI AVE 6 TWDS AYE EXIT ON 14/02/2019

11 MAR 2019

YOONG NIAN CHIANG

Dear Sir/ Mdm

OUR REF : CC3/AXA16012550/eb3

YOUR REF : SFM 6650U

ACCIDENT INVOLVING SFM 6650U AND SJZ 7825K ALONG CLEMENTI AVE 6 TWDS AYE EXIT ON 14/02/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SLP MOTORING SERVICES acting on behalf of the owner of SJZ 7825K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SJZ 7825K. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher

Case Handler

DID: 6841 6051

FAX: 6741 4108

Email: ashersng@lkkauto.com

c.c. *AXA Insurance Pte Ltd (AXA)*

(Motor Claims Dept)

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email:slpmotoring@gmail.com

18.02.2019.

Our Ref : SJZ 7825 K

Your Ref : SFM 6650 U

Rico Engineering Works Pte Ltd
C/O SLP Motoring Services

Attn: Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Dear Sir/Mdm,

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING SJZ 7825 K & SFM 6650 U ON 14.02.2019.

We, Rico Engineering Works Pte Ltd, owner of vehicle no. SJZ 7825 K hereby authorize M/s SLP Motoring Services as our authorized representative to write, negotiate and settle claim on our behalf in our claim against the owner and / or driver of vehicle no. SFM 6650 U in respect of the above mentioned accident.

Kindly make payment directly to SLP Motoring Services.

Kindly contact Susan (HP : 91004390) or Fion (HP: 91254449) should you have any queries regarding the above.

Yours faithfully,

by



Rico Engineering Works Pte Ltd.



redefining / insurance

CLAIM REF : S9M01DYX
INSURED : YOONG NIAN CHIANG

DISCHARGE VOUCHER

We/I [RICO ENGINEERING WORKSPTE LTD, NRIC NO. 199800407G] hereby agree to accept the sum of [FOUR THOUSAND AND FIFTY ONLY.] [S\$4,050.00] to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property and all costs and expenses that we/I have or may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SFM 6650U] as a result of an accident at [CLEMENTI AVE 6 TO AYE] on [14/02/2019] of which we/I were/was the hirer/owner/driver/pillion/Passenger/ insurer of motor vehicle [SJZ 7825K].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for all claim(s) whatsoever and whosoever present or future that we/I have or may have against the said Insurer, owner and/or driver of vehicle no. [SFM 6650U] in connection directly or indirectly with the said accident and give our/my full and final discharge.


We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SFM 6650U]

Dated this 05 day of Apr 2019

Claimant's Signature

: X kay



NRIC no./ Company Stamp

: 199800407G

Occupation/ Business

: _____

Address

: 350 Jln Kayu, Singapore 799475

Telephone No.

: HP 91004390

Witness's Name

: Lim Kah Noi

Witness's Signature

: [Signature]

Witness's NRIC No.

: S0200161F

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

WITHOUT PREJUDICE to:

- (a) Insurance Subrogated Claim and/or
 - (b) Any Personal Injury Claims
- (Note: This Notice supersedes any inconsistencies found in this Discharge Voucher)

SLP Motoring Services

102 Gerald Drive #04-75 Singapore 798593

HP 91004390/91254449 Fax 6484 1482

Email:slpmotoring@gmail.com

Invoice No : 1202

M/s AXA Insurance Pte Ltd

DATE 27.02.2019

8 Shenton Way #27-01 AXA Tower


CAR NO SJZ 7825 K

Singapore 068811

MAKE Mitsubishi Lancer

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SFM 6650 U

Qty	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
		<u>Recommended Parts (Nett item)</u>		
1	pcs	Rear boot lid		
1	pcs	Rear boot lid Mitsubishi logo emblem		
1	pcs	Rear boot lid "Lancer" emblem		
1	pcs	Rear boot lid "MR" emblem		
1	pcs	Rear boot lid top lock		
1	pcs	Rear boot lid number plate garnish		
1	pcs	Rear boot lid weatherstrip		
1	pcs	Rear bumper		
2	pcs	Rear bumper bracket		
1	set	Rear bumper reverse sensor		
1	pcs	Rear bumper reinforcement		
10	pcs	Rear bumper clips		
1	pcs	Rear bumper lower lip		
1	pcs	RH tail lamp		
1	pcs	Rear end panel		
1	pcs	Rear end panel top garnish		
		<u>Recommended Labour</u>		
		To provide labour, workmanship to re-align, straightening rear two side mudguard, spare tyre tank panel, cutting rear end panel, dismantle & replace the above mentioned parts.		
		Labour for respray rear bumper, rear end panel, rear bootlid cover, spare tyre tank panel & rear two side mudguard.		
		Continue on page 2		
		Page 1 of 2	Total	


SLP Motoring Services.

B & O VEHICLE RENTAL

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 53060835M
TOWING SERVICE: 6858 4067 (After 10.30 pm)

车辆出租合同 VEHICLE RENTAL AGREEMENT

Date: 18/11/19
Owner: B & O VEHICLE RENTAL ("the owner")
Hirer: RICO Engineering Works Pte Ltd
NRIC / Co. Reg. No: 1998004076
Tel: 66905713 Fax: H/P: 81213439
Address:

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SGJ914C		Agreement No.: 19159	
Driver's Particulars		Odometer:	
Name: Chur Zhen Long		Date & Time Out: 18/11/19 9.25am	
Address: Blk 450C Bukit Batok West Ave 6 #19-627 S 653450		Date & Time In: 23/11/19 9am	
I/C No: S8538129F	Dr/Licence No: S8538129F	Hour @\$	
Date of Issue:	Occupation:	5 Days @\$ 120/✓	
Date of Birth:	Tools: Old Spare Tyre: 2 new	Wks @\$	
		Mths @\$	

Third Party Claim
In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 2000/✓ comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage
Hirer is responsible for the first \$ 3000/✓ excess for collision/damage to first party, (i.e.) B & O VEHICLE RENTAL (including windscreen) plus loss of earnings while damaged vehicle is under repair.


Authorised Driver
Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance
General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable):
Sub-Total:
Balance To Pay: 600/✓

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

B & O VEHICLE RENTAL



Authorised Signature

7  

Hirer's Signature

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SFM 6650U <input checked="" type="checkbox"/> (Insd veh)	Model:	MITSUBISHI LANCER
	SJZ 7825K <input checked="" type="checkbox"/> (TP veh)		AUTO <input checked="" type="checkbox"/>
Date of Accident:	14/02/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,079.00
Final Repair Cost	:	\$	3,550.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	4,050.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No:
 BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown		
1)	SLP MOTORING SERVICES	\$ 4,050.00

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

 18/04/2019
 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002867/Eeb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 18-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 6650U	Veh. Inspected	SJZ 7825K
Policy No.	GA204164/1	Coverage (\$)	0.00
Claim No.	S9M01DYX	Excess (\$)	0.00
Assign From		Assign Date	15/02/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER AUTO	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JMYSRCS3AAU003565	Colour	BLACK
Odometer	149481	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	TOYO	7 mm
L/H Front Tyre	195/60 R15	TOYO	7 mm
R/H Rear Tyre	195/60 R15	TOYO	7 mm
L/H Rear Tyre	195/60 R15	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2019	Inspection Date	18/02/2019
Survey held at	BLK 10 AMK IND.PARK 2A #03-07		
Repairer	SLP MOTORING SERVICES		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 7825K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (CONSISTENT) (N)	DENTED	595.00	510.00
1	REAR BOOT LID MITSUBISHI LOGO EMBLEM (CONSISTENT) (N)	NECESSARY	46.00	46.00
1	REAR BOOT LID 'LANCER' EMBLEM (CONSISTENT) (N)	NECESSARY	25.00	25.00
1	REAR BOOT LID 'MR' EMBLEM (CONSISTENT) (N)	NECESSARY	24.00	24.00
1	REAR BOOT LID TOP LOCK (CONSISTENT) (N)	BENT	65.00	48.00
1	REAR BOOT LID LOWER LOCK (CONSISTENT) (N)	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$26.00 (CONSISTENT) (N)	NOT NECESSARY	52.00	-
1	REAR BOOT LID NUMBER PLATE GARNISH (CONSISTENT) (N)	CRACKED	197.00	141.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$26.00 (CONSISTENT) (N)	REPEATED	52.00	-
1	REAR BOOT LID WEATHERSTRIP (CONSISTENT) (N)	CRACKED	139.00	139.00
1	REAR BUMPER (CONSISTENT) (N)	DENTED	681.00	535.00
2	REAR BUMPER BRACKET @\$34.00 (CONSISTENT) (N)	BROKEN	68.00	68.00
1	SET REAR BUMPER REVERSE SENSOR (CONSISTENT) (N)	BROKEN	350.00	200.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT) (N)	BENT	175.00	175.00
10	REAR BUMPER CLIPS @\$5.00 (CONSISTENT) (N)	NECESSARY	50.00	30.00
1	REAR BUMPER LOWER LIP (CONSISTENT) (N)	BROKEN	764.00	528.00
2	TAIL LAMP (LEFT & RIGHT) @\$379.00 (CONSISTENT) (N)	O/S BROKEN	794.00	379.00
1	REAR END PANEL (CONSISTENT) (N)	DENTED	141.00	141.00
1	REAR END PANEL TOP GARNISH (CONSISTENT) (N)	CUT	175.00	175.00
1	SPARE TYRE TANK PANEL (CONSISTENT) (N)	TO REPAIR SEE LABOUR	876.00	-
	LESS 10% DISCOUNT		-	-316.40
			5,319.00	2,847.60
LABOUR				
	TO PROVIDE LABOUR ,WORKMANSHIP TO RE-ALIGN,STRAIGHTENING REAR TWO SIDE MUDGUARD ,CUTTING REAR END PANEL,DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS.INCLUSIVE OF THE REPAIR OF SPARE TYRE TANK PANEL .		1,300.00	750.00

Report Ref No. CC4/ASM19002867/Eeb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR RESPRAY REAR BUMPER ,REAR END PANEL,REAR BOOT LID COVER & REAR TWO SIDE MUDGUARD.		1,200.00	750.00
	TO INSTALL REAR BUMPER SENSOR TO NEW BUMPER INCLUDE TESTING FOR FUNCTIONS.		80.00	20.00
	RUST-PROOFING ON THE FRONT ACCIDENT AFFECTED PORTIONS.		180.00	50.00
			2,760.00	1,570.00
GRAND TOTAL			8,079.00	4,417.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CC4/ASM19002867/Eeb3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SYM01DYX	Vehicle Information	
Reference	EC4/ASH19002867/Ehb3g2	Incident Vehicle Registration #	SZ7825K
Loss Date	14 February 2019	Make	TPVD
Report Date	15 Feb 2019 8:58:00 AM	Model	TBC
Request Date	12 April 2019	Service Address	...
Due Date		Primary Contact/Insured	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)		YOUNG HIAN CHIANG 2 INDUS ROAD, #10-10, EMERALD PARK TOWER 2, 169586, Singapore
Type of Loss	Third Party Vehicle Damage		YOUNGHIANCHIANG@YAHOO.COM.SG
Services	Pending verification - Direct Settlement	Claim Handler	
			WANG Peter peter.wang@axa.com.sg

Actions

Next Step: Wait for Approve Invoice

[Add Invoice](#)

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKX Invoice 1 (1).pdf	Invoice	Surveyor Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	18 April 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
■ GIA REPORT OF SFM66500 (INSD).PDF	Reports & Statement	GIA Report	KADRI Mateen	15 February 2019