

Steve 18/2/19 12pm
 L/S with prejudice
 Remy Aff spy to Dismantle
 5 days

Steve Chenig LKR Auto - L 200
 8322 8813

SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593
 HP 91004390/HP 91254449 Fax 64841482
 Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	18.02.2019
No 8 Shenton Way #27-02 AXA Tower	CAR NO	SJZ 7825 K
S068811 Tel 63387288 Fax 68804838	MAKE	Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
<u>Recommended Parts</u>				
1	pcs	Rear boot lid / DO	Nett	\$595.00
1	pcs	Rear boot lid Mitsubishi logo emblem / NEC	Nett	\$46.00
1	pcs	Rear boot lid 'Lancer' emblem / NEC	Nett	\$25.00
1	pcs	Rear boot lid 'MR' emblem / NEC	Nett	\$24.00
1	pcs	Rear boot lid top lock / BT	Nett	\$65.00
1	pcs	Rear boot lid lower lock X NI	Nett	\$50.00
2	pcs	Rear boot lid number plate lamp X NI	Nett	\$26.00 \$52.00
1	pcs	Rear boot lid number plate garnish / CRA	Nett	\$197.00
2	pcs	Rear boot lid number plate lamp X RPT	Nett	\$26.00 \$52.00
1	pcs	Rear boot lid weatherstrip / CR4	Nett	\$139.00
1	pcs	Rear bumper / DO	Nett	\$681.00
2	pcs	Rear bumper bracket 2 LH / RH / BR	Nett	\$34.00 \$68.00
1	set	Rear bumper reverse sensor / BR	Nett	200 / \$350.00
1	pcs	Rear bumper reinforcement 2 / BT	Nett	\$175.00
10	pcs	Rear bumper clips / NEC	Nett	\$5.00 30 / \$50.00
1	pcs	Rear bumper lower lip 2 ✓ BR	Nett	\$764.00
1/2	pcs	Tail lamp (left & right) LH X RH 2 ✓ BR	Nett	\$379.00 \$794.00
1	pcs	Rear end panel 2 ✓ DO	Nett	\$141.00
1	pcs	Rear end panel top garnish / CUT	Nett	\$175.00
1	pcs	Spare tyre tank panel X R	Nett	\$876.00



Total

SLP MOTORING SERVICES

Blk 102 Gerald Drive #04-75 Singapore 798593

HP 91004390/HP 91254449 Fax 64841482

Email : slpmotoring@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	18.02.2019
No 8 Shenton Way #27-02 AXA Tower	CAR NO	SJZ 7825 K
S068811 Tel 63387288 Fax 68804838	MAKE	Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SFM 6650 U

Pc	Pcs	JMYSRCS3AAU003565	UNIT PRICE	AMOUNT
		Continue from page one.		\$4,443.00
		To provide labour, workmanship to re-align, straightening rear two side mudguard, cutting rear end panel, dismantle & replace the above mentioned parts. <i>750 600 /</i>		\$1,300.00
		Labour for respray rear bumper, rear end panel, rear boot lid cover & rear two side mudguard. <i>150 750 / 6000</i>		\$1,200.00
		To install rear bumper sensor to new bumper include testing for functions. <i>20 /</i>		\$80.00
		Rust-proofing on the front accident affected portions. <i>50 /</i>		\$180.00
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
			Total	\$7,203.00

Page 2 of 2

flor

SLP MOTORING SERVICES.