

TPH
VIC

keny

Subject: SGN8976A.

Date:

Toyota Wish.
ZNE100325270

Rees Bumper Deformed.	485 ✓
Rees Bumper Lips. New	30 ✓
Rees Bumper Side Holder x02 New	58.1x2=116.20 ✓
Rees Bumper Reflector x02 Not New	83.1x2=166.20 X
Rees Bumper Impact Bracket x02 Painted	68.4x2=136.80 ✓
Reverse Sensor Dmg	280(SN) 200(SN)
Rees End Panel Outer Dented	581.10 ✓
Rees End Panel Inner Repair	213 X.
Rees End Panel Top Garnish Deformed	326.20 ✓
Rees End Panel Sealant. New	60(SN) ✓
Tailthip x02 cracked.	417.9x2=835.80 ✓
Tailgate Repair	1272.90 X
Tailgate Lock	2585.20 497 X
Tailgate Weatherstripe.	1938.90 276.10 X
Tailgate Glass Moulding	SN: 200 140.60 X
Tailgate Glass Sealant.	60(SN) X
Toyota Logo. New	74.10 ✓

Panel Beating
Spray Painting
Wishy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey, before/after spray painting
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey is not a "Without Fee" price
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval by insurance company

Acknowledged by Repairer

Signature:

Date:

1200	600
1200	600
52	30
150	50
100	50
150	60
150	80
180	120

Total: 3728.90

4/5: 2950 050mgs.